







7623 Hart Road

501.944.8481

carushing@sbcglobal.net

September 15, 2011

Water Division Enforcement Branch Manager ADEQ 5301 Northshore Drive North Little Rock, AR 72118-5317

RE: Waterview Estates NPDES Permit No: AR0050393.

I received your letter about a routine compliance inspection at the Waterview treatment facility on August 30. I understand the inspection was conducted in response to a strong odor coming from the facility AND the pump station, which are located approximately one-half mile apart. I understand the inspection revealed the following violation: significant corrosion.

The rust and corrosion has been removed and the areas have been re-painted. Please see the attached photos. I will continue to watch for any corrosion and/or septic conditions.

Regarding the original odor complaint: I have managed six water treatment facilities over the past decade, and there is always a sewage odor- especially when there is flow coming in from lift stations or when equalization pumps are feeding the plant. I have not observed any **unusual** odors in the vicinity of the plant or lift station - other than the **usual** raw sewage odors that are present around such facilities.

During extremely hot weather, the equalization chamber is aerated every 15 minutes by a blower. During cooler weather, it is aerated every 30 minutes. This frequent aeration should prevent septic conditions in the equalization chamber.

Please contact me if you have any other questions regarding the violation or the odor complaint.

Thank you,

Charles Rushing Operator



ADEQ Water Division Enforcement Branch Manager 5301 Northshore Drive North Little Rock, Qr 72118-5317

7211845317

Աունեսինունիուկիորիություններիություն