

ADEQ

ARKANSAS
Department of Environmental Quality

June 18th, 2012

Mr. Kirby Thompson, Manager
WM Eco-Vista Landfill
2210 Waste Management Drive
Springdale AR 72762

RE: NPDES Permit Tracking Number ARG160003, AFIN 72-00144

Dear Mr. Thompson,

A review of the NPDES file for the Eco-Vista Landfill through April 30, 2012 reveals the following compliance issues:

The facility has failed to submit Discharge Monitoring Reports for the following period:

- Monitoring period ending 12/31/09 Discharge 001-A
- Monitoring period ending 12/31/09 Discharge 002-A
- Monitoring period ending 12/31/09 Discharge 003-A

Any violation of your NPDES Permit is subject to enforcement action by this Department, pursuant to the Arkansas Water and Air Pollution Control Act. The regulations and your NPDES Permit require that you take all reasonable measures necessary to eliminate or prevent the occurrence of violations.

Should you have any questions concerning the above referenced compliance issues, please feel free to contact me at 501-682-0631, or you may e-mail me at johnsonm@adeq.state.ar.us.

Sincerely,



Miles Johnson
Enforcement Analyst
Water Division, Enforcement Branch