# RELEASE PREVENTION (Cont'd)

Facility ID#: 35000034

Check ( √ ) for compliance; "No" for noncompliance. Leave blank for "N/A".

| IV. CORROSION PROTECTION<br>A. Material of Construction (Check all that apply) | System# 1 | | System# 2 | | System# 3 | | System# | |
|---|---|---|---|---|---|---|---|---|
| | Tank | Piping | Tank | Piping | Tank | Piping | Tank | Piping |
| **NON-CORRODIBLE** | | ✔ | | ✔ | | ✔ | | |
| **CORRODIBLE** | ✔ | | ✔ | | ✔ | | | |
| **B. Internal lining** | | | | | | | | |
| (1) Installed according to a recommended practice. | | | | | | | | |
| (2) Inspected in a timely manner and lining is in compliance. [ 7 ] | | | | | | | | |
| (3) Inspected according to approved protocol. | | | | | | | | |
| (4) Corrective action taken on failed inspection. | | | | | | | | |
| **C. Galvanic (sacrificial) anodes** | | | | | | | | |
| (1) Designed by CP expert/specialist. | | | | | | | | |
| (2) Tested in a timely manner. | | | | | | | | |
| (3) Corrective action taken on failed test. | | | | | | | | |
| (4) Metal components (i.e., flex lines, subpumps, etc.) protected as required. [ 8 ] | | | | | | | | |
| (5) Operational records available. | | | | | | | | |
| **D. Impressed current** | | | | | | | | |
| (1) Designed by CP expert/specialist. | ✔ | | ✔ | | ✔ | | | |
| (2) Tested in a timely manner. | ✔ | | ✔ | | ✔ | | | |
| (3) Rectifier is operational. | ✔ | | ✔ | | ✔ | | | |
| (4) Verify records of 60 day check. [ 6 ] | ✔ | | ✔ | | ✔ | | | |
| (5) Corrective action taken on failed check. | ✔ | | ✔ | | ✔ | | | |
| (6) Operational records available. | ✔ | | ✔ | | ✔ | | | |
| (7) CP system maintained. | ✔ | | ✔ | | ✔ | | | |
| (8) Metal components (i.e., flex lines, subpumps, etc.) protected as required. [ 8 ] | ✔ | ✔ | ✔ | ✔ | ✔ | ✔ | | |

Comments:
Impress current system installed by Scott's Underground March 16, 2007

Inspector's Signature _____ Date Jul 10, 2007