

ARKANSAS DEPARTMENT OF ENVIRONMENTAL QUALITY
FOLLOW-UP COMPLIANCE INSPECTION SUMMARY
(AN ASTERISK [*] DENOTES VIOLATION)

INITIAL INSPECTION CONDUCTED BY:

R Fowler

FACILITY ID#:

35000034

Lat.

34.27117

Long.

-92.08965

DATE OF INITIAL INSPECTION:

5-4-04

FACILITY NAME:

Big Red #30

FOLLOW-UP CONDUCTED BY:

R Fowler

FACILITY STREET LOCATION:

8006 Dollarway

DATE FOLLOW-UP CONDUCTED:

6-30-04

CITY: Whitehall

COUNTY:

JEFFERSON

LUST#:

DATE REPORTED:

N/A

FACILITY OWNER:

Big Red - Ben Jones

Check (✓) the appropriate box:

- ☒ This facility meets both Release Detection and Release Prevention requirements.
- ☐ This facility meets Release Detection requirements, but does not meet Release Prevention requirements.
- ☐ This facility meets Release Prevention requirements, but does not meet Release Detection requirements.
- ☐ This facility does not meet either Release Detection or Release Prevention requirements.

This follow-up inspection summary serves as your Notice of Noncompliance (if violations are indicated).

You have until _____ to provide evidence of compliance. Noncompliance issues could result in enforcement actions including, but not limited to, penalty assessments. Failure to resolve these noncompliance issues within the specified time frame could result in the escalation of enforcement actions.

Emmett R. Pittman
Signature of Owner/Owner's Representative

6-30-2004
Date