

STATE OF ARKANSAS DEPARTMENT OF POLLUTION CONTROL AND ECOL

SOLID WASTE MANAGEMENT DIVISION 8017 I-30, P.O. BOX 8913 LITTLE ROCK, ARKANSAS 72219-8913 ENFORCEMENT: (501) 682-0595 PROGRAMS: (501) 682-0584 TECHNICAL: (501) 682-0602

FAX: (501) 682-0611



October 28, 1998

Mr. Ron Hunt, Supervisor Sunray Services, Inc. P. O. Box 1310 Springdale, AR 72765-1310

RE: CSN 72-0144 Permit No. 5-WTP

Dear Mr. Hunt:

On October 27, 1998, I performed a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Regulation 22, the Waste Tire Regulation 14, the Arkansas Solid Waste Management Act 237 of 1971, as amended, A.C.A. 8-6-201 et seq., the above referenced permit, and all other applicable rules and regulations. A facility inspection and evaluation report was completed.

Refer to the attached report to note any allegations or deficiencies that require corrective action. The aforementioned items require immediate attention and correction. Please send a written response as to the corrective action taken. Failure to respond to this letter in writing shall be construed as an admission of any allegations contained therein. Any items noted that are neglected and persistent may warrant formal enforcement action.

If we can be of any further assistance, feel free to contact me at 8017 I-30, P.O. Box 8913, Little Rock, AR, 72219-8913, or call (501) 682-0582.

Sincerely,

Scott McWilliams Scott McWilliams, Inspector Solid Waste Division

SM:sic Enclosure

cc: Central Files

> Heidi Love, Inspector Supervisor SWD Elizabeth Hoover, Waste Tire Program SWD

The Hon. Charles Johnson, Washington County Judge

Steven Parker, Director, Four County RSWMB

Arkansas Department of Pollution Control and Ecology - Facility Evaluation

Name of Site: SUNRAY SERVICES, INC.	County: CSN # 72-0/44	Permit # 5-WTP
WASHINGTON CO. Rd. 865	Address of Permittee Row HUNT P.D. Box 1300 SPRINGDALE, AR 72765	
Telephone Number:	Licensed Operator & No.	Date: /0/27/98
501-361-2069	RON HUNT #829	Entry Time: 1040
Type of Facility: OTHER OCOMPOST OTRANSFER STA. OMRF XTIRE	•	Exit Time: /204

OPER	٧.	TIO	МΛ	ı c	TAR	IDΛ	BDS
UPER	A	HU	INA	L O	ı An	1DB	เหบอ

NO PROBLEMS NOTED DURING THIS INSPECTION.

OTHER CRITERIA				
Soil Conditions: Dry	Scott Mwill. Signature of Inspector:			