

STATE OF ARKANSAS

DEPARTMENT OF POLLUTION CONTROL AND ECOLOGY

SOLID WASTE MANAGEMENT DIVISION 8017 I-30, P.O. BOX 8913 LITTLE ROCK, ARKANSAS 72219-8913 ENFORCEMENT: (501) 682-0595

PROGRAMS: (501) 682-0584 TECHNICAL: (501) 682-0602 FAX: (501) 682-0611

August 28, 1998

Mr. Ron Hunt, Supervisor Sunray Services, Inc. P. O. Box 1310 Springdale, AR 72765-1310

RE:

CSN 72-0144

Permit No. 5-WTP

Dear Mr. Hunt:

On August 6, 1998, I performed a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Regulation 22, the Waste Tire Regulation 14, the Arkansas Solid Waste Management Act 237 of 1971, as amended, A.C.A. 8-6-201 et seq., the above referenced permit, and all other applicable rules and regulations. A facility inspection and evaluation report was completed.

Refer to the attached report to note any allegations or deficiencies that require corrective action. The aforementioned items require immediate attention and correction. Please send a written response as to the corrective action taken. Failure to respond to this letter in writing shall be construed as an admission of any allegations contained therein. Any items noted that are neglected and persistent may warrant formal enforcement action.

If we can be of any further assistance, feel free to contact me at 501/452-4822, or P. O. Box 11045, Ft. Smith, AR 72917-1045.

Sincerely,

Tom Coleman, Inspector

Solid Waste Division

TC:sic Enclosure

cc:

Central Files

Heidi Love, Inspector Supervisor SWD Elizabeth Hoover, Waste Tire Program SWD

The Hon. Charles Johnson, Washington County Judge

Steven Parker, Director, Four County RSWMB

Arkansas Department of Pollution Control and Ecolog, - Facility Evaluation

Name of Site: Sunray Services, Inc	County: Washington	CSN # EF2-0144	Permit #
Location: Washington Co. Rd. 865		Po Box 1310	<u> </u>
	S	promodale, A	HR 72765
Telephone Number:	Licensed Operator & No.		Date: 8-4-78
501-361-2069	Ron Hunt #		Entry Time: (330h/3)
Type of Facility:		•	Exit Time: 1575hB,

OPERATIONAL STANDARDS

- Facility must reduce the volume of waste tires being stored on site.

- No other problems noted during this inspection.

OTHER CRITERIA		
Soil Conditions: Ory Wet Photos? Y	Total Points	
Signature of Person Interviewed:	Signature of Inspector:	