

STATE OF ARKANSAS DEPAR I MENT OF POLLUTION CONTROL AND ECOLOGY

SOLID WASTE MANAGEMENT DIVISION

8017 I-30, P.O. BOX 8913 LITTLE ROCK, ARKANSAS 72219-8913 ENFORCEMENT: (501) 682-0595 PROGRAMS: (501) 682-0584 TECHNICAL: (501) 682-0602

FAX: (501) 682-0611

April 21, 1998

Mr. Ron Hunt, Supervisor Sunray Services Inc. P O Box 1310 Springdale, AR 72765-1310

CSN 72-0144 RE: Permit No. 5-WTP

Dear Mr. Hunt:

On April 14, 1998, I performed a routine inspection of your facility pursuant to the Arkansas Solid Waste Management Regulation 22, the Waste Tire Regulation 14, the Arkansas Solid Waste Management Act 237 of 1971, as amended, A.C.A. 8-6-201 et seq., the above referenced permit, and all other applicable rules and regulations. A facility inspection and evaluation report was completed.

Refer to the attached report to note any allegations or deficiencies that require corrective action. The aforementioned items require immediate attention and correction. Please send a written response as to the corrective action taken. Failure to respond to this letter in writing shall be construed as an admission of any allegations contained therein. Any items noted that are neglected and persistent may warrant formal enforcement action.

If we can be of any further assistance, feel free to contact me at 501/785-1822, or P O Box 1544, Ft. Smith, AR 72902-1544.

Sincerely,

Tom Coleman, Inspector Solid Waste Division

Central Files XC:

> Heidi Love, Inspector Supervisor SWD Susan Speake, Waste Tire Program SWD

The Hon. Charles Johnson, Washington County Judge

Steven Parker, Director, Four County RSWMB

Arkansas Department of Pollution Control and Ecology - Facility Evaluation

Name of Site: Sunray Services, Inc.	County: Washington	CSN # 72-0144	Permit # 5- WTP
Location:	Address of Permittee	Ron Hunt	
Washington Cc. Rd. 865	PO 30X 1310		
		Springdale,	AR 72765
Telephone Number:	Licensed Operator & No		Date: 4-14-98
501-361-2069	Ron that #	825	Entry Time: 1150 k/3.
Type of Facility:			Exit Time: 1340 hrs.
	Kon that	825	Entry Time: 1150kg

OPERATIONAL STANDARDS

- Waste tire cutter has been down for the past month.
- Cutter has been repaired and is being put back into operation.
- Facility needs to catch up on waste time pile now that this equipment is back in operation.
- No operational violations noted during this inspection.

OTHER CRITERIA			
Soil Conditions: YDry □Wet Photos? YN	Total Points		
	NIA		
Signature of Person Interviewed:	Signature of Inspector:		