



Arkansas Department of Environmental Quality Solid Waste Management Division Other Report Form



Activity	Site Visit	PDS #	Doc ID: 066281
Site Name	DAMCO Project / NWRSWMD WTP site	County	Baxter
Location	Baxter CR 831	Date	6-13-14

COMMENTS

This site visit was in conjunction with the quarterly inspection of the Northwest Arkansas Regional Solid Waste Management District Waste Tire Processing facility (Permit Number 0022-SWTP), and a citizen's complaint regarding the number of mosquitos on site. (Complaint PDS Number 017184)


This report centers on the site visit only. My observation at this time is there has been no activity on this site, including removal of tires, during this growing season. The vegetation on site is overgrown: a visual inspection of the number of tires on site is not possible based on the condition of the vegetation.

1020- I entered the site by climbing over the locked gate at the entrance and walking west toward the lake. The vegetation on the site was overgrown to the extent that I could not see the lake, or the majority of the baled tires. I walked down the entrance road approximately 300ft and found the tire baling equipment and several piles of loose tires. (Approximately 250 loose tires in the vicinity of the baling equipment) It is unclear from the condition of the site to observe where the permitted area is located, and where the boundary of the DAMCO Project begins.

The violations noted on my inspection report list the same violations noted on the previous inspection dated 2-19-14. No corrections of the violations from the previous inspection have been made at the time of this visit.

No vector control measures are in place. All loose tires I observed had standing water in them, and the mosquitos in the area are very bad with vegetation growing through the baled tires.

1100- I exited the site.

Signature of Inspector		Date	6/13/2014
-------------------------------	---	-------------	-----------

PDS Number 017184
Photos 1 & 2

