



Arkansas Department of Environmental Quality Solid Waste Management Division Other Report Form



Activity	Site Visit	PDS #	Doc ID: 66282
Site Name	DAMCO Project / NWRSWMD WTP site	County	Baxter
Location	Baxter CR 831	Date	7-17-14

COMMENTS

This site visit was in conjunction with the quarterly inspection of the Northwest Arkansas Regional Solid Waste Management District Waste Tire Processing facility (Permit Number 0022-SWTP).

This report centers on the site visit only for the DAMCO Project. The vegetation on site is overgrown: a visual inspection of the number of tires on site is not possible based on the condition of the vegetation. It appears that there has been no activity on site, including removal of tires during this growing season.


A key was obtained to enter the property through the locked gate. Inspector Supervisor, Heidi Love, and I entered the site at approximately 1030 through the front gate. The vegetation on the site was overgrown to the extent that I could not see the lake or the majority of the baled tires from the entrance. After entering the site, we drove along the North access road to the lake. Approximately 50 Bales of tires were noted stacked along the north side of the lake. From there, we drove to the two bailers still located in the waste tire processing area for the permitted site located east of the lake. Approximately 250 loose tires were noted in the vicinity of the baling equipment. It is unclear from the condition of the site to observe where the permitted area is located, and where the boundary of the DAMCO Project begins due to the close proximity of the baled tires and the processing equipment. (Approximately 50 feet)

The excessive vegetation growing around the baled tires prevented us from determining the number of baled tires on site. A previous estimation was noted of approximately 400,000 tires using Google Earth images.

Eight Semi-Truck trailers were noted on site, all locked. It is unknown if these trailers contain waste tires.

No vector control measures are in place. I observed standing water in the loose tire and the mosquitos in the area are very bad.

1100 - We exited the site.

Signature of Inspector		Date	7-22-14
-------------------------------	---	-------------	---------

Permit Number 0022-SWTP
Photos 1 & 2



Permit Number 0022-SWTP
Photos 3 & 4



Permit Number 0022-SWTP
Photos 5 & 6



Permit Number 0022-SWTP
Photos 7 & 8

