

AFIN: 0022-SWTP

PMT#: 03-00208

RECEIVED

By Barbara J. Mathews at 11:34 am, May 03, 2016

DOC ID#: 69512

TO: LW> file

S
W
M
D

ADEQ
Hazardous Waste Division
Trip Report

Project	DAMCO Inc.
Location	Mountain Home, Arkansas
Date	04/25/2016
Time	1300
Reason	Initial site visit to view site conditions
ADEQ personnel	Weston Lee Engineer, Annette Cusher Engineering Supervisor
Facility, contractor, and EPA personnel	Jeremy Brooks (FTN), Mark Koch (FTN), Paul Crawford (FTN), and Kenny Treat (land owner)
Activity Summary	<p>Annette and I arrived at the DAMCO site at 1300. We were joined by FTN associates: Mark Koch, Paul Crawford, and Jeremy Brooks. We started on the eastern side of the dam and walked to the toe of the dam. Photos were taken showing the exposed tires within the dam as well as many more in piles (Photos: 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 16, 17, 18, 19, 20, 21, 22, 31, 33, and 37). At the toe of the dam, there was evidence of water seeping out of the base as shown with the red-orange discoloration on the grass (Photos: 13, 14, and 15). On the far side of the dam, the unused bailed tires were stacked in large groups (Photos: 23, 24, 25, 26, 27, 28, 29, 30, 36, 38, 39, 40, 41, 42, 43, 44, and 45). Also on site was a pile of re-tread truck tires (photo 34), pile of inter tubes (photo 35), and the tire baling machine (photo 32). Mr. Treat showed up as we were leaving the site and discussed some of the past history of the dam that was built. We left the site at 1440.</p> <p>There are approximately 1 million tires either in bales or in loose piles above ground that need to be addressed. The dam will require additional work to bring the slope to a 3 to 1 gradient. Additional soil will be required to cover the exposed tires already located in the dam structure.</p> <p>Photos that are attached are of the current site conditions.</p>
Anticipated follow-up	Review FTN submitted recommendations for the site.
Other	Photos attached.

Name	Initials	Date
Weston Lee	wkh	5/2/16
Annette Cusher	Ac	5/2/16
Tammie Hynum	TH	5-3-2016



Arkansas Department of Environmental Quality
Official Photographic Log
Camera Location Map




Photo 1

Title: Pond with boat dock



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:05 PM

Photo 2

Title: Visible row of tires on the top of the dam



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WLL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:09 PM

Photo 3

Title: Exposed tires with no soil cover



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>Ac</i>
Date Time Stamp	04/25/2016 1:11 PM

Photo 4

Title: Exposed tires with no soil cover




04/25/2016 1:13 PM
04/25/2016 1:13 PM



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee ^{WAL}
Witness	Annette Cusher ^{AC}
Date Time Stamp	04/25/2016 1:13 PM

Photo 5

Title: Tractor tires laying on the ground



	Attributes
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WRL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:15 PM

Photo 6


Title: Exposed tires with no soil cover



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WLL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:17 PM

Photo 7

Title: Exposed tires with no soil cover



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WML</i>
Witness	Annette Cusher <i>Ac</i>
Date Time Stamp	04/25/2016 1:18 PM

Photo 8


Title: Exposed tires with no soil cover, exposed bedrock



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WLL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:19 PM

Photo 9


Title: Exposed tires with no soil cover 6 rows visible



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:21 PM

Photo 10


Title: Exposed tires with no soil cover 7 rows visible



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WLL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:23 PM

Photo 11

Title: Exposed tires with no soil cover last row at the toe of the dam



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WLL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:23 PM

Photo 12

Title: Exposed tires with no soil cover 7 rows visible trees growing in the dam



V:092° 22' 32.232"
N:036° 26' 54.06"



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:25 PM

Photo 13

Title: Seep under the rock next to exposed tires



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WBL</i>
Witness	Annette Cusher <i>Ac</i>
Date Time Stamp	04/25/2016 1:26 PM

Photo 14

Title: Seep near the toe of the dam



04/25/2016 1:27 PM
04/25/2016 1:27 PM



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:27 PM

Photo 15

Title: Seep near the toe of the dam



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WBL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:27 PM

Photo 16


Title: Exposed tires with no soil cover 7 rows visible trees growing in the dam



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:28 PM

Photo 17

Title: Exposed tires with no soil cover 7 rows visible trees growing in the dam



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WM</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:29 PM

Photo 18

Title: Exposed tires (monster truck size)



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WLL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:31 PM

Photo 19

Title: Exposed tires in the dam



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee ^{WKL}
Witness	Annette Cusher ^{AC}
Date Time Stamp	04/25/2016 1:34 PM

Photo 20

Title: Exposed tires in the dam



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee ^{W&L}
Witness	Annette Cusher ^{AC}
Date Time Stamp	04/25/2016 1:36 PM

Photo 21

Title: Exposed tires in the dam



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:38 PM

Photo 22

Title: Exposed tires in the dam with trees growing in the dam



43.993° 23° 23.79"
92.928° 38° 52.018"



	Attributes
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WBL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:40 PM

Photo 23

Title: Tires baled stacked 3 high



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WML</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:43 PM

Photo 24

Title: Tires baled stacked 3 high



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:43 PM

Photo 25

Title: Tires baled stacked 3 high



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WBL</i>
Witness	Annette Cusher <i>Ac</i>
Date Time Stamp	04/25/2016 1:45 PM

Photo 26

Title: Tires baled stacked 4 high



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>W Lee</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:46 PM

Photo 27

Title: Tires baled stacked 3 high



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WLL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:47 PM

Photo 28

Title: Tires baled stacked 2 high



	Attributes
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:48 PM

Photo 29

Title: Tires baled stacked 2 high



	Attributes
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:50 PM

Photo 30

Title: Tires baled stacked 4 high



	Attributes
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:51 PM

Photo 31

Title: Tires stacked in a pile



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WBL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:54 PM

Photo 32

Title: Tire baling machine



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WKL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 1:55 PM

Photo 33


Title: Old trailer with tires around it



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WLL</i>
Witness	Annette Cusher <i>Ac</i>
Date Time Stamp	04/25/2016 1:58 PM

Photo 34

Title: Re-tread off large truck tires



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WBL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 2:00 PM

Photo 35


Title: Intertubes discarded in a pile



	Attributes
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 2:02 PM

Photo 36


Title: Tires baled stacked 4 high



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WAL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 2:03 PM

Photo 37

Title: Large tractor tires in a pile



	Attributes
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee ^{WAL}
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 2:04 PM

Photo 38

Title: Tires baled stacked 4 high



	Attributes
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WBL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 2:08 PM

Photo 39

Title: Tires baled stacked 3 high



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>W&L</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 2:10 PM

Photo 40

Title: Tires baled stacked 4 high



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WXL</i>
Witness	Annette Cusher <i>AC</i>
Date Time Stamp	04/25/2016 2:11 PM

Photo 41

Title: Tires baled stacked 5 high



	Attributes
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee ^{WAL}
Witness	Annette Cusher ^{AC}
Date Time Stamp	04/25/2016 2:12 PM

Photo 42

Title: Tires baled stacked 4 high



	Attributes
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee ^{W&L}
Witness	Annette Cusher ^{AC}
Date Time Stamp	04/25/2016 2:16 PM


Photo 43

Title: Tires baled stacked 3 high



Attributes	
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee ^{WKL}
Witness	Annette Cusher ^{AC}
Date Time Stamp	04/25/2016 2:18 PM

Photo 44
Title: Tires baled stacked 3 high



	Attributes
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee ^{WBL}
Witness	Annette Cusher ^{AC}
Date Time Stamp	04/25/2016 2:19 PM

Photo 45
Title: Tires baled stacked 2 high



	Attributes
Facility	DAMCO
Event	Site Inspection
Site Location	Mountain Home, AR
AFIN	03-00208
Photographer	Weston Lee <i>WBL</i>
Witness	Annette Cusher <i>Ac</i>
Date Time Stamp	04/25/2016 2:21 PM