

ADEQ
Office of Land Resources
Groundwater Branch
Trip Report
Document ID 76171

Project	NABORS Landfill; Permit 0249-S1-R2
Location	Three Brothers, Arkansas
Date	April 23, 2019
Time	Arrived 11:05 am; Departed 5:00 pm
Reason	Site visit to identify spring locations for sampling
ADEQ personnel	Robert Cramer, Geologist Bill Sadler, Geology Supervisor
Other personnel onsite	Mike Lybrand, Harbor Environmental Mike Dollar, Harbor Environmental
Activity Summary	<ul style="list-style-type: none">• Observed and marked spring locations on site.• Took M. Lybrand and M. Dollar around to the springs to show them where they are marked.
Action Items Summary	None
Anticipated follow-up	None
Other	

Arkansas Department of Environmental Quality
Official Photograph Log

Route to:

ADEQ personnel review:		Date:
Robert Cramer	RC	4-25-19
Bill Sadler	BS	4-25-19
Diana Kilburn	DK	4/26/19
Mo Shafii	mo	4/29/19
Clark McWilliams	CW	4/29/19
Ben Reynolds	BR	4/29/19
To Solid Waste Database & Zylab		

Arkansas Department of Environmental Quality
Official Photograph Log



SITE NAME: NABORS Landfill	PHOTO #: 3065
SITE LOCATION: Three Brothers, Arkansas	
AFIN#: 03-00051	PERMIT # 0249-S1-R2
PHOTOGRAPHER: Bill Sadler BS	WITNESS: Robert Cramer RC
DATE: April 23, 2019	CAMERA: Cannon Power Shot A560
DIRECTION: North	
SUBJECT: TSP-1	

Arkansas Department of Environmental Quality
Official Photograph Log



SITE NAME: NABORS Landfill	PHOTO #: 3074
SITE LOCATION: Three Brothers, Arkansas	
AFIN#: 03-00051	PERMIT # 0249-S1-R2
PHOTOGRAPHER: Bill Sadler <i>BS</i>	WITNESS: Robert Cramer <i>RC</i>
DATE: April 23, 2019	CAMERA: Cannon Power Shot A560
DIRECTION: West	
SUBJECT: Class IV Draw Spring	

Arkansas Department of Environmental Quality
Official Photograph Log



SITE NAME: NABORS Landfill	PHOTO #: 3082
SITE LOCATION: Three Brothers, Arkansas	
AFIN#: 03-00051	PERMIT # 0249-S1-R2
PHOTOGRAPHER: Bill Sadler <i>BS</i>	WITNESS: Robert Cramer <i>RC</i>
DATE: April 23, 2019	CAMERA: Cannon Power Shot A560
DIRECTION: Northeast	
SUBJECT: Class I Draw Spring	

Arkansas Department of Environmental Quality
Official Photograph Log



SITE NAME: NABORS Landfill	PHOTO #: 3080
SITE LOCATION: Three Brothers, Arkansas	
AFIN#: 03-00051	PERMIT # 0249-S1-R2
PHOTOGRAPHER: Bill Sadler <i>BS</i>	WITNESS: Robert Cramer <i>RC</i>
DATE: April 23, 2019	CAMERA: Cannon Power Shot A560
DIRECTION: Northeast	
SUBJECT: Mike Lybrand sampling CAO-3	

Arkansas Department of Environmental Quality
Official Photograph Log



SITE NAME: NABORS Landfill	PHOTO #: 3085
SITE LOCATION: Three Brothers, Arkansas	
AFIN#: 03-00051	PERMIT # 0249-S1-R2
PHOTOGRAPHER: Bill Sadler <i>BS</i>	WITNESS: Robert Cramer <i>RC</i>
DATE: April 23, 2019	CAMERA: Cannon Power Shot A560
DIRECTION: East	
SUBJECT: Landfill Entrance Seep	

Arkansas Department of Environmental Quality
Official Photograph Log



SITE NAME: NABORS Landfill	PHOTO #: 3089
SITE LOCATION: Three Brothers, Arkansas	
AFIN#: 03-00051	PERMIT # 0249-S1-R2
PHOTOGRAPHER: Bill Sadler <i>BS</i>	WITNESS: Robert Cramer <i>RC</i>
DATE: April 23, 2019	CAMERA: Cannon Power Shot A560
DIRECTION: East	
SUBJECT: SP-7	

Arkansas Department of Environmental Quality
Official Photograph Log



SITE NAME: NABORS Landfill	PHOTO #: 3093
SITE LOCATION: Three Brothers, Arkansas	
AFIN#: 03-00051	PERMIT # 0249-S1-R2
PHOTOGRAPHER: Bill Sadler <i>BS</i>	WITNESS: Robert Cramer <i>RC</i>
DATE: April 23, 2019	CAMERA: Cannon Power Shot A560
DIRECTION: Northwest	
SUBJECT: TSP-3	