

AFIN: 03-00208
PMT#: 0022-SWTP

Progress Report

OCT 04 2019

Project No. R03013-0020-044

TO: MM > File < CR

Doc ID #
77151

Arkansas Department of Environmental Quality Remedial Action Construction Quality Assurance DAMCO Waste Tire Disposal Facility – Phase II

During the month of September 2019, the following activities were accomplished:

1. Provided 15 days of full-time on-site construction observation and five (5) days of part time on-site construction observation (partial weather days).
2. Conduct two Bi-weekly progress meeting (9/5/19 & 9/20/19)
3. Coordinated geotechnical testing for cementitious materials.
4. Reviewed and approved one (1) contractor pay application.
5. Provided general project management and client coordination.

During the month of October 2019, the following activities are anticipated:

1. Continue on-site construction observation as needed to complete the project.
2. Coordinate CQA geotechnical testing for cementitious materials.
3. Conduct substantial completion inspection site meetings.
4. Provide submittal review, pay application review, change order request review, and RFI responses as submitted.
5. Provide general project management and client coordination.

