

AFIN: 03-00208
PMT#: 0022-SWTP

Progress Report

JAN 13 2020

DOC ID#: 77531

TO: Project No. R03013-0020-044

MM > File < CR

Arkansas Department of Environmental Quality Remedial Action Construction Quality Assurance DAMCO Waste Tire Disposal Facility – Phase II

During the month of December 2019, the following activities were accomplished:

1. Provided on day on on-site part time construction observation to evaluate status of punch list items (12/9/19)
2. Consolidated daily field report data and rainfall data and provided this data to contractor in PDF format at request of DEQ,
3. Continued discussion with land Owner and Contractor regarding leaking pipe and potential resolutions
4. Evaluated topographic survey to compare volumes to as designed and pre-construction conditions to assess fill volumes,
5. Provided general project management and client coordination.

During the month of January 2020, the following activities are anticipated:

1. Conduct additional follow-up site visit to check on punch list items status.
2. Provide pay application review and change order request review as submitted.
3. Provide general project management and client coordination.

