

ARKANSAS DEPARTMENT OF ENVIRONMENTAL QUALITY
P. O. BOX 8913, LITTLE ROCK, AR 72219-8913

COMPLAINT REPORT

LOG#:	AFIN#: 63-00063 PERMIT#: AR0036498		
DATE RECEIVED: 3/28/08	COUNTY: Saline County		
COMPLAINANT NAME: Pam Corey	COMPLAINT AGAINST: City of Benton- WWTP		
ADDRESS: Dale Street Benton, AR	ADDRESS:		
PHONE: 501-672-0399	PHONE: FAX:		
PERSON RECEIVING REPORT: Jill Glenn	DATE: 3/28/08	SUPERVISOR REFERRAL:	DATE:
INSPECTOR REFERRED:	DATE:	MEDIA SUPERVISOR REFERRAL:	DATE:
PHONE REFERRAL CONTACT:	DATE:	RECEIVING INSPECTOR: Jill Glenn	DATE: 3/28/08

DESCRIPTION (IN DETAIL)

Benton WWTP discharges into Depot Creek and beaver dam downstream is causing raw sewage to back up onto her property.

LOCATION (IN DETAIL)

Take exit #116 off of I-30. Go over freeway towards the Benton Airport. Turn onto Airline Dr., turn right at stop sign, turn left after 1 block onto Dale St. Depot Creek is backing up onto property at dead end.

PREVIOUS COMPLAINT? YES NO **DATES:**

DISCHARGE TO STREAM? YES NO **NAME OF STREAM:** Depot Creek

HOW COMPLAINT WAS RECEIVED: PHONE LETTER VERBAL FAX E-MAIL

FOLLOW UP ON COMPLAINT

COMPLAINT #:	AFIN #: 63-00063
INSPECTOR: Jill Glenn	DATE: 4/9/08

ACTION TAKEN:	PHOTOS TAKEN: Yes
---------------	-------------------

On 4/9/08 at 1100 I arrived at Ms. Corey's property. I looked at the water backed up on Ms. Corey's property and did not see any evidence of raw sewage. I also walked over to Depot Creek. There was some sediment and decaying leaves, there was no evidence of raw sewage in the creek or on Ms. Corey's property. I called Ms. Corey and told her I saw decaying leaves and sediment, but I did not see any raw sewage. I told her she can call AGFC and they could help her with the beaver dam.

FURTHER ACTION TAKEN/TO BE TAKEN:

<u>None</u>

INSPECTOR SIGNATURE: 	DATE: 4/9/08	HOURS WORKED: 4
--------------------------------------------------------------------------------------------------------	--------------	-----------------