

January 11, 2008

Altman Motor Company Attn: Mr. J. T. Altman 415 Sylamore Ave. Mt. View, AR 72560

RE: Construction Storm Water Site in Stone County

NPDES Permit No.: ARR150000

Dear Mr. Altman:

I am writing in regard to the construction site at the Hwy 5/9 and Herple Road intersection in Mountain View. On December 10, 2007, I performed a routine compliance inspection of the above referenced construction site in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. This inspection revealed the following violations:

- 1. A construction site notice was not posted at the construction site in a prominent place for public viewing; this is a violation of Part I Section B: 7.a.iv.B.(2) of the permit.
- 2. A Storm Water Pollution Prevention Plan (SWPPP) was not available for review; this is a violation of Part II Section A:1. of the permit.
- 3. Disturbed areas of the construction site had not been inspected at least once every fourteen (14) calendar days and within 24 hours of the end of a 0.5 inch or greater storm event; this is a violation of Part II Section A: 4.e. of the permit.

The above items require your immediate attention. Please submit a written response to these findings to the Water Division Enforcement Section of this Department at the following address:

Water Division Enforcement Section Arkansas Department of Environmental Quality 5301 Northshore Drive North Little Rock, AR 72118-5317

This response should contain detailed documentation describing the course of action taken to correct the items noted. This corrective action should be completed as soon as possible, and the written response is due by February 11, 2008.

For additional information you may contact the enforcement section by telephone at 501-682-0639 or by fax at 501-682-0910.

J.T. Altman January 11, 2008 Page 2

If you would like to discuss this matter in greater detail or I can be of any assistance, please contact me at 870-446-2770 or by e-mail at <u>morris@adeq.state.ar.us</u>.

Sincerely,

Vory L morris

Tony L. Morris District #2 Field Inspector ADEQ Water Division

cc: Water Division Enforcement Branch Water Division Permits Branch

≎EPA									Form Approved OMB No. 2040-0003													
UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Washington, D.C. 20460																						
	NPDES Compliance Inspection Report																					
Section A: National Data System Coding           Transaction Code         NPDES         Yr/Mo/Day         Inspector         Fac. Type																						
1		R	1 5	NPDE 0	2S 0	0	0	11	12	0	7 1	<sup>2</sup> /Mo/l	Jay 1	0	17	Insp 18	ес. Т <b>W</b>	ype	Ins 19	specto S	or 20	Fac. Type <b>2</b>
Remarks										1		_	I		1							
	6 9 - 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0																					
	Inspection Work Days	I	Facility	1	tion R	ating		Í	BI	1	QA	 I	 I	 I _ ,	I	F	Reserv	ed		 I	 I	 I
L	67 69		70	Ν	]			71	N	72	<b>N</b> 73			74	75							80
Nor	e and Location of Facility Inspected	I (Ear	in ducto	ial	na diaa	hanai		tion B		v	Data Entry Tir	no/De	ta				Dorm	nit Eff	ootiv	a Date	0	
inclu	ude POTW name and NPDES permit construction site is located at the 1	numl	ber)								10:45 De			2007			I CIII		ective		6	
	View in Stone County	nwy.	5/9 anu	nerpa	e Noa	u mtei	secu		noru	lei II	Exit Time 11:30 De			2007			Pern	nit Exp	piratio	on Da	ate	
	Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)     Other Facility Data       Forrest Cotter     870-491-5612       W 92.1024																					
Name, Address of Responsible Official/Title/Phone and Fax Number     Image: Contacted       J.T. Altman     Contacted       Altman Motor Company     Yes Image: No Image																						
			(S	= Satis							<b>iring Insp</b> sfactory, N			uated)								
S	Permit	Ν	Flow	Measu	reme	rement N Op			erations &	Mair	tenar	ice		N	N Sampling							
U	<b>Records/Reports</b>	N	Self-N	Aonito	ring F	g Program N Slu				dge Handl	ing/D	isposa	ıl	-	N							
M S	Facility Site Review	N	1	oliance	Sche										N N							
3	Effluent/Receiving Waters	N Se		ratory : Sumi	nary	of Fin	dings/	/Com	•		rm Water ach additi	onal s	heets	if nec			Othe	r:				
<ol> <li>A small construction site notice was not posted at the site entrance.</li> <li>No site inspections were available for review.</li> <li>A SWPPP was not available for review.</li> <li>A steep slope on the northern side of the site had been seeded.</li> </ol>																						
	Name(s) and Signature(s) of Inspector(s) Tony L. Morris							of En	iviroi	nmen	Fax tal Quality 70 (Fax)	-Jasp	er Fie	ld Off	ïce		Date December 12, 2007					
							ency/O	Office/	/Phon	e and	Fax Numb	ers					Date					

ADEQ Const. Storm Water Insp. AFIN:	69-00000 Permit	#: ARR150000
-------------------------------------	-----------------	--------------

A. General Information										
Site Name: Altman Construction	Sito									
Latitude: 35.8786	Longitude: 92.102	D <i>A</i>								
Total Acreage: <5										
Total Acreage: <5       Acreage Disturbed: <5       Starting Date: N/A         Project Type:										
□ Residential ØCommercial □I	ndustrial ⊡Roadw	vav ⊡Other	:							
Construction Stage:										
☑Clearing ☑Rough Grading □Infrastructure □Building Construction □Final Stabilization										
□Inactive □Other:										
Permit Type:		Site Posted:								
☑General □Individual ☑Unper	mitted	⊡Yes ⊠No	□Improper							
	· · · · · · · · · · · · · · · · · · ·									
B. Storm Water Pollution Preven	ntion Plan (SWPPF	P) [Part II Sectio	n A of Permit]							
SWPPP Developed and Onsite?	∃Yes ⊠No ⊡Inco	mplete DN	ot Updated as Needed							
Comments: No SWPPP was avai	lable for review.		•							
Are Stabilization Practices Satisfac	ctory?  ☐Yes  ØNo									
Comments: Some seeding was of	done on a steep no	orthern slop	e however most of the site is barren.							
	•	•								
Are erosion controls Satisfactory?	□Yes ØNo □NA									
Comments: Additional erosion c			reek.							
Evidence of sediment leaving the site?										
Comments:										
Evidence of off-site tracking?	es ⊠No ⊡NA									
Comments:										
Evidence of sediment entering the	Waters of the State	? □Yes ☑	Likely ⊡No ⊡NA							
Comments:			•							
Are inspections conducted and records kept as required in the permit?										
Comments:										
Is corrective action taken based on results of inspections?   Yes  No  NA										
Comments:										
Are daily rainfall totals recorded?	□Yes ☑No □NA									
Rainfall measured using: <b>DOn-site Rain Gauge ØNA DOther:</b>										
Comments: No rain gage on site										
General Comments:										

ADEQ Const. Storm Water Insp.
-------------------------------

AFIN: 69-00000

		Water	Divisio	n Construction Storm	n Water Photog	raphic Evide	nce Sheet	
Location:	Alt	man Co	onstructio	on Site, Stone County				
Photographer	:	Tony L	. Morris		Witness:	None		
Photo #	1	Of	2		Date:	12/10/07	Time:	11:03
Description:		Lookin	g north f	rom Herple Road at th	e disturbed site.			
Photographer		Tony L	. Morris		Witness:	None		
Photo #	2	Of	2		Date:	12/10/07	Time:	11:06
Description:				bes of the disturbed are				

	ADEQ Const.	Storm Water	Insp.
--	-------------	-------------	-------

AFIN: 69-00000

WATER DIVISION CONSTRUCTION STORM WATER COMPLAINT REPORT								
GPS LOCATION: 35.8786		AFIN: 69-						
92.1024		PERMIT#: ARR150000						
DATE RECEIVED: <b>12/04/07</b>		COUNTY: Stone						
COMPLAINANT NAME: Gerald Weber		COMPLAINT AGAINST: J.T. Altman						
ADDRESS: 17221 Highway 9		ADDRESS: Altman Motor Co.						
Mt. View, AR 72560		Attn: J.T. A						
		415 Sylam						
PHONE: N/A		Mt View, AR 72560 PHONE: 800-467-3851						
		RAL INFORMATION						
PERSON RECEIVING REPORT:	DATE: 12/04/07	SUPERVISOR REFERR	AL:	DATE:				
Frank Esry INSPECTOR REFERRAL:	DATE:	MEDIA SUPERVISOR F		DATE:				
	BATE.			DATE.				
PHONE REFERRAL CONTACT:	DATE:	RECEIVING INSPECTO	R:	DATE:				
		Tony Morris		12/04/07				
COMPLAINT RECEIVED BY: DPHONE DLETTER DVERBAL DINTERNET DEMAIL								
DETAILED DESCRIPTION								
A construction site being developed on a tributary of the White River in northern Mt View in Stone County. No BMP's and no site posting.								
LOCATION								
North from Mt View on Hwy 5/9 to Herple Road. The construction site is located on the north east corner of the intersection.								
PREVIOUS COMPLAINT: YES MO	DATES:							
DISCHARGE TO STREAM: ØYES DNO	NAME OF ST	REAM: Hell Creek, tribut	ary to the White <b>R</b>	liver				
	INVEST	GATION						
INSPECTOR:		DATE:						
Tony Morris		12/10/07						
ACTION TAKEN:		РНОТ	OS TAKEN: ØYE	es ⊡no				
Conducted a construction storm water site inspection. Discussed the site and the small construction site								
permit with the developer. Wrote a letter to the developer dated 12/12/07 listing violations.								
FURTHER ACTION:								
SIGNATURE: Tony L. Morris	- moris		DATE: Decembe	er 12, 2007				