



November 17, 2009

Gary Wiederkehr, Vice-President
Wiederkehr Wine Cellars Inc.
3324 Swiss Family Drive
Altus, AR 72821

AFIN: 24-00002

NPDES Permit No.: AR0034592

Dear Mr. Wiederkehr:

On October 29, 2009, I performed a routine compliance inspection of the waste water treatment facility in accordance with the provisions of the Federal Clean Water Act, the Arkansas Water and Air Pollution Control Act, and the regulations promulgated thereunder. This inspection revealed the following violations:

1. Facility was unable to provide any copies of Discharge Monitoring Reports, records or any other documentation which could be reviewed to determine compliance with the permit.
2. It is unclear as to whether the facility is collecting routine samples at outfall 002 or outfall 003. Department records indicate that only five discharges have occurred at outfall 002 since December 2006 and there have been no reported discharges from outfall 003 in the last five years. The permit specifically states that any discharges occurring from outfalls 002 and 003 must be monitored at a minimum of once per month. Permit also states that the flow must be monitored twice per week at each outfall.

During the inspection, I observed used oil on the ground's surface at an outside storage area. This area is located near the fermenting building and is used in conjunction with the compressor. It was uncovered and several storage drums were present without lids and at capacity. This area must be cleaned and maintained in a manner which will prevent contaminated surface water runoff.

Wiederkehr, Wiederkehr Wine Cellars, Inc

November 10, 2009

Page 2

The above items require your immediate attention. Please submit a written response to these findings to Cindy Garner, Water Division Enforcement Branch Manager, at the address listed on page one. This response should contain documentation describing the course of action taken to correct the items noted. This corrective action should be completed as soon as possible, and the written response with all necessary documentations (i.e. picture) is due by November 27, 2009.

If I can be of any assistance, please contact me at 479-452-4822 ext. 11.

Sincerely,

A handwritten signature in black ink, appearing to read "Jeff Tyler", written in a cursive style.

Jeff Tyler

District 4 Field Inspector

Water Division

cc: Water Division Enforcement Branch
Water Division Permits Branch



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
Washington, D.C. 20460

NPDES Compliance Inspection Report

Form Approved
OMB No. 2040-0003

Section A: National Data System Coding

Transaction Code										NPDES										Yr/Mo/Day										Inspec. Type		Inspector		Fac. Type	
1	N	2	5	3	A	R	0	0	3	4	5	9	2	11	12	0	9	1	0	2	9	17	18	C	19	S	20	2							
Remarks																																			
A F I N 2 4 - 0 0 0 0 2																																			
Inspection Work Days										Facility Evaluation Rating										BI		QA		-----Reserved-----											
67				69	70	1	71	N	72	N	73			74	75													80							

Section B: Facility Data

Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number)		Entry Time/Date	Permit Effective Date
Wiederkehr Wine Cellars, Inc 3324 Swiss Family Drive Altus, AR 72821		1515 / October 29, 2009	July 1, 2004
		Exit Time/Date	Permit Expiration Date
		1700 / October 29, 2009	June 30, 2009
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)		Other Facility Data	
Al Wiederkehr /President / 479-468-2611		Coordinates::	
Name, Address of Responsible Official/Title/Phone and Fax Number		Outfall 002 N 35° 27' 35.4"	
Gary Wiederkehr / Vice-President / 479-468-2611		W 93° 44' 58.9"	
3324 Swiss Family Drive		Outfall 003 N 35° 27' 33.5"	
Altus, AR 72821		W 93° 44' 56.6"	
		Contacted Yes ☒ No ☐	

Section C: Areas Evaluated During Inspection

(S = Satisfactory, M = Marginal, U = Unsatisfactory, N = Not Evaluated)

S	Permit	U	Flow Measurement	S	Operations & Maintenance	U	Sampling
U	Records/Reports	U	Self-Monitoring Program	S	Sludge Handling/Disposal	N	Pollution Prevention
U	Facility Site Review	S	Compliance Schedules	N	Pretreatment	N	Multimedia
M	Effluent/Receiving Waters	U	Laboratory	N	Storm Water	U	DMR's

Section D: Summary of Findings/Comments (Attach additional sheets if necessary)

Facility was unable to provide any Discharge Monitoring Reports, records, or any other documentation that could be used to determine compliance with the permit. Therefore Unsatisfactory ratings were marked in Section C.

At this time it is unclear whether or not the facility is collecting routine samples as required by the permit at outfall 002 and outfall 003. Records in the Central Office indicate that outfall 002 has discharged 5 times since December 2006 and there have been no reported discharges for outfall 003 in the last 5 years.

During the inspection, I observed the outside storage area for used oil from the compressor. There was used oil the ground and storage drums without lids. Facility personnel were advised that this area must be cleaned and maintained in an effort to prevent runoff waters laden with petroleum products.

Name(s) and Signature(s) of Inspector(s)	Agency/Office/Telephone/Fax	Date
Jeff Tyler	AR Dept. of Environmental Quality- / Fort Smith / 479-452-4822 ext. 11 / fax / 479-452-4827	October 5, 2009
Signature of Reviewer	Agency/Office/Phone and Fax Numbers	Date

SECTION A: PERMIT VERIFICATION

PERMIT SATISFACTORILY ADDRESSES OBSERVATIONS

☒S ☐M ☐U ☐NA ☐NE

DETAILS:

- | | |
|--|--|
| 1. CORRECT NAME AND MAILING ADDRESS OF PERMITTEE: | ☒ Y ☐ N ☐ NA ☐ NE |
| 2. NOTIFICATION GIVEN TO EPA/STATE OF NEW DIFFERENT OR INCREASED DISCHARGES: | ☐ Y ☐ N ☒ NA ☐ NE |
| 3. NUMBER AND LOCATION OF DISCHARGE POINTS AS DESCRIBED IN PERMIT: | ☒ Y ☐ N ☐ NA ☐ NE |
| 4. ALL DISCHARGES ARE PERMITTED: | ☒ Y ☐ N ☐ NA ☐ NE |

SECTION B: RECORDKEEPING AND REPORTING EVALUATION

RECORDS AND REPORTS MAINTAINED AS REQUIRED BY PERMIT

☐S ☐M ☒U ☐NA ☐NEDETAILS: No documentation provided by facility.

- | | |
|--|---|
| 1. ANALYTICAL RESULTS CONSISTENT WITH DATA REPORTED ON DMRS: | ☐ Y ☐ N ☐ NA ☒ NE |
| 2. SAMPLING AND ANALYSES DATA ADEQUATE AND INCLUDE: | ☐ S ☐ M ☐ U ☐ NA ☒ NE |
| a. DATES AND TIME(S) OF SAMPLING: | ☐ Y ☐ N ☐ NA ☒ NE |
| b. EXACT LOCATION(S) OF SAMPLING: | ☐ Y ☐ N ☐ NA ☒ NE |
| c. NAME OF INDIVIDUAL PERFORMING SAMPLING: | ☐ Y ☐ N ☐ NA ☒ NE |
| d. ANALYTICAL METHODS AND TECHNIQUES: | ☐ Y ☐ N ☐ NA ☒ NE |
| e. RESULTS OF CALIBRATIONS: | ☐ Y ☐ N ☐ NA ☒ NE |
| f. RESULTS OF ANALYSES: | ☐ Y ☐ N ☐ NA ☒ NE |
| g. DATES AND TIMES OF ANALYSES: | ☐ Y ☐ N ☐ NA ☒ NE |
| h. NAME OF PERSON(S) PERFORMING ANALYSES: | ☐ Y ☐ N ☐ NA ☒ NE |
| 3. LABORATORY EQUIPMENT CALIBRATION AND MAINTENANCE RECORDS ADEQUATE: | ☐ S ☐ M ☐ U ☐ NA ☒ NE |
| 4. PLANT RECORDS INCLUDE SCHEDULES, DATES OF EQUIPMENT MAINTENANCE AND REPAIR: | ☐ S ☐ M ☐ U ☐ NA ☒ NE |
| 5. EFFLUENT LOADINGS CALCULATED USING DAILY EFFLUENT FLOW AND DAILY ANALYTICAL DATA: | ☐ Y ☐ N ☐ NA ☒ NE |

SECTION C: OPERATIONS AND MAINTENANCE

TREATMENT FACILITY PROPERLY OPERATED AND MAINTAINED

☒S ☐M ☐U ☐NA ☐NE

DETAILS:

- | | |
|---|---|
| 1. TREATMENT UNITS PROPERLY OPERATED: | ☒ S ☐ M ☐ U ☐ NA ☐ NE |
| 2. TREATMENT UNITS PROPERLY MAINTAINED: | ☒ S ☐ M ☐ U ☐ NA ☐ NE |
| 3. STANDBY POWER OR OTHER EQUIVALENT PROVIDED: | ☐ S ☐ M ☐ U ☐ NA ☒ NE |
| 4. ADEQUATE ALARM SYSTEM FOR POWER OR EQUIPMENT FAILURES AVAILABLE: | ☐ S ☐ M ☐ U ☐ NA ☒ NE |
| 5. ALL NEEDED TREATMENT UNITS IN SERVICE: | ☒ S ☐ M ☐ U ☐ NA ☐ NE |
| 6. ADEQUATE NUMBER OF QUALIFIED OPERATORS PROVIDED: | ☐ S ☐ M ☐ U ☐ NA ☒ NE |
| 7. SPARE PARTS AND SUPPLIES INVENTORY MAINTAINED: | ☐ S ☐ M ☐ U ☒ NA ☐ NE |
| 8. OPERATION AND MAINTENANCE MANUAL AVAILABLE: | ☐ Y ☐ N ☒ NA ☐ NE |
| 9. STANDARD OPERATING PROCEDURES AND SCHEDULES ESTABLISHED: | ☐ Y ☐ N ☒ NA ☐ NE |
| 10. PROCEDURES FOR EMERGENCY TREATMENT CONTROL ESTABLISHED: | ☐ Y ☐ N ☒ NA ☐ NE |
| 11. HAVE BYPASSES/OVERFLOWS OCCURRED AT THE PLANT OR IN THE COLLECTION SYSTEM IN THE LAST YEAR: | ☐ Y ☐ N ☐ NA ☒ NE |
| 12. IF SO, HAS THE REGULATORY AGENCY BEEN NOTIFIED: | ☐ Y ☐ N ☒ NA ☐ NE |
| 13. HAS CORRECTIVE ACTION BEEN TAKEN TO PREVENT ADDITIONAL BYPASSES/OVERFLOWS. | ☐ Y ☐ N ☒ NA ☐ NE |
| 14. HAVE ANY HYDRAULIC OVERLOADS OCCURRED AT THE TREATMENT PLANT: | ☐ Y ☐ N ☐ NA ☐ NE |
| 15. IF SO, DID PERMIT VIOLATIONS OCCUR AS A RESULT: | ☐ Y ☐ N ☒ NA ☐ NE |

SECTION D: SAMPLING

PERMITTEE SAMPLING MEETS PERMIT REQUIREMENTS

☐S ☐M ☒U ☐NA ☐NEDETAILS: Facility was unable to provide any documentation to determine compliance.

- | | |
|---|--|
| 1. SAMPLES TAKEN AT SITE(S) SPECIFIED IN PERMIT: | ☐ Y ☒ N ☐ NA ☐ NE |
| 2. LOCATIONS ADEQUATE FOR REPRESENTATIVE SAMPLES: | ☒ Y ☐ N ☐ NA ☐ NE |
| 3. FLOW PROPORTIONED SAMPLES OBTAINED WHEN REQUIRED BY PERMIT: | ☐ Y ☐ N ☐ NA ☐ NE |
| 4. SAMPLING AND ANALYSES COMPLETED ON PARAMETERS SPECIFIED IN PERMIT: | ☐ Y ☐ N ☐ NA ☒ NE |
| 5. SAMPLING AND ANALYSES PERFORMED AT FREQUENCY SPECIFIED IN PERMIT: | ☐ Y ☐ N ☐ NA ☒ NE |
| 6. SAMPLE COLLECTION PROCEDURES ADEQUATE: | ☐ Y ☐ N ☐ NA ☒ NE |
| a. SAMPLES REFRIGERATED DURING COMPOSITING: | ☐ Y ☐ N ☐ NA ☒ NE |
| b. PROPER PRESERVATION TECHNIQUES USED: | ☐ Y ☐ N ☐ NA ☒ NE |
| c. CONTAINERS AND SAMPLE HOLDING TIMES CONFORM TO 40 CFR 136: | ☐ Y ☐ N ☐ NA ☒ NE |
| 7. IF MONITORING IS PERFORMED MORE OFTEN THAN REQUIRED ARE RESULTS REPORTED ON THE DMR: | ☐ Y ☐ N ☐ NA ☒ NE |

SECTION E: FLOW MEASUREMENT

PERMITTEE FLOW MEASUREMENT MEETS PERMIT REQUIREMENTS

☐S ☐M ☒U ☐NA ☐NEDETAILS: No flow records were provided by the facility.

- | | |
|--|--|
| 1. PRIMARY FLOW MEASUREMENT DEVICE PROPERLY INSTALLED AND MAINTAINED: TYPE OF DEVICE: <u>12" rec. weir w/o end</u> | ☒ Y ☐ N ☐ NA ☐ NE |
| 2. FLOW MEASURED AT EACH OUTFALL AS REQUIRED: | ☐ Y ☐ N ☐ NA ☒ NE |
| 3. SECONDARY INSTRUMENTS (TOTALIZERS, RECORDERS, ETC.) PROPERLY OPERATED AND MAINTAINED: | ☐ Y ☐ N ☒ NA ☐ NE |
| 4. CALIBRATION FREQUENCY ADEQUATE: <u>(Date of last calibration)</u> | ☐ Y ☐ N ☒ NA ☐ NE |
| 5. RECORDS MAINTAINED OF CALIBRATION PROCEDURES: | ☐ Y ☐ N ☒ NA ☐ NE |
| 6. CALIBRATION CHECKS DONE TO ASSURE CONTINUED COMPLIANCE: | ☐ Y ☐ N ☒ NA ☐ NE |
| 7. FLOW ENTERING DEVICE WELL DISTRIBUTED ACROSS THE CHANNEL AND FREE OF TURBULENCE: | ☒ Y ☐ N ☐ NA ☐ NE |
| 8. FLOW MEASUREMENT EQUIPMENT ADEQUATE TO HANDLE EXPECTED RANGE OF FLOW RATES: | ☒ Y ☐ N ☐ NA ☐ NE |
| 9. HEAD MEASURED AT PROPER LOCATION: | ☐ Y ☐ N ☒ NA ☐ NE |

SECTION F: LABORATORY

PERMITTEE LABORATORY PROCEDURES MEET PERMIT REQUIREMENTS

☐S ☐M ☒U ☐NA ☐NEDETAILS: No lab reports were provided by the facility.

- | | |
|---|--|
| 1. EPA APPROVED ANALYTICAL PROCEDURES USED (40 CFR 136.3 FOR LIQUIDS, 503.8(B) FOR SLUDGES) : | ☐ Y ☐ N ☐ NA ☒ NE |
| 2. IF ALTERNATIVE ANALYTICAL PROCEDURES ARE USED, PROPER APPROVAL HAS BEEN OBTAINED: | ☐ Y ☐ N ☐ NA ☒ NE |
| 3. SATISFACTORY CALIBRATION AND MAINTENANCE OF INSTRUMENTS AND EQUIPMENT: | ☐ Y ☐ N ☐ NA ☒ NE |
| 4. QUALITY CONTROL PROCEDURES ADEQUATE: | ☐ Y ☐ N ☐ NA ☒ NE |
| 5. DUPLICATE SAMPLES ARE ANALYZED $\geq 10\%$ OF THE TIME: | ☐ Y ☐ N ☐ NA ☒ NE |
| 6. SPIKED SAMPLES ARE ANALYZED $\geq 10\%$ OF THE TIME: | ☐ Y ☐ N ☐ NA ☒ NE |
| 7. COMMERCIAL LABORATORY USED: | ☐ Y ☐ N ☐ NA ☒ NE |
| a. LAB NAME: <u>Unknown</u> | |
| b. LAB ADDRESS: <u>NA</u> | |
| c. PARAMETERS PERFORMED: <u>NA</u> | |
| 8. BIOMONITORING PROCEDURES ADEQUATE: | ☐ Y ☐ N ☒ NA ☐ NE |
| a. PROPER ORGANISMS USED: | ☐ Y ☐ N ☒ NA ☐ NE |
| b. PROPER DILUTION SERIES FOLLOWED: | ☐ Y ☐ N ☒ NA ☐ NE |
| c. PROPER TEST METHODS AND DURATION: | ☐ Y ☐ N ☒ NA ☐ NE |
| d. RETESTS AND/OR TRE PERFORMED AS REQUIRED: | ☐ Y ☐ N ☒ NA ☐ NE |

SECTION G: EFFLUENT/RECEIVING WATERS OBSERVATIONS							
BASED ON VISUAL OBSERVATIONS ONLY						☐ S ☒ M ☐ U ☐ NA ☐ NE	
DETAILS:							
OUTFALL #:	OIL SHEEN	GREASE	TURBIDITY	VISIBLE FOAM	FLOATING SOLIDS	COLOR	OTHER
002	None	None	moderate	None	moderate	brown	
003	No Discharge	N/D	N/D	N/D	N/D	N/D	N/D
SECTION H: SLUDGE DISPOSAL							
SLUDGE DISPOSAL MEETS PERMIT REQUIREMENTS						☒ S ☐ M ☐ U ☐ NA ☐ NE	
DETAILS: <u>No sludge as recently been removed.</u>							
1. SLUDGE MANAGEMENT ADEQUATE TO MAINTAIN EFFLUENT QUALITY:						☒ S ☐ M ☐ U ☐ NA ☐ NE	
2. SLUDGE RECORDS MAINTAINED AS REQUIRED BY 40 CFR 503:						☐ S ☐ M ☐ U ☒ NA ☐ NE	
3. FOR LAND APPLIED SLUDGE, TYPE OF LAND APPLIED TO: (E.G., FOREST, AGRICULTURAL, PUBLIC CONTACT SITE):							
SECTION I: SAMPLING INSPECTION PROCEDURES							
SAMPLE RESULTS WITHIN PERMIT REQUIREMENTS						☐ S ☐ M ☐ U ☒ NA ☐ NE	
DETAILS:							
1. SAMPLES OBTAINED THIS INSPECTION:						☐ Y ☐ N ☒ NA ☐ NE	
2. TYPE OF SAMPLE: ☐ GRAB:___ ☐ COMPOSITE:___ METHOD:___ FREQUENCY:___							
3. SAMPLES PRESERVED:						☐ Y ☐ N ☒ NA ☐ NE	
4. FLOW PROPORTIONED SAMPLES OBTAINED:						☐ Y ☐ N ☒ NA ☐ NE	
5. SAMPLE OBTAINED FROM FACILITY'S SAMPLING DEVICE:						☐ Y ☐ N ☒ NA ☐ NE	
6. SAMPLE REPRESENTATIVE OF VOLUME AND NATURE OF DISCHARGE:						☐ Y ☐ N ☒ NA ☐ NE	
7. SAMPLE SPLIT WITH PERMITTEE:						☐ Y ☐ N ☒ NA ☐ NE	
8. CHAIN-OF-CUSTODY PROCEDURES EMPLOYED:						☐ Y ☐ N ☒ NA ☐ NE	
9. SAMPLES COLLECTED IN ACCORDANCE WITH PERMIT:						☐ Y ☐ N ☒ NA ☐ NE	
SECTION J: STORM WATER POLLUTION PREVENTION PLAN							
STORM WATER MANAGEMENT MEETS PERMIT REQUIREMENTS						☐ S ☐ M ☐ U ☒ NA ☐ NE	
DETAILS:							
1. SWPPP UPDATED AS NEEDED:___ DATE OF LAST UPDATE:___						☐ Y ☐ N ☒ NA ☐ NE	
2. SITE MAP INCLUDING ALL DISCHARGES AND SURFACE WATERS:						☐ Y ☐ N ☒ NA ☐ NE	
3. POLLUTION PREVENTION TEAM IDENTIFIED:						☐ Y ☐ N ☒ NA ☐ NE	
4. POLLUTION PREVENTION TEAM PROPERLY TRAINED:						☐ Y ☐ N ☒ NA ☐ NE	
5. LIST OF POTENTIAL POLLUTANT SOURCES:						☐ Y ☐ N ☒ NA ☐ NE	
6. LIST OF POTENTIAL SOURCES AND PAST SPILLS AND LEAKS:						☐ Y ☐ N ☒ NA ☐ NE	
7. ALL NON-STORM WATER DISCHARGES ARE AUTHORIZED:						☐ Y ☐ N ☒ NA ☐ NE	
8. LIST OF STRUCTURAL BMPS:						☐ Y ☐ N ☒ NA ☐ NE	
9. LIST OF NON-STRUCTURAL BMPS:						☐ Y ☐ N ☒ NA ☐ NE	
10. BMPS PROPERLY OPERATED AND MAINTAINED:						☐ Y ☐ N ☒ NA ☐ NE	
11. INSPECTIONS CONDUCTED AS REQUIRED:						☐ Y ☐ N ☒ NA ☐ NE	

FLOW CALCULATION SHEET

Date: **NA**Time: **NA**

Head in Inches:

Feet:

Type & Size of Primary Flow Measurement Device:

NA

Name & Model of Secondary Flow Measurement Device:

NADate of last Calibration of Secondary Flow Device: **NA**

Recorded Flow at Date & Time Listed Above:

(Facility Flow Meter)

Calculated Flow at Date & Time Listed Above:

(Flow is calculated using flow charts in: ISCO Open Channel Flow Measurement Handbook-5th Edition -Table # 13-4)

% Error =

Recorded

-

Calculated

X 100

Calculated

% Error =

-

X 100

% Error =

-

X 100

% Error =

-

X 100

% Error =

%

Comments: **No totalizer, therefore a flow check was not performed.**

DMR Calculation Check

Reporting Period:	From	<u>NA</u>	<u>NA</u>	<u>NA</u>	To	<u>NA</u>	<u>NA</u>	<u>NA</u>
		Year	Month	Day		Year	Month	Day

Parameter Checked: NA

	Minimum	Maximum
Reported Value:		
Calculated Value:		
Permit Value:		

If calculated value does not equal reported value, explain: <u>any DMR's for review.</u>	<u>Facility was unable to provide</u>

ADEQ Water NPDES Inspection	AFIN: 24-00002	Permit #: AR0034592
-----------------------------	----------------	---------------------

Water Division NPDES Photographic Evidence Sheet

Location: Wiederkehr Wine Cellars Inc. located at 3324 Swiss Family Drive in Franklin County							
Photographer: Jeff Tyler				Witness: None			
1	Of	4		Date:	10-29-09	Time:	1550
Description:		View of outfall 002 at time of inspection with discharge.					



Photographer: Jeff Tyler				Witness: None			
2	Of	4		Date:	10-29-09	Time:	1602
Description:		Outfall 003(green pipe) with no discharge. Visible flow is from storm water.					



ADEQ Water NPDES Inspection	AFIN: 24-00002	Permit #: AR0034592
-----------------------------	----------------	---------------------

Water Division NPDES Photographic Evidence Sheet

Location: Wiederkehr Wine Cellars Inc. located at 3324 Swiss Family Drive in Franklin County.							
Photographer: Jeff Tyler				Witness: None			
3	Of	4		Date:	10-29-09	Time:	1609
Description:		Outside storage area for used oil from the compressor with no protection from rainfall.					



Photographer: Jeff Tyler				Witness: None			
4	Of	4		Date:	10-29-09	Time:	1610
Description:		Used oil on the ground observed at storage area from compressor.					





March 18, 2010

Mr. Gary Wiederkehr, President
Wiederkehr Wine Cellars, Inc.
3324 Swiss Family Drive
Altus, AR 72821

RE: Permit No.: AR0034592, AFIN: 24-00002
Response to Inspection

Dear Mr. Wiederkehr:

The Department has received your response to the October 29, 2009 inspection of your facility by our District Field Inspector, Jeff Tyler. Your letter appears to adequately address the discrepancies identified during the visit. The Department assumes the corrective actions taken will be maintained to ensure consistent compliance with the requirements of the permit. Acceptance of this response by the Department does not preclude any future enforcement action deemed necessary at this site or any other site.

The Department will keep the inspection and response on file. If future violations occur that require enforcement action, the Department will consider the inspection and response as required by the Pollution Control and Ecology Commission Regulation No. 7, Civil Penalties. This regulation requires the Department to consider the past history of your facility and how expeditiously the violations were addressed in determining any civil penalty that may be necessary for any future violations.

If we need further information concerning this matter, we will contact you. Thank you for your attention to this matter. Should you have any questions, feel free to contact me at 501-682-0823 or you may e-mail me at woodbury@adeq.state.ar.us.

Sincerely,

Anne Woodbury,
Enforcement Analyst
Water Division Enforcement Branch