

## ANALYTICAL RESULTS

Prepared by:

Eurofins Lancaster Laboratories Environmental  
2425 New Holland Pike  
Lancaster, PA 17601

Prepared for:

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

August 23, 2013

Project: Mayflower, AR Pipeline Incident

Submittal Date: 08/16/2013

Group Number: 1412007

SDG: PEK68

PO Number: B0086003.1301

State of Sample Origin: AR

### Client Sample Description

<u>Client Sample Description</u>	<u>Lancaster Labs (LL) #</u>
WS-014(1.5-2.0)081513 Grab Surface Water	7163651
WS-014(5.5-6.0)081513 Grab Surface Water	7163652
WS-012(1.5-2.0)081513 Grab Surface Water	7163653
WS-012(5.0-5.5)081513 Grab Surface Water	7163654
WS-010(1.5-2.0)081513 Grab Surface Water	7163655
WS-010(3.5-4.0)081513 Grab Surface Water	7163656
WS-006(0.5-1.0)081513 Grab Surface Water	7163657
WS-005(Surface)081513 Grab Surface Water	7163658
WS-002(Surface)081513 Grab Surface Water	7163659
WS-018(Surface)081513 Grab Surface Water	7163660
WS-011(1.5-2.0)081513 Grab Surface Water	7163661
WS-011(5.0-5.5)081513 Grab Surface Water	7163662
WS-003(Surface)081513 Grab Surface Water	7163663
WS-007(0.5-1.0)081513 Grab Surface Water	7163664
WS-001(0.5-1.0)081513 Grab Surface Water	7163665
WS-BKG-002(Surface)081513 Grab Surface Water	7163666
WS-008(Surface)081513 Grab Surface Water	7163667
DUP-WS-71-081513 Grab Surface Water	7163668
WS-EB-30-081513 Grab Water	7163669
WS-TB-124-081513 Water	7163670

The specific methodologies used in obtaining the enclosed analytical results are indicated on the Laboratory Sample Analysis Record.

ELECTRONIC     ARCADIS  
COPY TO  
ELECTRONIC     ARCADIS  
COPY TO

Attn: Stephen Barrick

Attn: Lyndi Mott

ELECTRONIC COPY TO	ExxonMobil	Attn: Michael J. Firth
ELECTRONIC COPY TO	ARCADIS	Attn: Emily Leamer
ELECTRONIC COPY TO	ARCADIS	Attn: Rhiannon Parmalee
ELECTRONIC COPY TO	ARCADIS	Attn: Jamie Pritchard
ELECTRONIC COPY TO	ExxonMobil	Attn: Michael L Sixsmith
ELECTRONIC COPY TO	ExxonMobil	Attn: Julie Foster
ELECTRONIC COPY TO	ExxonMobil	Attn: Carl Wideman

Respectfully Submitted,



Katherine A. Klinefelter  
Principal Specialist

(717) 556-7256

---

Project Name: Mayflower, AR Pipeline Incident  
LLI Group #: 1412007

**General Comments:**

See the Laboratory Sample Analysis Record section of the Analysis Report for the method references.

All QC met criteria unless otherwise noted in an Analysis Specific Comment below. Refer to the QC Summary for specific values and acceptance criteria.

Project specific QC samples are not included in this data set

Matrix QC may not be reported if site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD was performed, unless otherwise specified in the method.

Surrogate recoveries (if applicable) which are outside of the QC window are confirmed unless attributed to a dilution or otherwise noted in an Analysis Specific Comment below.

The samples were received at the appropriate temperature and in accordance with the chain of custody unless otherwise noted.

**Analysis Specific Comments:****SW-846 8260B 25mL purge, GC/MS Volatiles**

Batch #: C132282AA (Sample number(s): 7163651-7163670 UNSPK: 7163651)

The recovery(ies) for the following analyte(s) in the MS and/or MSD was outside the acceptance window: Bromomethane, Trichlorofluoromethane, Hexachlorobutadiene

**SW-846 8270C SIM, GC/MS Semivolatiles**

Batch #: 13229WAB026 (Sample number(s): 7163651-7163669)

The recovery(ies) for the following analyte(s) in the LCS and/or LCSD exceeded the acceptance window indicating a positive bias: Acenaphthylene

The recovery(ies) for one or more surrogates were outside of the QC window for sample(s) 7163663, 7163664

**Sample #s: 7163651**

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

Sample #s: 7163652, 7163653, 7163654, 7163655, 7163656, 7163657, 7163658, 7163659, 7163660, 7163661, 7163662, 7163665, 7163666, 7163667, 7163668, 7163669

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

**Sample #s: 7163663, 7163664**

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis. The recovery for the sample surrogate(s) is outside the QC acceptance limits as noted on the QC Summary. The client was contacted and the data reported.

Sample Description: **WS-014(1.5-2.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163651**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 08:20 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15141 SDG#: PEK68-01

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-014(1.5-2.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163651**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 08:20 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15141 SDG#: PEK68-01

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
		<b>purge</b>				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	0.1 J	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.053	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.053	1
08357	Anthracene	120-12-7	N.D.	0.011	0.053	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.053	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.053	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.053	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.053	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.053	1
08357	Chrysene	218-01-9	N.D.	0.011	0.053	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.053	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.053	1
08357	Fluorene	86-73-7	N.D.	0.011	0.053	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.053	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.053	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.053	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.053	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.053	1
08357	Pyrene	129-00-0	N.D.	0.011	0.053	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	27.1	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0455	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-014(1.5-2.0)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163651  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 08:20 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15141 SDG#: PEK68-01

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	6.19	0.0334	0.200	1
07051	Chromium	7440-47-3	0.0027 J	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.83	0.0167	0.100	1
07061	Nickel	7440-02-0	0.0016 J	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	2.0 J	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/16/2013 23:41	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/16/2013 23:41	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 05:08	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 20:49	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 20:49	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 20:49	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 20:49	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 20:49	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 20:49	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 20:49	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 20:49	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 20:49	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 20:49	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 20:49	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 08:59	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-014(5.5-6.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163652**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 08:30 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15142 SDG#: PEK68-02

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-014(5.5-6.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163652**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 08:30 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15142 SDG#: PEK68-02

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.055	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.055	1
08357	Anthracene	120-12-7	N.D.	0.011	0.055	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.055	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.055	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.055	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.055	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.055	1
08357	Chrysene	218-01-9	N.D.	0.011	0.055	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.055	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.055	1
08357	Fluorene	86-73-7	N.D.	0.011	0.055	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.055	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.055	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.055	1
08357	Naphthalene	91-20-3	N.D.	0.033	0.055	1
08357	Phenanthrene	85-01-8	N.D.	0.033	0.055	1
08357	Pyrene	129-00-0	N.D.	0.011	0.055	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	26.5	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0444	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result



Sample Description: WS-014(5.5-6.0)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163652  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 08:30 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15142 SDG#: PEK68-02

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	6.04	0.0334	0.200	1
07051	Chromium	7440-47-3	0.0017 J	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.77	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 02:40	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 02:40	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 05:38	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 20:53	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 20:53	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 20:53	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 20:53	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 20:53	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 20:53	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 20:53	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 20:53	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 20:53	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 20:53	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 20:53	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:11	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-012(1.5-2.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163653**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 08:40 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15121 SDG#: PEK68-03

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-012(1.5-2.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163653**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 08:40 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15121 SDG#: PEK68-03

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
		<b>purge</b>				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.054	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.054	1
08357	Anthracene	120-12-7	N.D.	0.011	0.054	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.054	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.054	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.054	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.054	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.054	1
08357	Chrysene	218-01-9	N.D.	0.011	0.054	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.054	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.054	1
08357	Fluorene	86-73-7	N.D.	0.011	0.054	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.054	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.054	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.054	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.054	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.054	1
08357	Pyrene	129-00-0	N.D.	0.011	0.054	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	26.0	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0455	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-012(1.5-2.0)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163653  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 08:40 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15121 SDG#: PEK68-03

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	5.93	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.72	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 03:02	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 03:02	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 06:07	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:05	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:05	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:05	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:05	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:05	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:05	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:05	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:05	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:05	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:05	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:05	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:13	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-012(5.0-5.5)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163654**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 08:50 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15122 SDG#: PEK68-04

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-012(5.0-5.5)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163654**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 08:50 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15122 SDG#: PEK68-04

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.053	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.053	1
08357	Anthracene	120-12-7	N.D.	0.011	0.053	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.053	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.053	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.053	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.053	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.053	1
08357	Chrysene	218-01-9	N.D.	0.011	0.053	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.053	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.053	1
08357	Fluorene	86-73-7	N.D.	0.011	0.053	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.053	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.053	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.053	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.053	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.053	1
08357	Pyrene	129-00-0	N.D.	0.011	0.053	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	25.7	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0437	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-012(5.0-5.5)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163654  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 08:50 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15122 SDG#: PEK68-04

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	5.86	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.69	0.0167	0.100	1
07061	Nickel	7440-02-0	0.0016 J	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	1.5 J	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 03:24	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 03:24	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 06:37	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:08	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:08	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:08	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:08	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:08	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:08	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:08	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:08	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:08	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:08	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:08	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:15	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-010(1.5-2.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163655**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 09:10 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15101 SDG#: PEK68-05

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result



Sample Description: **WS-010(1.5-2.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163655**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 09:10 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15101 SDG#: PEK68-05

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.055	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.055	1
08357	Anthracene	120-12-7	N.D.	0.011	0.055	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.055	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.055	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.055	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.055	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.055	1
08357	Chrysene	218-01-9	N.D.	0.011	0.055	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.055	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.055	1
08357	Fluorene	86-73-7	N.D.	0.011	0.055	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.055	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.055	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.055	1
08357	Naphthalene	91-20-3	N.D.	0.033	0.055	1
08357	Phenanthrene	85-01-8	N.D.	0.033	0.055	1
08357	Pyrene	129-00-0	N.D.	0.011	0.055	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	23.6	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0323	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-010(1.5-2.0)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163655  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 09:10 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15101 SDG#: PEK68-05

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	5.38	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.47	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	1.9 J	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 03:47	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 03:47	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 07:06	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:12	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:12	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:12	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:12	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:12	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:12	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:12	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:12	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:12	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:12	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:12	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:17	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-010(3.5-4.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163656**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 09:20 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15102 SDG#: PEK68-06

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-010(3.5-4.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163656**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 09:20 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15102 SDG#: PEK68-06

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	0.1 J	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.053	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.053	1
08357	Anthracene	120-12-7	N.D.	0.011	0.053	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.053	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.053	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.053	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.053	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.053	1
08357	Chrysene	218-01-9	N.D.	0.011	0.053	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.053	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.053	1
08357	Fluorene	86-73-7	N.D.	0.011	0.053	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.053	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.053	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.053	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.053	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.053	1
08357	Pyrene	129-00-0	N.D.	0.011	0.053	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	24.4	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0337	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-010(3.5-4.0)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163656  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 09:20 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15102 SDG#: PEK68-06

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	5.56	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.54	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 04:09	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 04:09	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 07:35	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:16	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:16	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:16	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:16	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:16	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:16	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:16	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:16	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:16	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:16	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:16	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:19	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-006(0.5-1.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163657**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 09:30 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15006 SDG#: PEK68-07

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-006(0.5-1.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163657**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 09:30 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15006 SDG#: PEK68-07

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.054	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.054	1
08357	Anthracene	120-12-7	N.D.	0.011	0.054	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.054	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.054	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.054	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.054	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.054	1
08357	Chrysene	218-01-9	N.D.	0.011	0.054	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.054	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.054	1
08357	Fluorene	86-73-7	N.D.	0.011	0.054	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.054	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.054	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.054	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.054	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.054	1
08357	Pyrene	129-00-0	N.D.	0.011	0.054	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	24.9	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0381	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-006(0.5-1.0)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163657  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 09:30 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15006 SDG#: PEK68-07

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	5.66	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.61	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	1.6 J	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 04:32	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 04:32	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 08:05	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 20:27	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 20:27	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 20:27	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 20:27	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 20:27	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 20:27	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 20:27	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 20:27	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 20:27	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 20:27	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 20:27	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:21	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result



Sample Description: WS-005 (Surface) 081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163658  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 10:00 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15005 SDG#: PEK68-08

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-005 (Surface) 081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163658**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 10:00 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15005 SDG#: PEK68-08

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
		<b>purge</b>				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.051	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.051	1
08357	Anthracene	120-12-7	N.D.	0.010	0.051	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.010	0.051	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.051	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.010	0.051	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.051	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.010	0.051	1
08357	Chrysene	218-01-9	N.D.	0.010	0.051	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.051	1
08357	Fluoranthene	206-44-0	N.D.	0.010	0.051	1
08357	Fluorene	86-73-7	N.D.	0.010	0.051	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.051	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.051	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.051	1
08357	Naphthalene	91-20-3	N.D.	0.030	0.051	1
08357	Phenanthrene	85-01-8	N.D.	0.030	0.051	1
08357	Pyrene	129-00-0	N.D.	0.010	0.051	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	26.6	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0397	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-005 (Surface) 081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163658  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 10:00 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15005 SDG#: PEK68-08

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	6.17	0.0334	0.200	1
07051	Chromium	7440-47-3	0.0016 J	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.73	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 04:54	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 04:54	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 08:34	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:20	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:20	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:20	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:20	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:20	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:20	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:20	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:20	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:20	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:20	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:20	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:23	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-002 (Surface) 081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163659**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 10:20 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15002 SDG#: PEK68-09

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-002 (Surface) 081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163659**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 10:20 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15002 SDG#: PEK68-09

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.051	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.051	1
08357	Anthracene	120-12-7	N.D.	0.010	0.051	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.010	0.051	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.051	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.010	0.051	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.051	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.010	0.051	1
08357	Chrysene	218-01-9	N.D.	0.010	0.051	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.051	1
08357	Fluoranthene	206-44-0	N.D.	0.010	0.051	1
08357	Fluorene	86-73-7	N.D.	0.010	0.051	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.051	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.051	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.051	1
08357	Naphthalene	91-20-3	N.D.	0.030	0.051	1
08357	Phenanthrene	85-01-8	N.D.	0.030	0.051	1
08357	Pyrene	129-00-0	N.D.	0.010	0.051	1
The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.						
<b>Metals</b>		<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
06256	Total Hardness as CaCO3	471-34-1	27.0	0.033	0.20	1
		<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0390	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-002 (Surface) 081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163659**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 10:20 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15002 SDG#: PEK68-09

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	6.16	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.83	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

**General Sample Comments**

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

**Laboratory Sample Analysis Record**

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 05:17	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 05:17	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 09:04	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:24	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:24	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:24	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:24	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:24	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:24	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:24	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:24	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:24	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:24	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:24	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:25	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-018 (Surface) 081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163660**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 10:40 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15018 SDG#: PEK68-10

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-018 (Surface) 081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163660**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 10:40 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15018 SDG#: PEK68-10

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
		<b>purge</b>				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.051	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.051	1
08357	Anthracene	120-12-7	N.D.	0.010	0.051	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.010	0.051	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.051	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.010	0.051	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.051	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.010	0.051	1
08357	Chrysene	218-01-9	N.D.	0.010	0.051	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.051	1
08357	Fluoranthene	206-44-0	N.D.	0.010	0.051	1
08357	Fluorene	86-73-7	N.D.	0.010	0.051	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.051	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.051	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.051	1
08357	Naphthalene	91-20-3	N.D.	0.030	0.051	1
08357	Phenanthrene	85-01-8	N.D.	0.030	0.051	1
08357	Pyrene	129-00-0	N.D.	0.010	0.051	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	26.6	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0382	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result



Sample Description: WS-018 (Surface) 081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163660  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 10:40 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15018 SDG#: PEK68-10

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	6.02	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.80	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
<b>SW-846 7470A</b>						
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 05:39	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 05:39	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 09:34	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:27	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:27	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:27	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:27	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:27	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:27	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:27	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:27	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:27	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:27	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:27	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:31	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-011(1.5-2.0)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163661  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 11:10 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15111 SDG#: PEK68-11

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-011(1.5-2.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163661**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 11:10 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15111 SDG#: PEK68-11

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
		<b>purge</b>				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	0.1 J	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.052	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.052	1
08357	Anthracene	120-12-7	N.D.	0.010	0.052	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.010	0.052	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.052	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.010	0.052	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.052	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.010	0.052	1
08357	Chrysene	218-01-9	N.D.	0.010	0.052	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.052	1
08357	Fluoranthene	206-44-0	N.D.	0.010	0.052	1
08357	Fluorene	86-73-7	N.D.	0.010	0.052	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.052	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.052	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.052	1
08357	Naphthalene	91-20-3	N.D.	0.031	0.052	1
08357	Phenanthrene	85-01-8	N.D.	0.031	0.052	1
08357	Pyrene	129-00-0	N.D.	0.010	0.052	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	26.4	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0529	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-011(1.5-2.0)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163661  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 11:10 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15111 SDG#: PEK68-11

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	5.95	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.80	0.0167	0.100	1
07061	Nickel	7440-02-0	0.0015 J	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
<b>SW-846 7470A</b>						
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 06:01	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 06:01	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 10:03	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:31	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:31	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:31	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:31	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:31	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:31	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:31	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:31	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:31	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:31	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:31	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:33	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-011(5.0-5.5)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163662**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 11:20 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15112 SDG#: PEK68-12

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-011(5.0-5.5)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163662**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 11:20 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15112 SDG#: PEK68-12

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.054	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.054	1
08357	Anthracene	120-12-7	N.D.	0.011	0.054	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.054	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.054	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.054	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.054	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.054	1
08357	Chrysene	218-01-9	N.D.	0.011	0.054	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.054	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.054	1
08357	Fluorene	86-73-7	N.D.	0.011	0.054	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.054	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.054	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.054	1
08357	Naphthalene	91-20-3	N.D.	0.033	0.054	1
08357	Phenanthrene	85-01-8	N.D.	0.033	0.054	1
08357	Pyrene	129-00-0	N.D.	0.011	0.054	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	26.5	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0545	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-011(5.0-5.5)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163662  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 11:20 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15112 SDG#: PEK68-12

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	5.97	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.83	0.0167	0.100	1
07061	Nickel	7440-02-0	0.0016 J	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 06:24	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 06:24	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 10:33	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:35	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:35	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:35	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:35	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:35	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:35	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:35	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:35	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:35	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:35	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:35	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:35	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-003 (Surface) 081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163663  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 11:30 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15003 SDG#: PEK68-13

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result



Sample Description: **WS-003 (Surface) 081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163663**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 11:30 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15003 SDG#: PEK68-13

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	0.1 J	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.051	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.051	1
08357	Anthracene	120-12-7	N.D.	0.010	0.051	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.010	0.051	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.051	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.010	0.051	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.051	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.010	0.051	1
08357	Chrysene	218-01-9	N.D.	0.010	0.051	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.051	1
08357	Fluoranthene	206-44-0	N.D.	0.010	0.051	1
08357	Fluorene	86-73-7	N.D.	0.010	0.051	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.051	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.051	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.051	1
08357	Naphthalene	91-20-3	N.D.	0.030	0.051	1
08357	Phenanthrene	85-01-8	N.D.	0.030	0.051	1
08357	Pyrene	129-00-0	N.D.	0.010	0.051	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

The recovery for the sample surrogate(s) is outside the QC acceptance limits as noted on the QC Summary. The client was contacted and the data reported.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	27.9	0.033	0.20	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-003 (Surface) 081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163663  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 11:30 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15003 SDG#: PEK68-13

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
		<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0432	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
01750	Calcium	7440-70-2	6.33	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.95	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		<b>SW-846 7470A</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
		<b>EPA 1664A</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 06:46	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 06:46	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 11:03	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:39	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:39	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:39	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:39	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:39	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:39	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:39	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:39	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:39	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:39	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:39	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:37	Damary Valentin	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-003 (Surface) 081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163663  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 11:30 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15003 SDG#: PEK68-13

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-007(0.5-1.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163664**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 11:40 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15007 SDG#: PEK68-14

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-007(0.5-1.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163664**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 11:40 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15007 SDG#: PEK68-14

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	0.4 J	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.050	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.050	1
08357	Anthracene	120-12-7	0.019 J	0.010	0.050	1
08357	Benzo(a)anthracene	56-55-3	0.020 J	0.010	0.050	1
08357	Benzo(a)pyrene	50-32-8	0.021 J	0.010	0.050	1
08357	Benzo(b)fluoranthene	205-99-2	0.042 J	0.010	0.050	1
08357	Benzo(g,h,i)perylene	191-24-2	0.018 J	0.010	0.050	1
08357	Benzo(k)fluoranthene	207-08-9	0.035 J	0.010	0.050	1
08357	Chrysene	218-01-9	0.045 J	0.010	0.050	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.050	1
08357	Fluoranthene	206-44-0	0.084	0.010	0.050	1
08357	Fluorene	86-73-7	N.D.	0.010	0.050	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	0.019 J	0.010	0.050	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.050	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.050	1
08357	Naphthalene	91-20-3	N.D.	0.030	0.050	1
08357	Phenanthrene	85-01-8	0.032 J	0.030	0.050	1
08357	Pyrene	129-00-0	0.086	0.010	0.050	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

The recovery for the sample surrogate(s) is outside the QC acceptance limits as noted on the QC Summary. The client was contacted and the data reported.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	15.4	0.033	0.20	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-007(0.5-1.0)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163664  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 11:40 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15007 SDG#: PEK68-14

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
		<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0293	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
01750	Calcium	7440-70-2	3.59	0.0334	0.200	1
07051	Chromium	7440-47-3	0.0022 J	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	1.57	0.0167	0.100	1
07061	Nickel	7440-02-0	0.0023 J	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		<b>SW-846 7470A</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
		<b>EPA 1664A</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 07:09	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 07:09	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 11:33	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:50	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:50	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:50	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:50	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:50	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:50	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:50	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:50	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:50	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:50	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:50	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:39	Damary Valentin	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-007(0.5-1.0)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163664  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 11:40 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15007 SDG#: PEK68-14

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-001(0.5-1.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163665**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 11:50 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15001 SDG#: PEK68-15

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result



Sample Description: **WS-001(0.5-1.0)081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163665**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 11:50 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15001 SDG#: PEK68-15

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.051	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.051	1
08357	Anthracene	120-12-7	N.D.	0.010	0.051	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.010	0.051	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.051	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.010	0.051	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.051	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.010	0.051	1
08357	Chrysene	218-01-9	N.D.	0.010	0.051	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.051	1
08357	Fluoranthene	206-44-0	N.D.	0.010	0.051	1
08357	Fluorene	86-73-7	N.D.	0.010	0.051	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.051	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.051	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.051	1
08357	Naphthalene	91-20-3	N.D.	0.030	0.051	1
08357	Phenanthrene	85-01-8	N.D.	0.030	0.051	1
08357	Pyrene	129-00-0	N.D.	0.010	0.051	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	24.3	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0330	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-001(0.5-1.0)081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163665  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 11:50 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15001 SDG#: PEK68-15

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	5.54	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.53	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 07:32	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 07:32	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 12:03	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:54	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:54	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:54	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:54	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:54	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:54	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:54	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:54	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:54	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:54	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:54	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:42	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-BKG-002 (Surface) 081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163666**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 12:10 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15BK2 SDG#: PEK68-16

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-BKG-002 (Surface) 081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163666**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 12:10 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15BK2 SDG#: PEK68-16

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.053	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.053	1
08357	Anthracene	120-12-7	N.D.	0.011	0.053	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.053	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.053	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.053	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.053	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.053	1
08357	Chrysene	218-01-9	N.D.	0.011	0.053	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.053	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.053	1
08357	Fluorene	86-73-7	N.D.	0.011	0.053	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.053	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.053	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.053	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.053	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.053	1
08357	Pyrene	129-00-0	N.D.	0.011	0.053	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	20.0	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0333	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

Sample Description: **WS-BKG-002 (Surface) 081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163666**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 12:10 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15BK2 SDG#: PEK68-16

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	4.99	0.0334	0.200	1
07051	Chromium	7440-47-3	0.0026 J	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	1.84	0.0167	0.100	1
07061	Nickel	7440-02-0	0.0029 J	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	0.0034 J	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 07:58	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 07:58	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 12:33	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 21:58	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 21:58	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 21:58	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 21:58	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 21:58	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 21:58	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 21:58	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 21:58	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 21:58	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 21:58	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 21:58	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:44	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-008 (Surface) 081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163667**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 12:20 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15008 SDG#: PEK68-17

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-008 (Surface) 081513 Grab Surface Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163667**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 12:20 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15008 SDG#: PEK68-17

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.052	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.052	1
08357	Anthracene	120-12-7	N.D.	0.010	0.052	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.010	0.052	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.052	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.010	0.052	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.052	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.010	0.052	1
08357	Chrysene	218-01-9	N.D.	0.010	0.052	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.052	1
08357	Fluoranthene	206-44-0	N.D.	0.010	0.052	1
08357	Fluorene	86-73-7	N.D.	0.010	0.052	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.052	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.052	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.052	1
08357	Naphthalene	91-20-3	N.D.	0.031	0.052	1
08357	Phenanthrene	85-01-8	N.D.	0.031	0.052	1
08357	Pyrene	129-00-0	N.D.	0.010	0.052	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	51.8	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0249	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-008 (Surface) 081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163667  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 12:20 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15008 SDG#: PEK68-17

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	10.5	0.0334	0.200	1
07051	Chromium	7440-47-3	0.0021 J	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	6.20	0.0167	0.100	1
07061	Nickel	7440-02-0	0.0022 J	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 08:21	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 08:21	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 13:04	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 22:01	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 22:01	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 22:01	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 22:01	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 22:01	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 22:01	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 22:01	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 22:01	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 22:01	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 22:01	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 22:01	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:46	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result



Sample Description: DUP-WS-71-081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163668  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15D71 SDG#: PEK68-18FD

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: DUP-WS-71-081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163668  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15D71 SDG#: PEK68-18FD

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
		<b>purge</b>				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.055	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.055	1
08357	Anthracene	120-12-7	N.D.	0.011	0.055	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.055	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.055	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.055	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.055	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.055	1
08357	Chrysene	218-01-9	N.D.	0.011	0.055	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.055	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.055	1
08357	Fluorene	86-73-7	N.D.	0.011	0.055	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.055	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.055	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.055	1
08357	Naphthalene	91-20-3	N.D.	0.033	0.055	1
08357	Phenanthrene	85-01-8	N.D.	0.033	0.055	1
08357	Pyrene	129-00-0	N.D.	0.011	0.055	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	24.2	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0359	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: DUP-WS-71-081513 Grab Surface Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163668  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013 by HVA

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15D71 SDG#: PEK68-18FD

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
	<b>SW-846 6010B</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	5.50	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.53	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	<b>SW-846 7470A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
<b>Wet Chemistry</b>						
	<b>EPA 1664A</b>		<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 08:43	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 08:43	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 13:34	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 22:05	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 22:05	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 22:05	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 22:05	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 22:05	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 22:05	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 22:05	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 22:05	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 22:05	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 22:05	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 22:05	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:48	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1
08079	HEM (oil & grease)	EPA 1664A	1	13234807902A	08/22/2013 16:48	Michelle L Lalli	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-EB-30-081513 Grab Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163669**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 13:00 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15E30 SDG#: PEK68-19EB

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-EB-30-081513 Grab Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163669**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 13:00 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15E30 SDG#: PEK68-19EB

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
		<b>purge</b>				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
<b>GC/MS</b>	<b>Semivolatiles</b>	<b>SW-846 8270C SIM</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.056	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.056	1
08357	Anthracene	120-12-7	N.D.	0.011	0.056	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.056	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.056	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.056	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.056	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.056	1
08357	Chrysene	218-01-9	N.D.	0.011	0.056	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.056	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.056	1
08357	Fluorene	86-73-7	N.D.	0.011	0.056	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.056	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.056	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.056	1
08357	Naphthalene	91-20-3	N.D.	0.034	0.056	1
08357	Phenanthrene	85-01-8	N.D.	0.034	0.056	1
08357	Pyrene	129-00-0	N.D.	0.011	0.056	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

<b>Metals</b>	<b>SM 2340 B-1997</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
06256	Total Hardness as CaCO3	471-34-1	0.22	0.033	0.20	1
	<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.00035 J	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-EB-30-081513 Grab Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163669**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013 13:00 by HVA

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15E30 SDG#: PEK68-19EB

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>Metals</b>						
		<b>SW-846 6010B</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
01750	Calcium	7440-70-2	0.0893 J	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	N.D.	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		<b>SW-846 7470A</b>	<b>mg/l</b>	<b>mg/l</b>	<b>mg/l</b>	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 00:04	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 00:04	Brett W Kenyon	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13229WAB026	08/20/2013 14:05	Brian K Graham	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13229WAB026	08/18/2013 18:00	Nicholas W Shroyer	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132356256001	08/23/2013 05:39	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132281848003	08/22/2013 22:09	John P Hook	1
07046	Barium	SW-846 6010B	1	132281848003	08/22/2013 22:09	John P Hook	1
07049	Cadmium	SW-846 6010B	1	132281848003	08/22/2013 22:09	John P Hook	1
01750	Calcium	SW-846 6010B	1	132281848003	08/22/2013 22:09	John P Hook	1
07051	Chromium	SW-846 6010B	1	132281848003	08/22/2013 22:09	John P Hook	1
07055	Lead	SW-846 6010B	1	132281848003	08/22/2013 22:09	John P Hook	1
01757	Magnesium	SW-846 6010B	1	132281848003	08/22/2013 22:09	John P Hook	1
07061	Nickel	SW-846 6010B	1	132281848003	08/22/2013 22:09	John P Hook	1
07036	Selenium	SW-846 6010B	1	132281848003	08/22/2013 22:09	John P Hook	1
07066	Silver	SW-846 6010B	1	132281848003	08/22/2013 22:09	John P Hook	1
07071	Vanadium	SW-846 6010B	1	132281848003	08/22/2013 22:09	John P Hook	1
00259	Mercury	SW-846 7470A	1	132285713005	08/20/2013 09:50	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132281848003	08/18/2013 12:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132285713005	08/19/2013 11:40	Katlin N Cataldi	1

\*=This limit was used in the evaluation of the final result

Sample Description: **WS-TB-124-081513 Water**  
**Mayflower, AR**  
**Pipeline Incident**

LL Sample # **WW 7163670**  
 LL Group # **1412007**  
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 08/15/2013

ExxonMobil c/o Arcadis  
 630 Plaza Drive, Suite 600  
 Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15124 SDG#: PEK68-20TB\*

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
<b>GC/MS</b>	<b>Volatiles</b>	<b>SW-846 8260B 25mL</b>	<b>ug/l</b>	<b>ug/l</b>	<b>ug/l</b>	
	<b>purge</b>					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

\*=This limit was used in the evaluation of the final result

Sample Description: WS-TB-124-081513 Water  
Mayflower, AR  
Pipeline Incident

LL Sample # WW 7163670  
LL Group # 1412007  
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 08/15/2013

ExxonMobil c/o Arcadis  
630 Plaza Drive, Suite 600  
Highlands Ranch CO 80129

Submitted: 08/16/2013 09:40

Reported: 08/23/2013 11:05

15124 SDG#: PEK68-20TB\*

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1

### General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

### Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	C132282AA	08/17/2013 00:26	Brett W Kenyon	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	C132282AA	08/17/2013 00:26	Brett W Kenyon	1

\*=This limit was used in the evaluation of the final result



## Quality Control Summary

Client Name: ExxonMobil c/o Arcadis  
Reported: 08/23/13 at 11:05 AM

Group Number: 1412007

Matrix QC may not be reported if insufficient sample or site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD was performed, unless otherwise specified in the method.

All Inorganic Initial Calibration and Continuing Calibration Blanks met acceptable method criteria unless otherwise noted on the Analysis Report.

### Laboratory Compliance Quality Control

<u>Analysis Name</u>	<u>Blank Result</u>	<u>Blank MDL**</u>	<u>Blank LOQ</u>	<u>Report Units</u>	<u>LCS %REC</u>	<u>LCSD %REC</u>	<u>LCS/LCSD Limits</u>	<u>RPD</u>	<u>RPD Max</u>
Batch number: C132282AA	Sample number(s): 7163651-7163670								
Acetone	N.D.	3.0	5.0	ug/l	99		73-135		
Allyl Chloride	N.D.	0.1	0.5	ug/l	78		61-130		
Benzene	N.D.	0.1	0.5	ug/l	94		80-120		
Bromobenzene	N.D.	0.1	0.5	ug/l	96		80-120		
Bromochloromethane	N.D.	0.1	0.5	ug/l	108		80-125		
Bromodichloromethane	N.D.	0.1	0.5	ug/l	105		80-120		
Bromoform	N.D.	0.1	0.5	ug/l	112		63-132		
Bromomethane	N.D.	0.1	0.5	ug/l	121		38-146		
2-Butanone	N.D.	1.0	5.0	ug/l	89		70-130		
n-Butylbenzene	N.D.	0.1	0.5	ug/l	91		80-120		
sec-Butylbenzene	N.D.	0.1	0.5	ug/l	92		80-120		
tert-Butylbenzene	N.D.	0.1	0.5	ug/l	93		80-120		
Carbon Tetrachloride	N.D.	0.1	0.5	ug/l	113		74-133		
Chlorobenzene	N.D.	0.1	0.5	ug/l	100		80-120		
Chloroethane	N.D.	0.1	0.5	ug/l	119		67-124		
Chloroform	N.D.	0.1	0.5	ug/l	104		80-120		
Chloromethane	N.D.	0.2	0.5	ug/l	76		55-135		
2-Chlorotoluene	N.D.	0.1	0.5	ug/l	94		80-120		
4-Chlorotoluene	N.D.	0.1	0.5	ug/l	96		80-120		
1,2-Dibromo-3-chloropropane	N.D.	0.2	0.5	ug/l	98		57-141		
Dibromochloromethane	N.D.	0.1	0.5	ug/l	107		80-126		
1,2-Dibromoethane	N.D.	0.1	0.5	ug/l	104		80-120		
Dibromomethane	N.D.	0.1	0.5	ug/l	106		80-120		
1,2-Dichlorobenzene	N.D.	0.1	0.5	ug/l	101		80-120		
1,3-Dichlorobenzene	N.D.	0.1	0.5	ug/l	98		80-120		
1,4-Dichlorobenzene	N.D.	0.1	0.5	ug/l	99		80-112		
Dichlorodifluoromethane	N.D.	0.1	0.5	ug/l	57		39-120		
1,1-Dichloroethane	N.D.	0.1	0.5	ug/l	96		80-120		
1,2-Dichloroethane	N.D.	0.1	0.5	ug/l	115		80-127		
1,1-Dichloroethene	N.D.	0.1	0.5	ug/l	95		80-123		
cis-1,2-Dichloroethene	N.D.	0.1	0.5	ug/l	97		80-120		
trans-1,2-Dichloroethene	N.D.	0.1	0.5	ug/l	98		80-120		
Dichlorofluoromethane	N.D.	0.2	0.5	ug/l	133		63-149		
1,2-Dichloropropane	N.D.	0.1	0.5	ug/l	97		80-120		
1,3-Dichloropropane	N.D.	0.1	0.5	ug/l	97		80-120		
2,2-Dichloropropane	N.D.	0.1	0.5	ug/l	104		75-122		
1,1-Dichloropropene	N.D.	0.1	0.5	ug/l	101		80-121		
cis-1,3-Dichloropropene	N.D.	0.1	0.5	ug/l	99		74-120		
trans-1,3-Dichloropropene	N.D.	0.1	0.5	ug/l	100		73-126		
Ethyl ether	N.D.	0.1	0.5	ug/l	93		59-130		
Ethylbenzene	N.D.	0.1	0.5	ug/l	94		80-120		
Freon 113	N.D.	0.2	0.5	ug/l	97		78-132		
Hexachlorobutadiene	N.D.	0.1	0.5	ug/l	96		61-125		

\*- Outside of specification

\*\* - This limit was used in the evaluation of the final result for the blank

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

## Quality Control Summary

Client Name: ExxonMobil c/o Arcadis  
Reported: 08/23/13 at 11:05 AM

Group Number: 1412007

<u>Analysis Name</u>	<u>Blank Result</u>	<u>Blank MDL**</u>	<u>Blank LOQ</u>	<u>Report Units</u>	<u>LCS %REC</u>	<u>LCS D %REC</u>	<u>LCS/LCS D Limits</u>	<u>RPD</u>	<u>RPD Max</u>
Isopropylbenzene	N.D.	0.1	0.5	ug/l	97		80-120		
p-Isopropyltoluene	N.D.	0.1	0.5	ug/l	93		80-120		
Methyl Tertiary Butyl Ether	N.D.	0.1	0.5	ug/l	97		80-125		
4-Methyl-2-Pentanone	N.D.	1.0	5.0	ug/l	99		69-135		
Methylene Chloride	N.D.	0.2	0.5	ug/l	99		80-120		
n-Propylbenzene	N.D.	0.1	0.5	ug/l	90		80-120		
Styrene	N.D.	0.1	0.5	ug/l	100		80-120		
1,1,1,2-Tetrachloroethane	N.D.	0.1	0.5	ug/l	107		80-120		
1,1,2,2-Tetrachloroethane	N.D.	0.1	0.5	ug/l	96		80-125		
Tetrachloroethene	N.D.	0.1	0.5	ug/l	101		80-120		
Tetrahydrofuran	N.D.	2.0	5.0	ug/l	92		65-131		
Toluene	N.D.	0.1	0.5	ug/l	93		80-120		
1,2,3-Trichlorobenzene	N.D.	0.1	0.5	ug/l	93		63-120		
1,2,4-Trichlorobenzene	N.D.	0.1	0.5	ug/l	96		70-120		
1,1,1-Trichloroethane	N.D.	0.1	0.5	ug/l	104		79-127		
1,1,2-Trichloroethane	N.D.	0.1	0.5	ug/l	99		80-120		
Trichloroethene	N.D.	0.1	0.5	ug/l	103		80-120		
Trichlorofluoromethane	N.D.	0.1	0.5	ug/l	129		77-132		
1,2,3-Trichloropropane	N.D.	0.3	1.0	ug/l	103		80-120		
1,2,4-Trimethylbenzene	N.D.	0.1	0.5	ug/l	95		80-120		
1,3,5-Trimethylbenzene	N.D.	0.1	0.5	ug/l	95		80-120		
Vinyl Chloride	N.D.	0.1	0.5	ug/l	95		65-127		
Xylene (Total)	N.D.	0.1	0.5	ug/l	95		80-120		

Batch number: 13229WAB026

Sample number(s): 7163651-7163669

Acenaphthene	N.D.	0.010	0.050	ug/l	109	107	77-118	2	30
Acenaphthylene	N.D.	0.010	0.050	ug/l	125*	118	80-123	6	30
Anthracene	N.D.	0.010	0.050	ug/l	118	113	78-123	4	30
Benzo(a)anthracene	N.D.	0.010	0.050	ug/l	107	98	73-127	9	30
Benzo(a)pyrene	N.D.	0.010	0.050	ug/l	111	105	72-120	5	30
Benzo(b)fluoranthene	N.D.	0.010	0.050	ug/l	98	90	79-136	8	30
Benzo(g,h,i)perylene	N.D.	0.010	0.050	ug/l	104	94	64-130	9	30
Benzo(k)fluoranthene	N.D.	0.010	0.050	ug/l	116	112	73-131	3	30
Chrysene	N.D.	0.010	0.050	ug/l	106	106	76-125	0	30
Dibenz(a,h)anthracene	N.D.	0.010	0.050	ug/l	98	92	58-131	7	30
Fluoranthene	N.D.	0.010	0.050	ug/l	111	105	79-124	6	30
Fluorene	N.D.	0.010	0.050	ug/l	108	96	74-115	12	30
Indeno(1,2,3-cd)pyrene	N.D.	0.010	0.050	ug/l	96	86	62-130	11	30
1-Methylnaphthalene	N.D.	0.010	0.050	ug/l	109	120	80-126	9	30
2-Methylnaphthalene	N.D.	0.010	0.050	ug/l	111	118	81-124	7	30
Naphthalene	N.D.	0.030	0.050	ug/l	107	104	75-120	3	30
Phenanthrene	N.D.	0.030	0.050	ug/l	104	100	75-120	4	30
Pyrene	N.D.	0.010	0.050	ug/l	109	101	71-130	7	30

Batch number: 132281848003

Sample number(s): 7163651-7163669

Arsenic	N.D.	0.0068	0.0200	mg/l	101		90-113		
Barium	N.D.	0.00033	0.0050	mg/l	103		90-110		
Cadmium	N.D.	0.00076	0.0050	mg/l	102		90-112		
Calcium	N.D.	0.0334	0.200	mg/l	101		90-110		
Chromium	N.D.	0.0016	0.0150	mg/l	101		90-110		
Lead	N.D.	0.0047	0.0150	mg/l	107		88-110		
Magnesium	N.D.	0.0167	0.100	mg/l	100		90-110		
Nickel	N.D.	0.0015	0.0100	mg/l	105		90-111		
Selenium	N.D.	0.0084	0.0200	mg/l	104		80-120		
Silver	N.D.	0.0021	0.0050	mg/l	98		80-120		
Vanadium	N.D.	0.0020	0.0050	mg/l	101		90-110		

\*- Outside of specification

\*\* - This limit was used in the evaluation of the final result for the blank

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

## Quality Control Summary

Client Name: ExxonMobil c/o Arcadis  
Reported: 08/23/13 at 11:05 AM

Group Number: 1412007

<u>Analysis Name</u>	<u>Blank Result</u>	<u>Blank MDL**</u>	<u>Blank LOQ</u>	<u>Report Units</u>	<u>LCS %REC</u>	<u>LCS %REC</u>	<u>LCS/LCSD Limits</u>	<u>RPD</u>	<u>RPD Max</u>
Batch number: 132285713005 Mercury	Sample number(s): 7163651-7163669 N.D.	0.00006	0.00020	mg/l	101		80-120		
Batch number: 13234807902A HEM (oil & grease)	Sample number(s): 7163651-7163668 N.D.	1.4	5.0	mg/l	110	98	78-114	12	16

## Sample Matrix Quality Control

Unspiked (UNSPK) = the sample used in conjunction with the matrix spike  
Background (BKG) = the sample used in conjunction with the duplicate

<u>Analysis Name</u>	<u>MS %REC</u>	<u>MSD %REC</u>	<u>MS/MSD Limits</u>	<u>RPD</u>	<u>RPD MAX</u>	<u>BKG Conc</u>	<u>DUP Conc</u>	<u>DUP RPD</u>	<u>Dup RPD Max</u>
Batch number: C132282AA	Sample number(s): 7163651-7163670 UNSPK: 7163651								
Acetone	103	96	57-163	7	30				
Allyl Chloride	83	89	56-160	6	30				
Benzene	102	104	87-126	2	30				
Bromobenzene	102	105	80-123	3	30				
Bromochloromethane	111	115	82-125	3	30				
Bromodichloromethane	113	114	82-133	0	30				
Bromoform	121	118	60-138	3	30				
Bromomethane	135*	118	66-130	13	30				
2-Butanone	82	81	56-160	1	30				
n-Butylbenzene	106	105	83-131	0	30				
sec-Butylbenzene	105	106	84-128	1	30				
tert-Butylbenzene	104	106	84-135	2	30				
Carbon Tetrachloride	131	131	81-148	0	30				
Chlorobenzene	110	110	78-133	0	30				
Chloroethane	137	118	70-139	14	30				
Chloroform	113	114	86-136	0	30				
Chloromethane	89	89	49-135	0	30				
2-Chlorotoluene	104	105	75-134	2	30				
4-Chlorotoluene	106	107	76-134	1	30				
1,2-Dibromo-3-chloropropane	102	96	43-143	6	30				
Dibromochloromethane	113	115	79-125	1	30				
1,2-Dibromoethane	108	109	84-127	1	30				
Dibromomethane	114	114	83-126	0	30				
1,2-Dichlorobenzene	111	111	83-117	0	30				
1,3-Dichlorobenzene	107	109	79-132	2	30				
1,4-Dichlorobenzene	107	107	79-120	1	30				
Dichlorodifluoromethane	68	68	28-136	0	30				
1,1-Dichloroethane	104	106	88-136	2	30				
1,2-Dichloroethane	124	122	82-135	1	30				
1,1-Dichloroethene	116	109	83-150	7	30				
cis-1,2-Dichloroethene	105	107	82-129	1	30				
trans-1,2-Dichloroethene	109	111	88-127	2	30				
Dichlorofluoromethane	155	132	81-161	16	30				
1,2-Dichloropropane	104	107	91-126	3	30				
1,3-Dichloropropane	103	105	80-127	1	30				
2,2-Dichloropropane	120	119	80-134	1	30				
1,1-Dichloropropene	115	116	86-139	1	30				

\*- Outside of specification

\*\* - This limit was used in the evaluation of the final result for the blank

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

## Quality Control Summary

Client Name: ExxonMobil c/o Arcadis  
Reported: 08/23/13 at 11:05 AM

Group Number: 1412007

### Sample Matrix Quality Control

Unspiked (UNSPK) = the sample used in conjunction with the matrix spike  
Background (BKG) = the sample used in conjunction with the duplicate

<u>Analysis Name</u>	<u>MS</u> <u>%REC</u>	<u>MSD</u> <u>%REC</u>	<u>MS/MSD</u> <u>Limits</u>	<u>RPD</u>	<u>RPD</u> <u>MAX</u>	<u>BKG</u> <u>Conc</u>	<u>DUP</u> <u>Conc</u>	<u>DUP</u> <u>RPD</u>	<u>Dup RPD</u> <u>Max</u>
cis-1,3-Dichloropropene	105	109	74-132	4	30				
trans-1,3-Dichloropropene	107	109	71-128	2	30				
Ethyl ether	136	138	57-139	1	30				
Ethylbenzene	106	106	80-140	0	30				
Freon 113	120	111	77-147	8	30				
Hexachlorobutadiene	130*	119	65-128	8	30				
Isopropylbenzene	110	109	81-133	1	30				
p-Isopropyltoluene	105	107	84-124	1	30				
Methyl Tertiary Butyl Ether	100	104	82-132	4	30				
4-Methyl-2-Pentanone	102	106	69-149	3	30				
Methylene Chloride	105	110	77-135	5	30				
n-Propylbenzene	102	102	79-131	1	30				
Styrene	108	108	63-151	0	30				
1,1,1,2-Tetrachloroethane	115	115	87-126	0	30				
1,1,2,2-Tetrachloroethane	102	104	75-131	1	30				
Tetrachloroethene	115	115	75-129	0	30				
Tetrahydrofuran	84	82	56-154	3	30				
Toluene	103	104	83-127	0	30				
1,2,3-Trichlorobenzene	120	114	73-125	5	30				
1,2,4-Trichlorobenzene	120	114	77-120	5	30				
1,1,1-Trichloroethane	120	121	85-140	1	30				
1,1,2-Trichloroethane	107	108	85-129	1	30				
Trichloroethene	116	117	85-131	1	30				
Trichlorofluoromethane	159*	137	73-139	15	30				
1,2,3-Trichloropropane	108	111	76-120	2	30				
1,2,4-Trimethylbenzene	105	106	87-126	1	30				
1,3,5-Trimethylbenzene	105	106	89-129	1	30				
Vinyl Chloride	104	104	62-135	0	30				
Xylene (Total)	106	106	81-137	1	30				

Batch number: 132281848003	Sample number(s): 7163651-7163669	UNSPK: 7163657	BKG: 7163657						
Arsenic	103	107	81-123	4	20	N.D.	N.D.	0 (1)	20
Barium	101	101	78-118	0	20	0.0381	0.0377	1	20
Cadmium	101	106	83-116	4	20	N.D.	N.D.	0 (1)	20
Calcium	97	93	81-118	2	20	5.66	5.66	0	20
Chromium	100	101	81-120	0	20	N.D.	N.D.	0 (1)	20
Lead	105	110	75-125	4	20	N.D.	N.D.	0 (1)	20
Magnesium	97	92	75-125	2	20	2.61	2.61	0	20
Nickel	104	109	86-115	4	20	N.D.	N.D.	0 (1)	20
Selenium	103	105	75-125	2	20	N.D.	N.D.	0 (1)	20
Silver	96	96	75-125	0	20	N.D.	N.D.	0 (1)	20
Vanadium	102	101	90-111	0	20	N.D.	N.D.	0 (1)	20

Batch number: 132285713005	Sample number(s): 7163651-7163669	UNSPK: 7163651	BKG: 7163651						
Mercury	111	100	80-120	10	20	N.D.	N.D.	0 (1)	20

Batch number: 13234807902A	Sample number(s): 7163651-7163668	UNSPK: 7163666							
HEM (oil & grease)	90		78-114						

\*- Outside of specification

\*\* - This limit was used in the evaluation of the final result for the blank

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

## Quality Control Summary

Client Name: ExxonMobil c/o Arcadis  
Reported: 08/23/13 at 11:05 AM

Group Number: 1412007

### Surrogate Quality Control

Surrogate recoveries which are outside of the QC window are confirmed unless attributed to dilution or otherwise noted on the Analysis Report.

Analysis Name: BTEX 25-ml purge

Batch number: C132282AA

	Dibromofluoromethane	1,2-Dichloroethane-d4	Toluene-d8	4-Bromofluorobenzene
7163651	110	105	96	100
7163652	110	105	97	100
7163653	111	102	96	98
7163654	111	106	97	99
7163655	112	106	96	99
7163656	111	106	97	99
7163657	112	106	96	99
7163658	111	106	97	98
7163659	111	105	95	99
7163660	112	107	96	98
7163661	111	104	96	98
7163662	112	104	96	99
7163663	111	104	96	98
7163664	111	104	96	98
7163665	111	105	96	99
7163666	114	113	95	99
7163667	111	105	95	97
7163668	111	102	97	98
7163669	110	105	96	99
7163670	110	105	95	99
Blank	109	105	97	100
LCS	106	106	98	103
MS	107	103	98	105
MSD	106	104	98	103
Limits:	77-114	74-113	77-110	78-110

Analysis Name: PAHs in waters by SIM

Batch number: 13229WAB026

	Fluoranthene-d10	Benzo(a)pyrene-d12	1-Methylnaphthalene-d10
7163651	99	76	110
7163652	92	70	109
7163653	105	79	114
7163654	100	75	107
7163655	93	72	109
7163656	92	80	112
7163657	95	81	114
7163658	100	79	108
7163659	99	83	106
7163660	104	75	107
7163661	96	64	110
7163662	97	69	114
7163663	97	56*	103
7163664	72	58*	105
7163665	100	68	104
7163666	87	78	101
7163667	88	81	107

\*- Outside of specification

\*\* - This limit was used in the evaluation of the final result for the blank

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

## Quality Control Summary

Client Name: ExxonMobil c/o Arcadis  
Reported: 08/23/13 at 11:05 AM

Group Number: 1412007

### Surrogate Quality Control

7163668	92	68	103
7163669	97	93	109
Blank	82	78	85
LCS	107	111	109
LCSD	95	102	113
<hr/>			
Limits:	44-137	62-141	51-136

\*- Outside of specification

\*\* - This limit was used in the evaluation of the final result for the blank

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

# ExxonMobil Analysis Request/Chain of Custody



Lancaster Laboratories Environmental

Acct. # 14739 For Eurofins Lancaster Laboratories Environmental use only  
 Group # 1412007 Sample # 7163651-70  
Instructions on reverse side correspond with circled numbers.

1082

1 Client Information				4 Matrix				5 Analyses Requested												6 Remarks	
Facility #/SID <u>Mayflower Pipeline Incident</u>				Sediment <input type="checkbox"/> Potable <input type="checkbox"/> NPDES <input type="checkbox"/> Oil <input type="checkbox"/>	Ground <input type="checkbox"/> Surface <input checked="" type="checkbox"/>	Air <input type="checkbox"/>	Preservation Code												SCR#: _____		
Site Address <u>Mayflower, AR</u>							H H H N N N S S S												Preservation Codes H = HCl      T = Thiosulfate N = HNO <sub>3</sub> B = NaOH S = H <sub>2</sub> SO <sub>4</sub> O = Other		
ExxonMobil PM <u>Scott Bushroe</u>							Total # of Containers <u>VOCS 8260 B</u> <u>PAHS 8270 SIM</u> <u>PCRA Metals + Ni, V, Cr, Pb</u> <u>Diss Metals</u> <u>HEM Oil &amp; Grease</u>												6 Remarks <u>Lab to filter &amp; preserve diss metals upon receipt.</u>		
Consultant/Office <u>Arcadis</u>																					
Consultant PM <u>Steve Barrick</u>																					
Consultant Phone # <u>919-202-6799</u>																					
Sampler <u>Hu Van Allen/M. Long</u>																					
2 Sample Identification		3 Composite																			
		Collected																			
		Date	Time	Grab	Soil	Water	Oil														
WS-014(1.5-2.0)081513		8/15/13	820	X		X		9	X	X	X	X	X								
WS-014(5.5-6.0)081513			830	X		X		9	X	X	X	X	X								
WS-012(1.5-2.0)081513			840	X		X		9	X	X	X	X	X								
WS-012(5.0-5.5)081513			850	X		X		9	X	X	X	X	X								
WS-010(1.5-2.0)081513			910	X		X		9	X	X	X	X	X								
WS-010(3.5-4.0)081513			920	X		X		9	X	X	X	X	X								
WS-006(0.5-1.0)081513			930	X		X		9	X	X	X	X	X								
WS-005(Surface)081513			1000	X		X		9	X	X	X	X	X								
WS-002(Surface)081513			1020	X		X		9	X	X	X	X	X								
WS-018(Surface)081513			1040	X		X		9	X	X	X	X	X								
WS-011(1.5-2.0)081513			1110	X		X		9	X	X	X	X	X								
WS-011(5.0-5.5)081513			1120	X		X		9	X	X	X	X	X								
7 Turnaround Time Requested (TAT) (please circle)				Relinquished by <u>Hu Van Allen</u>				Date <u>8/15/13</u>		Time <u>1700</u>		Received by		Date		Time					
Standard <u>3</u> day      4 day				Relinquished by				Date		Time		Received by		Date		Time					
72 hour      48 hour      24 hour				Relinquished by				Date		Time		Received by		Date		Time					
8 Data Package (circle if required)				Relinquished by Commercial Carrier				Date		Time		Received by		Date		Time					
Type I - Full				UPS <input checked="" type="checkbox"/> FedEx _____      Other _____								<u>CE</u>		<u>8/16/13</u>		<u>0940</u>					
Type VI (Raw Data)				Temperature Upon Receipt <u>0.4-2.3</u> °C								Custody Seals Intact?		<u>Yes</u> No							
NJ Reduced																					
Other _____																					

Eurofins Lancaster Laboratories Environmental, LLC • 2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300

The white copy should accompany samples to Eurofins Lancaster Laboratories Environmental. The yellow copy should be retained by the client.

# ExxonMobil Analysis Request/Chain of Custody



Lancaster Laboratories  
Environmental

Acct. # 14739 For Eurofins Lancaster Laboratories Environmental use only  
Group # 1412007 Sample # 7163651-70  
Instructions on reverse side correspond with circled numbers.

2 of 2

1 Client Information				4 Matrix				5 Analyses Requested										6 Remarks																																			
Facility #/SID <u>Mayflower Pipeline Incident</u>				Sediment <input type="checkbox"/> Potable <input type="checkbox"/> NPDES <input type="checkbox"/> Soil <input type="checkbox"/>	Ground <input type="checkbox"/> Surface <input checked="" type="checkbox"/>	Air <input type="checkbox"/>	Preservation Code										SCR#: _____ Preservation Codes H = HCl      T = Thiosulfate N = HNO <sub>3</sub> B = NaOH S = H <sub>2</sub> SO <sub>4</sub> O = Other																																				
Site Address <u>Mayflower, AR</u>							Total # of Containers	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <th style="width: 5%;">H</th> <th style="width: 5%;">N</th> <th style="width: 5%;">H</th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>											H	N	H																																
H	N	H																																																			
ExxonMobil PM <u>Scott Bushroe</u>				Water <input type="checkbox"/>	Oil <input type="checkbox"/>	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 5%;"> </td> <td style="width: 5%;"> </td> <td style="width: 5%;"> </td> <td style="width: 5%;"> </td> <td style="width: 5%;"> </td> <td style="width: 5%;"> </td> <td style="width: 5%;"> </td> <td style="width: 5%;"> </td> <td style="width: 5%;"> </td> <td style="width: 5%;"> </td> <td style="width: 5%;"> </td> <td style="width: 5%;"> </td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </table>																																															
Consultant/Office <u>Arcadis</u>				VOCs B260 B PAHs B270 SIM PCRAMetals + Ni, V, Cr, Mg Diss Metals HEM Oil & Grease																																																	
Consultant PM <u>Steve Barrick</u>				Cost Center/AFE _____																																																	
Consultant Phone # <u>919 202 6799</u>				Hardness																																																	
Sampler <u>M. Van Aller / M. Long</u>				Diss Metals																																																	
2 Sample Identification				Collected		Grab <input type="checkbox"/> Composite <input type="checkbox"/>	Total # of Containers																																														
				Date	Time																																																
WS-003 (surface) 081513				8/15/13	1130	X	X	9	X	X	X	X	X	X	X	X	X																																				
WS-007 (0.5-1.0) 081513				↓	1140	X	X	9	X	X	X	X	X	X	X	X	X																																				
WS-001 (0.5-1.0) 081513				↓	1150	Y	X	9	X	X	X	X	X	X	X	X	X																																				
WS-13KG-002 (surface) 081513				↓	1210	X	X	9	X	X	X	X	X	X	X	X	X																																				
WS-008 (surface) 081513				↓	1220	Y	X	9	X	X	X	X	X	X	X	X	X																																				
DUP-WS-71-081513				↓	—	X	X	9	X	X	X	X	X	X	X	X	X																																				
WS-EB-30-081513				↓	1300	X	X	7	X	X	X	X	X	X	X	X	X																																				
WS-TB-124-081513				↓	—	X	X	2	X																																												

7 Turnaround Time Requested (TAT) (please circle) Standard <u>5 day</u> 4 day 72 hour      48 hour      24 hour			Relinquished by <u>M. Van Aller</u>		Date	Time	Received by	Date	Time
			Relinquished by _____		Date	Time	Received by	Date	Time
			Relinquished by _____		Date	Time	Received by	Date	Time

8 Data Package (circle if required) Type I - Full Type VI (Raw Data) NJ Reduced Other _____		EDD (circle if required) Locus EIM (default) Other _____		Relinquished by Commercial Carrier UPS <input checked="" type="checkbox"/> FedEx _____      Other _____			Received by	Date	Time
				Temperature Upon Receipt <u>0.4-2.3 °C</u>			Received by <u>Cash</u>	<u>8/16/13</u>	<u>0940</u>
Custody Seals Intact? <u>(Yes)</u> No									



Environmental Sample Administration  
Receipt Documentation Log

1412007

Client/Project: Mayflower Waters  
Date of Receipt: 8/16/13  
Time of Receipt: 0940  
Source Code: 60-1

Shipping Container Sealed: YES NO  
Custody Seal Present \* : YES NO  
\* Custody seal was intact unless otherwise noted in the discrepancy section  
Package: Chilled Not Chilled

Temperature of Shipping Containers

Cooler #	Thermometer ID	Temperature (°C)	Temp Bottle (TB) or Surface Temp (ST)	Wet Ice (WI) or Dry Ice (DI) or Ice Packs (IP)	Ice Present? Y/N	Loose (L) Bagged Ice (B) or NA	Comments
1	DT121	0.9	TB	WI	Y	B	
2	↓	0.4	↓	↓	↓	↓	
3	↓	2.3	↓	↓	↓	↓	
4	↓	0.7	↓	↓	↓	↓	
5	↓	0.6	↓	↓	↓	↓	
6	↓	0.4	↓	↓	↓	↓	

Number of Trip Blanks received NOT listed on chain of custody: 0

Paperwork Discrepancy/Unpacking Problems:

WS-007 @ 1140 - received 1 broken pb jar  
WS-008 (surface) @ 1220 - received 1 broken pb jar

Unpacker Signature/Emp#: Cashler 3647 Date/Time: 8/16/13 1025

Environmental Sample Administration  
Receipt Documentation Log

1412007

Client/Project: Mayflower Waters  
 Date of Receipt: 8/16/13  
 Time of Receipt: 0940  
 Source Code: 60-1

Shipping Container Sealed: YES NO  
 Custody Seal Present \* : YES NO  
 \* Custody seal was intact unless otherwise noted in the discrepancy section  
 Package: Chilled Not Chilled

Temperature of Shipping Containers							
Cooler #	Thermometer ID	Temperature (°C)	Temp Bottle (TB) or Surface Temp (ST)	Wet Ice (WI) or Dry Ice (DI) or Ice Packs (IP)	Ice Present? Y/N	Loose (L) Bagged Ice (B) or NA	Comments
1	DT121	0.4	TB	WI	Y	B	
2							
3							
4							
5							
6							

Number of Trip Blanks received NOT listed on chain of custody: 0

Paperwork Discrepancy/Unpacking Problems:

---



---



---



---

Unpacker Signature/Emp#: [Signature] 3647 Date/Time: 8/16/13 1025

# Explanation of Symbols and Abbreviations

The following defines common symbols and abbreviations used in reporting technical data:

<b>RL</b>	Reporting Limit	<b>BMQL</b>	Below Minimum Quantitation Level
<b>N.D.</b>	none detected	<b>MPN</b>	Most Probable Number
<b>TNTC</b>	Too Numerous To Count	<b>CP Units</b>	cobalt-chloroplatinate units
<b>IU</b>	International Units	<b>NTU</b>	nephelometric turbidity units
<b>umhos/cm</b>	micromhos/cm	<b>ng</b>	nanogram(s)
<b>C</b>	degrees Celsius	<b>F</b>	degrees Fahrenheit
<b>meq</b>	milliequivalents	<b>lb.</b>	pound(s)
<b>g</b>	gram(s)	<b>kg</b>	kilogram(s)
<b>µg</b>	microgram(s)	<b>mg</b>	milligram(s)
<b>mL</b>	milliliter(s)	<b>L</b>	liter(s)
<b>m<sup>3</sup></b>	cubic meter(s)	<b>µL</b>	microliter(s)
		<b>pg/L</b>	picogram/liter

< less than - The number following the sign is the limit of quantitation, the smallest amount of analyte which can be reliably determined using this specific test.

> greater than

**ppm** parts per million - One ppm is equivalent to one milligram per kilogram (mg/kg), or one gram per million grams. For aqueous liquids, ppm is usually taken to be equivalent to milligrams per liter (mg/l), because one liter of water has a weight very close to a kilogram. For gases or vapors, one ppm is equivalent to one microliter per liter of gas.

**ppb** parts per billion

**Dry weight basis** Results printed under this heading have been adjusted for moisture content. This increases the analyte weight concentration to approximate the value present in a similar sample without moisture. All other results are reported on an as-received basis.

*Data Qualifiers:*

**C** – result confirmed by reanalysis.

**J** - estimated value – The result is  $\geq$  the Method Detection Limit (MDL) and  $<$  the Limit of Quantitation (LOQ).

*U.S. EPA CLP Data Qualifiers:*

**Organic Qualifiers**

- A** TIC is a possible aldol-condensation product
- B** Analyte was also detected in the blank
- C** Pesticide result confirmed by GC/MS
- D** Compound quantitated on a diluted sample
- E** Concentration exceeds the calibration range of the instrument
- N** Presumptive evidence of a compound (TICs only)
- P** Concentration difference between primary and confirmation columns  $>25\%$
- U** Compound was not detected
- X,Y,Z** Defined in case narrative

**Inorganic Qualifiers**

- B** Value is  $<$ CRDL, but  $\geq$ IDL
- E** Estimated due to interference
- M** Duplicate injection precision not met
- N** Spike sample not within control limits
- S** Method of standard additions (MSA) used for calculation
- U** Compound was not detected
- W** Post digestion spike out of control limits
- \*** Duplicate analysis not within control limits
- +** Correlation coefficient for MSA  $<0.995$

**Analytical test results meet all requirements of NELAC unless otherwise noted under the individual analysis.**

Measurement uncertainty values, as applicable, are available upon request.

Tests results relate only to the sample tested. Clients should be aware that a critical step in a chemical or microbiological analysis is the collection of the sample. Unless the sample analyzed is truly representative of the bulk of material involved, the test results will be meaningless. If you have questions regarding the proper techniques of collecting samples, please contact us. We cannot be held responsible for sample integrity, however, unless sampling has been performed by a member of our staff. This report shall not be reproduced except in full, without the written approval of the laboratory.

Times are local to the area of activity. Parameters listed in the 40 CFR part 136 Table II as “analyze immediately” are not performed within 15 minutes.

**WARRANTY AND LIMITS OF LIABILITY** - In accepting analytical work, we warrant the accuracy of test results for the sample as submitted. THE FOREGOING EXPRESS WARRANTY IS EXCLUSIVE AND IS GIVEN IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED. WE DISCLAIM ANY OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING A WARRANTY OF FITNESS FOR PARTICULAR PURPOSE AND WARRANTY OF MERCHANTABILITY. IN NO EVENT SHALL EUROFINS LANCASTER LABORATORIES ENVIRONMENTAL, LLC BE LIABLE FOR INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES INCLUDING, BUT NOT LIMITED TO, DAMAGES FOR LOSS OF PROFIT OR GOODWILL REGARDLESS OF (A) THE NEGLIGENCE (EITHER SOLE OR CONCURRENT) OF EUROFINS LANCASTER LABORATORIES ENVIRONMENTAL AND (B) WHETHER EUROFINS LANCASTER LABORATORIES ENVIRONMENTAL HAS BEEN INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. We accept no legal responsibility for the purposes for which the client uses the test results. No purchase order or other order for work shall be accepted by Eurofins Lancaster Laboratories Environmental which includes any conditions that vary from the Standard Terms and Conditions, and Eurofins Lancaster Laboratories Environmental hereby objects to any conflicting terms contained in any acceptance or order submitted by client.