

ANALYTICAL RESULTS

Prepared by:

Eurofins Lancaster Laboratories Environmental
2425 New Holland Pike
Lancaster, PA 17601

Prepared for:

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

October 10, 2013

Project: Mayflower, AR Pipeline Incident

Submittal Date: 10/03/2013
Group Number: 1423470
SDG: PEL88
PO Number: B0086003.1301
State of Sample Origin: AR

<u>Client Sample Description</u>	<u>Lancaster Labs (LL) #</u>
WS-014(1.5-2.0)100213 Grab Surface Water	7222553
WS-014(5.5-6.0)100213 Grab Surface Water	7222554
WS-012(1.5-2.0)100213 Grab Surface Water	7222555
WS-012(5.0-5.5)100213 Grab Surface Water	7222556
WS-010(1.5-2.0)100213 Grab Surface Water	7222557
WS-010(3.5-4.0)100213 Grab Surface Water	7222558
WS-006(0.5-1.0)100213 Grab Surface Water	7222559
WS-005(Surface)100213 Grab Surface Water	7222560
WS-011(1.5-2.0)100213 Grab Surface Water	7222561
WS-011(5.0-5.5)100213 Grab Surface Water	7222562
WS-002(Surface)100213 Grab Surface Water	7222563
WS-018(Surface)100213 Grab Surface Water	7222564
WS-003(Surface)100213 Grab Surface Water	7222565
WS-007(0.5-1.0)100213 Grab Surface Water	7222566
WS-001(0.5-1.0)100213 Grab Surface Water	7222567
DUP-WS-96-100213 Grab Surface Water	7222568
WS-EB-79-100213 Grab Water	7222569
WS-TB-166-100213 Water	7222570

The specific methodologies used in obtaining the enclosed analytical results are indicated on the Laboratory Sample Analysis Record.

ELECTRONIC COPY TO	ARCADIS	Attn: Stephen Barrick
ELECTRONIC COPY TO	ARCADIS	Attn: Lyndi Mott
ELECTRONIC COPY TO	ExxonMobil	Attn: Michael J. Firth

ELECTRONIC COPY TO	ARCADIS	Attn: Emily Leamer
ELECTRONIC COPY TO	ARCADIS	Attn: Rhiannon Parmalee
ELECTRONIC COPY TO	ARCADIS	Attn: Jamie Pritchard
ELECTRONIC COPY TO	ExxonMobil	Attn: Michael L Sixsmith
ELECTRONIC COPY TO	ExxonMobil	Attn: Julie Foster

Respectfully Submitted,



Katherine A. Klinefelter
Principal Specialist

(717) 556-7256

Project Name: Mayflower, AR Pipeline Incident
LLI Group #: 1423470

General Comments:

See the Laboratory Sample Analysis Record section of the Analysis Report for the method references.

All QC met criteria unless otherwise noted in an Analysis Specific Comment below. Refer to the QC Summary for specific values and acceptance criteria.

Project specific QC samples are not included in this data set

Matrix QC may not be reported if site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD was performed, unless otherwise specified in the method.

Surrogate recoveries (if applicable) which are outside of the QC window are confirmed unless attributed to a dilution or otherwise noted in an Analysis Specific Comment below.

The samples were received at the appropriate temperature and in accordance with the chain of custody unless otherwise noted.

Analysis Specific Comments:**SW-846 8260B 25mL purge, GC/MS Volatiles**

Batch #: H132771AA (Sample number(s): 7222553-7222570 UNSPK: 7222553)

The recovery(ies) for the following analyte(s) in the MS and/or MSD was outside the acceptance window: 1,2-Dichloropropane, 1,3,5-Trimethylbenzene, 1,2,4-Trimethylbenzene

SW-846 8270C SIM, GC/MS Semivolatiles

Batch #: 13277WAA026 (Sample number(s): 7222553-7222569)

The recovery(ies) for one or more surrogates were outside of the QC window for sample(s) 7222557, 7222560, 7222561, 7222562, 7222563, 7222565, 7222567, 7222568

Sample #s: 7222553, 7222554, 7222555, 7222556, 7222558, 7222559, 7222564, 7222566, 7222569

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

Sample #s: 7222557, 7222560, 7222561, 7222562, 7222563, 7222565, 7222567, 7222568

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis. The recovery for the sample surrogate(s) is outside the QC acceptance limits as noted on the QC Summary. The client was contacted and the data reported.

SW-846 6010B, Metals

Batch #: 132761848001 (Sample number(s): 7222553-7222569 UNSPK: 7222563 BKG: 7222563)

The duplicate RPD for the following analyte(s) exceeded the acceptance window: Nickel

EPA 1664A, Wet Chemistry

Batch #: 13283807901A (Sample number(s): 7222553-7222568 UNSPK: 7222553)

The recovery(ies) for the following analyte(s) in the MS was outside the acceptance window: HEM (oil & grease)

Sample Description: WS-014(1.5-2.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222553
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 08:50 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2141 SDG#: PEL88-01

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-014(1.5-2.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222553**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 08:50 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2141 SDG#: PEL88-01

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.055	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.055	1
08357	Anthracene	120-12-7	N.D.	0.011	0.055	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.055	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.055	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.055	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.055	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.055	1
08357	Chrysene	218-01-9	N.D.	0.011	0.055	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.055	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.055	1
08357	Fluorene	86-73-7	N.D.	0.011	0.055	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.055	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.055	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.055	1
08357	Naphthalene	91-20-3	N.D.	0.033	0.055	1
08357	Phenanthrene	85-01-8	N.D.	0.033	0.055	1
08357	Pyrene	129-00-0	N.D.	0.011	0.055	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	28.9	0.033	0.20	1
	SW-846 6010B	mg/l	mg/l	mg/l		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0508	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-014(1.5-2.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222553
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 08:50 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2141 SDG#: PEL88-01

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
	SW-846 6010B		mg/l	mg/l	mg/l	
01750	Calcium	7440-70-2	6.54	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.06	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	SW-846 7470A		mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
	EPA 1664A		mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 11:26	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 11:26	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 02:28	Catherine E Bachman	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/08/2013 23:19	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/08/2013 23:19	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/08/2013 23:19	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/08/2013 23:19	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/08/2013 23:19	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/08/2013 23:19	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/08/2013 23:19	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/08/2013 23:19	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/08/2013 23:19	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/08/2013 23:19	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/08/2013 23:19	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 09:22	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300 • Fax: 717-656-2681 • www.LancasterLabs.com

Sample Description: WS-014(1.5-2.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222553
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 08:50 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2141 SDG#: PEL88-01

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-014(5.5-6.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222554**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 09:00 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2142 SDG#: PEL88-02

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-014(5.5-6.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222554
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 09:00 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2142 SDG#: PEL88-02

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.057	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.057	1
08357	Anthracene	120-12-7	N.D.	0.011	0.057	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.057	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.057	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.057	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.057	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.057	1
08357	Chrysene	218-01-9	N.D.	0.011	0.057	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.057	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.057	1
08357	Fluorene	86-73-7	N.D.	0.011	0.057	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.057	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.057	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.057	1
08357	Naphthalene	91-20-3	N.D.	0.034	0.057	1
08357	Phenanthrene	85-01-8	N.D.	0.034	0.057	1
08357	Pyrene	129-00-0	N.D.	0.011	0.057	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	29.9	0.033	0.20	1
	SW-846 6010B	mg/l	mg/l	mg/l		
07035	Arsenic	7440-38-2	0.0083 J	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0532	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-014(5.5-6.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222554
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 09:00 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2142 SDG#: PEL88-02

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
	SW-846 6010B		mg/l	mg/l	mg/l	
01750	Calcium	7440-70-2	6.76	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.15	0.0167	0.100	1
07061	Nickel	7440-02-0	0.0021 J	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	SW-846 7470A		mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
	EPA 1664A		mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 11:47	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 11:47	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 02:57	Catherine E Bachman	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/08/2013 23:23	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/08/2013 23:23	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/08/2013 23:23	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/08/2013 23:23	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/08/2013 23:23	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/08/2013 23:23	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/08/2013 23:23	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/08/2013 23:23	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/08/2013 23:23	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/08/2013 23:23	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/08/2013 23:23	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 09:24	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-014(5.5-6.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222554
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 09:00 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2142 SDG#: PEL88-02

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-012(1.5-2.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222555
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 09:20 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2121 SDG#: PEL88-03

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-012(1.5-2.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222555**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 09:20 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2121 SDG#: PEL88-03

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.054	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.054	1
08357	Anthracene	120-12-7	N.D.	0.011	0.054	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.054	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.054	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.054	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.054	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.054	1
08357	Chrysene	218-01-9	N.D.	0.011	0.054	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.054	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.054	1
08357	Fluorene	86-73-7	N.D.	0.011	0.054	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.054	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.054	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.054	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.054	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.054	1
08357	Pyrene	129-00-0	N.D.	0.011	0.054	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	29.3	0.033	0.20	1
	SW-846 6010B	mg/l	mg/l	mg/l		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0371	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-012(1.5-2.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222555**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 09:20 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2121 SDG#: PEL88-03

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
	SW-846 6010B		mg/l	mg/l	mg/l	
01750	Calcium	7440-70-2	6.61	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.10	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	SW-846 7470A		mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
	EPA 1664A		mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 12:08	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 12:08	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 03:26	Catherine E Bachman	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/08/2013 23:35	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/08/2013 23:35	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/08/2013 23:35	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/08/2013 23:35	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/08/2013 23:35	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/08/2013 23:35	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/08/2013 23:35	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/08/2013 23:35	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/08/2013 23:35	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/08/2013 23:35	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/08/2013 23:35	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 09:30	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-012(1.5-2.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222555
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 09:20 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2121 SDG#: PEL88-03

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-012(5.0-5.5)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222556**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 09:30 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2122 SDG#: PEL88-04

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-012(5.0-5.5)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222556**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 09:30 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2122 SDG#: PEL88-04

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.012	0.058	1
08357	Acenaphthylene	208-96-8	N.D.	0.012	0.058	1
08357	Anthracene	120-12-7	N.D.	0.012	0.058	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.012	0.058	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.012	0.058	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.012	0.058	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.012	0.058	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.012	0.058	1
08357	Chrysene	218-01-9	N.D.	0.012	0.058	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.012	0.058	1
08357	Fluoranthene	206-44-0	N.D.	0.012	0.058	1
08357	Fluorene	86-73-7	N.D.	0.012	0.058	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.012	0.058	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.012	0.058	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.012	0.058	1
08357	Naphthalene	91-20-3	N.D.	0.035	0.058	1
08357	Phenanthrene	85-01-8	N.D.	0.035	0.058	1
08357	Pyrene	129-00-0	N.D.	0.012	0.058	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	29.5	0.033	0.20	1
	SW-846 6010B	mg/l	mg/l	mg/l		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0428	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-012(5.0-5.5)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222556
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 09:30 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2122 SDG#: PEL88-04

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
	SW-846 6010B		mg/l	mg/l	mg/l	
01750	Calcium	7440-70-2	6.67	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.12	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	SW-846 7470A		mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
	EPA 1664A		mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	2.3 J	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 12:29	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 12:29	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 03:55	Catherine E Bachman	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/08/2013 23:39	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/08/2013 23:39	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/08/2013 23:39	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/08/2013 23:39	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/08/2013 23:39	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/08/2013 23:39	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/08/2013 23:39	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/08/2013 23:39	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/08/2013 23:39	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/08/2013 23:39	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/08/2013 23:39	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 09:32	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-012(5.0-5.5)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222556
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 09:30 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2122 SDG#: PEL88-04

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-010(1.5-2.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222557**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 09:50 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2101 SDG#: PEL88-05

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-010(1.5-2.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222557**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 09:50 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2101 SDG#: PEL88-05

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.053	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.053	1
08357	Anthracene	120-12-7	N.D.	0.011	0.053	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.053	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.053	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.053	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.053	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.053	1
08357	Chrysene	218-01-9	N.D.	0.011	0.053	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.053	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.053	1
08357	Fluorene	86-73-7	N.D.	0.011	0.053	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.053	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.053	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.053	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.053	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.053	1
08357	Pyrene	129-00-0	N.D.	0.011	0.053	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

The recovery for the sample surrogate(s) is outside the QC acceptance limits as noted on the QC Summary. The client was contacted and the data reported.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	28.8	0.033	0.20	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-010(1.5-2.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222557
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 09:50 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2101 SDG#: PEL88-05

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0585	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
01750	Calcium	7440-70-2	6.48	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.05	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
		EPA 1664A	mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 13:52	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 13:52	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 04:24	Catherine E Bachman	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/08/2013 23:43	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/08/2013 23:43	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/08/2013 23:43	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/08/2013 23:43	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/08/2013 23:43	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/08/2013 23:43	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/08/2013 23:43	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/08/2013 23:43	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/08/2013 23:43	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/08/2013 23:43	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/08/2013 23:43	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 09:34	Damary Valentin	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-010(1.5-2.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222557
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 09:50 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2101 SDG#: PEL88-05

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-010(3.5-4.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222558**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 10:00 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2102 SDG#: PEL88-06

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-010(3.5-4.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222558**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 10:00 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2102 SDG#: PEL88-06

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.054	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.054	1
08357	Anthracene	120-12-7	N.D.	0.011	0.054	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.054	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.054	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.054	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.054	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.054	1
08357	Chrysene	218-01-9	N.D.	0.011	0.054	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.054	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.054	1
08357	Fluorene	86-73-7	N.D.	0.011	0.054	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.054	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.054	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.054	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.054	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.054	1
08357	Pyrene	129-00-0	N.D.	0.011	0.054	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	29.5	0.033	0.20	1
	SW-846 6010B	mg/l	mg/l	mg/l		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0633	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-010(3.5-4.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222558
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 10:00 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2102 SDG#: PEL88-06

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
	SW-846 6010B		mg/l	mg/l	mg/l	
01750	Calcium	7440-70-2	6.65	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.13	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	SW-846 7470A		mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
	EPA 1664A		mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	1.8 J	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 14:13	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 14:13	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 04:54	Catherine E Bachman	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/08/2013 23:47	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/08/2013 23:47	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/08/2013 23:47	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/08/2013 23:47	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/08/2013 23:47	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/08/2013 23:47	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/08/2013 23:47	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/08/2013 23:47	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/08/2013 23:47	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/08/2013 23:47	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/08/2013 23:47	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 09:36	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-010(3.5-4.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222558
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 10:00 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2102 SDG#: PEL88-06

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-006(0.5-1.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222559**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 10:10 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2006 SDG#: PEL88-07

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-006(0.5-1.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222559**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 10:10 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2006 SDG#: PEL88-07

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.052	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.052	1
08357	Anthracene	120-12-7	N.D.	0.010	0.052	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.010	0.052	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.052	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.010	0.052	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.052	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.010	0.052	1
08357	Chrysene	218-01-9	N.D.	0.010	0.052	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.052	1
08357	Fluoranthene	206-44-0	N.D.	0.010	0.052	1
08357	Fluorene	86-73-7	N.D.	0.010	0.052	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.052	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.052	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.052	1
08357	Naphthalene	91-20-3	N.D.	0.031	0.052	1
08357	Phenanthrene	85-01-8	N.D.	0.031	0.052	1
08357	Pyrene	129-00-0	N.D.	0.010	0.052	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	29.1	0.033	0.20	1
	SW-846 6010B	mg/l	mg/l	mg/l		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0430	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-006(0.5-1.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222559
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 10:10 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2006 SDG#: PEL88-07

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
		SW-846 6010B	mg/l	mg/l	mg/l	
01750	Calcium	7440-70-2	6.59	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.08	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
		EPA 1664A	mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 14:34	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 14:34	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 05:23	Catherine E Bachman	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/08/2013 23:51	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/08/2013 23:51	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/08/2013 23:51	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/08/2013 23:51	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/08/2013 23:51	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/08/2013 23:51	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/08/2013 23:51	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/08/2013 23:51	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/08/2013 23:51	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/08/2013 23:51	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/08/2013 23:51	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 09:38	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-006(0.5-1.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222559
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 10:10 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2006 SDG#: PEL88-07

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-005(Surface)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222560
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 10:40 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2005 SDG#: PEL88-08

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	15	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	0.2 J	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-005(Surface)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222560
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 10:40 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2005 SDG#: PEL88-08

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	0.1 J	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.057	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.057	1
08357	Anthracene	120-12-7	N.D.	0.011	0.057	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.057	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.057	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.057	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.057	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.057	1
08357	Chrysene	218-01-9	N.D.	0.011	0.057	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.057	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.057	1
08357	Fluorene	86-73-7	N.D.	0.011	0.057	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.057	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.057	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.057	1
08357	Naphthalene	91-20-3	N.D.	0.034	0.057	1
08357	Phenanthrene	85-01-8	N.D.	0.034	0.057	1
08357	Pyrene	129-00-0	N.D.	0.011	0.057	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

The recovery for the sample surrogate(s) is outside the QC acceptance limits as noted on the QC Summary. The client was contacted and the data reported.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	29.6	0.033	0.20	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-005(Surface)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222560
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 10:40 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2005 SDG#: PEL88-08

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	0.0090 J	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0542	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
01750	Calcium	7440-70-2	6.90	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.01	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
		EPA 1664A	mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 14:55	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 14:55	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 05:53	Catherine E Bachman	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/08/2013 23:55	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/08/2013 23:55	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/08/2013 23:55	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/08/2013 23:55	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/08/2013 23:55	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/08/2013 23:55	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/08/2013 23:55	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/08/2013 23:55	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/08/2013 23:55	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/08/2013 23:55	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/08/2013 23:55	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 09:46	Damary Valentin	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-005(Surface)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222560
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 10:40 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2005 SDG#: PEL88-08

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-011(1.5-2.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222561
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 11:00 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2111 SDG#: PEL88-09

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-011(1.5-2.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222561**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 11:00 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2111 SDG#: PEL88-09

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.054	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.054	1
08357	Anthracene	120-12-7	N.D.	0.011	0.054	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.054	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.054	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.054	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.054	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.054	1
08357	Chrysene	218-01-9	N.D.	0.011	0.054	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.054	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.054	1
08357	Fluorene	86-73-7	N.D.	0.011	0.054	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.054	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.054	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.054	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.054	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.054	1
08357	Pyrene	129-00-0	N.D.	0.011	0.054	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

The recovery for the sample surrogate(s) is outside the QC acceptance limits as noted on the QC Summary. The client was contacted and the data reported.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	30.0	0.033	0.20	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-011(1.5-2.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222561
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 11:00 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2111 SDG#: PEL88-09

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0383	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
01750	Calcium	7440-70-2	6.73	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.20	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
		EPA 1664A	mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	1.7 J	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 15:17	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 15:17	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 06:22	Catherine E Bachman	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/08/2013 23:58	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/08/2013 23:58	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/08/2013 23:58	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/08/2013 23:58	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/08/2013 23:58	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/08/2013 23:58	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/08/2013 23:58	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/08/2013 23:58	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/08/2013 23:58	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/08/2013 23:58	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/08/2013 23:58	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 09:48	Damary Valentin	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-011(1.5-2.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222561
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 11:00 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2111 SDG#: PEL88-09

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-011(5.0-5.5)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222562
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 11:10 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2112 SDG#: PEL88-10

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-011(5.0-5.5)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222562**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 11:10 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2112 SDG#: PEL88-10

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.054	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.054	1
08357	Anthracene	120-12-7	N.D.	0.011	0.054	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.054	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.054	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.054	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.054	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.054	1
08357	Chrysene	218-01-9	N.D.	0.011	0.054	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.054	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.054	1
08357	Fluorene	86-73-7	N.D.	0.011	0.054	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.054	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.054	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.054	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.054	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.054	1
08357	Pyrene	129-00-0	N.D.	0.011	0.054	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

The recovery for the sample surrogate(s) is outside the QC acceptance limits as noted on the QC Summary. The client was contacted and the data reported.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	29.7	0.033	0.20	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-011(5.0-5.5)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222562
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 11:10 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2112 SDG#: PEL88-10

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0395	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
01750	Calcium	7440-70-2	6.66	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.18	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
		EPA 1664A	mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 15:38	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 15:38	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 06:51	Catherine E Bachman	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/09/2013 00:02	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/09/2013 00:02	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/09/2013 00:02	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/09/2013 00:02	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/09/2013 00:02	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/09/2013 00:02	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/09/2013 00:02	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/09/2013 00:02	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/09/2013 00:02	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/09/2013 00:02	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/09/2013 00:02	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 09:54	Damary Valentin	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-011(5.0-5.5)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222562
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 11:10 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2112 SDG#: PEL88-10

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-002 (Surface)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222563
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 11:30 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2002 SDG#: PEL88-11

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-002 (Surface)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222563**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 11:30 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2002 SDG#: PEL88-11

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.013	0.063	1
08357	Acenaphthylene	208-96-8	N.D.	0.013	0.063	1
08357	Anthracene	120-12-7	N.D.	0.013	0.063	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.013	0.063	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.013	0.063	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.013	0.063	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.013	0.063	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.013	0.063	1
08357	Chrysene	218-01-9	N.D.	0.013	0.063	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.013	0.063	1
08357	Fluoranthene	206-44-0	N.D.	0.013	0.063	1
08357	Fluorene	86-73-7	N.D.	0.013	0.063	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.013	0.063	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.013	0.063	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.013	0.063	1
08357	Naphthalene	91-20-3	N.D.	0.038	0.063	1
08357	Phenanthrene	85-01-8	N.D.	0.038	0.063	1
08357	Pyrene	129-00-0	N.D.	0.013	0.063	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

The recovery for the sample surrogate(s) is outside the QC acceptance limits as noted on the QC Summary. The client was contacted and the data reported.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	29.7	0.033	0.20	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-002 (Surface)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222563
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 11:30 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2002 SDG#: PEL88-11

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	0.0084 J	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0428	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
01750	Calcium	7440-70-2	6.72	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.13	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
		EPA 1664A	mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 15:59	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 15:59	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 07:20	Catherine E Bachman	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/08/2013 22:55	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/08/2013 22:55	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/08/2013 22:55	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/08/2013 22:55	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/08/2013 22:55	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/08/2013 22:55	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/08/2013 22:55	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/08/2013 22:55	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/08/2013 22:55	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/08/2013 22:55	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/08/2013 22:55	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 09:56	Damary Valentin	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-002 (Surface)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222563
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 11:30 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2002 SDG#: PEL88-11

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-018 (Surface)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222564**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 11:50 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2018 SDG#: PEL88-12

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-018 (Surface)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222564**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 11:50 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2018 SDG#: PEL88-12

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.055	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.055	1
08357	Anthracene	120-12-7	N.D.	0.011	0.055	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.055	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.055	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.055	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.055	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.055	1
08357	Chrysene	218-01-9	N.D.	0.011	0.055	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.055	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.055	1
08357	Fluorene	86-73-7	N.D.	0.011	0.055	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.055	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.055	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.055	1
08357	Naphthalene	91-20-3	N.D.	0.033	0.055	1
08357	Phenanthrene	85-01-8	N.D.	0.033	0.055	1
08357	Pyrene	129-00-0	N.D.	0.011	0.055	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	30.3	0.033	0.20	1
	SW-846 6010B	mg/l	mg/l	mg/l		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0593	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-018 (Surface)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222564
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 11:50 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2018 SDG#: PEL88-12

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
	SW-846 6010B		mg/l	mg/l	mg/l	
01750	Calcium	7440-70-2	6.82	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.22	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	SW-846 7470A		mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
	EPA 1664A		mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 16:19	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 16:19	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 10:10	Chad A Moline	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/09/2013 00:06	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/09/2013 00:06	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/09/2013 00:06	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/09/2013 00:06	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/09/2013 00:06	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/09/2013 00:06	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/09/2013 00:06	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/09/2013 00:06	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/09/2013 00:06	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/09/2013 00:06	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/09/2013 00:06	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 09:59	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-003 (Surface)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222565**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 12:00 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2003 SDG#: PEL88-13

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-003 (Surface)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222565**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 12:00 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2003 SDG#: PEL88-13

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.010	0.052	1
08357	Acenaphthylene	208-96-8	N.D.	0.010	0.052	1
08357	Anthracene	120-12-7	N.D.	0.010	0.052	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.010	0.052	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.010	0.052	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.010	0.052	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.010	0.052	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.010	0.052	1
08357	Chrysene	218-01-9	N.D.	0.010	0.052	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.010	0.052	1
08357	Fluoranthene	206-44-0	N.D.	0.010	0.052	1
08357	Fluorene	86-73-7	N.D.	0.010	0.052	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.010	0.052	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.010	0.052	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.010	0.052	1
08357	Naphthalene	91-20-3	N.D.	0.031	0.052	1
08357	Phenanthrene	85-01-8	N.D.	0.031	0.052	1
08357	Pyrene	129-00-0	N.D.	0.010	0.052	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

The recovery for the sample surrogate(s) is outside the QC acceptance limits as noted on the QC Summary. The client was contacted and the data reported.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	29.9	0.033	0.20	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-003 (Surface)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222565**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 12:00 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2003 SDG#: PEL88-13

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0533	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
01750	Calcium	7440-70-2	6.71	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.20	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
		EPA 1664A	mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	1.7 J	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 16:40	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 16:40	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 10:39	Chad A Moline	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/09/2013 00:10	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/09/2013 00:10	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/09/2013 00:10	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/09/2013 00:10	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/09/2013 00:10	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/09/2013 00:10	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/09/2013 00:10	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/09/2013 00:10	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/09/2013 00:10	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/09/2013 00:10	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/09/2013 00:10	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 10:01	Damary Valentin	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-003 (Surface)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222565
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 12:00 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2003 SDG#: PEL88-13

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-007(0.5-1.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222566
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 12:20 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2007 SDG#: PEL88-14

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-007(0.5-1.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222566**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 12:20 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2007 SDG#: PEL88-14

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.055	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.055	1
08357	Anthracene	120-12-7	N.D.	0.011	0.055	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.055	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.055	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.055	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.055	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.055	1
08357	Chrysene	218-01-9	N.D.	0.011	0.055	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.055	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.055	1
08357	Fluorene	86-73-7	N.D.	0.011	0.055	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.055	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.055	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.055	1
08357	Naphthalene	91-20-3	N.D.	0.033	0.055	1
08357	Phenanthrene	85-01-8	N.D.	0.033	0.055	1
08357	Pyrene	129-00-0	N.D.	0.011	0.055	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	21.9	0.033	0.20	1
	SW-846 6010B	mg/l	mg/l	mg/l		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0690	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-007(0.5-1.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222566
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 12:20 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2007 SDG#: PEL88-14

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
	SW-846 6010B		mg/l	mg/l	mg/l	
01750	Calcium	7440-70-2	5.25	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	2.13	0.0167	0.100	1
07061	Nickel	7440-02-0	0.0022 J	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	SW-846 7470A		mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
	EPA 1664A		mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	1.5 J	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 17:01	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 17:01	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 11:08	Chad A Moline	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/09/2013 00:22	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/09/2013 00:22	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/09/2013 00:22	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/09/2013 00:22	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/09/2013 00:22	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/09/2013 00:22	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/09/2013 00:22	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/09/2013 00:22	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/09/2013 00:22	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/09/2013 00:22	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/09/2013 00:22	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 10:03	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-001(0.5-1.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222567
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 12:40 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2001 SDG#: PEL88-15

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-001(0.5-1.0)100213 Grab Surface Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222567**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 12:40 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2001 SDG#: PEL88-15

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.053	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.053	1
08357	Anthracene	120-12-7	N.D.	0.011	0.053	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.053	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.053	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.053	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.053	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.053	1
08357	Chrysene	218-01-9	N.D.	0.011	0.053	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.053	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.053	1
08357	Fluorene	86-73-7	N.D.	0.011	0.053	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.053	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.053	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.053	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.053	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.053	1
08357	Pyrene	129-00-0	N.D.	0.011	0.053	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

The recovery for the sample surrogate(s) is outside the QC acceptance limits as noted on the QC Summary. The client was contacted and the data reported.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	29.4	0.033	0.20	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-001(0.5-1.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222567
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 12:40 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2001 SDG#: PEL88-15

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0537	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
01750	Calcium	7440-70-2	6.63	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.12	0.0167	0.100	1
07061	Nickel	7440-02-0	0.0019 J	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
		EPA 1664A	mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 17:22	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 17:22	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 11:37	Chad A Moline	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/09/2013 00:26	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/09/2013 00:26	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/09/2013 00:26	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/09/2013 00:26	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/09/2013 00:26	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/09/2013 00:26	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/09/2013 00:26	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/09/2013 00:26	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/09/2013 00:26	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/09/2013 00:26	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/09/2013 00:26	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 10:05	Damary Valentin	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-001(0.5-1.0)100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222567
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 12:40 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2001 SDG#: PEL88-15

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: DUP-WS-96-100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222568
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2D96 SDG#: PEL88-16FD

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: DUP-WS-96-100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222568
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2D96 SDG#: PEL88-16FD

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	N.D.	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.055	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.055	1
08357	Anthracene	120-12-7	N.D.	0.011	0.055	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.055	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.055	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.055	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.055	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.055	1
08357	Chrysene	218-01-9	N.D.	0.011	0.055	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.055	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.055	1
08357	Fluorene	86-73-7	N.D.	0.011	0.055	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.055	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.055	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.055	1
08357	Naphthalene	91-20-3	N.D.	0.033	0.055	1
08357	Phenanthrene	85-01-8	N.D.	0.033	0.055	1
08357	Pyrene	129-00-0	N.D.	0.011	0.055	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

The recovery for the sample surrogate(s) is outside the QC acceptance limits as noted on the QC Summary. The client was contacted and the data reported.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	29.7	0.033	0.20	1

*=This limit was used in the evaluation of the final result

Sample Description: DUP-WS-96-100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222568
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2D96 SDG#: PEL88-16FD

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0436	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
01750	Calcium	7440-70-2	6.72	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	3.14	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1
Wet Chemistry						
		EPA 1664A	mg/l	mg/l	mg/l	
08079	HEM (oil & grease)	n.a.	N.D.	1.4	5.0	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 17:43	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 17:43	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 12:06	Chad A Moline	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/09/2013 00:30	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/09/2013 00:30	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/09/2013 00:30	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/09/2013 00:30	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/09/2013 00:30	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/09/2013 00:30	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/09/2013 00:30	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/09/2013 00:30	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/09/2013 00:30	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/09/2013 00:30	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/09/2013 00:30	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 10:07	Damary Valentin	1

*=This limit was used in the evaluation of the final result

Sample Description: DUP-WS-96-100213 Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222568
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2D96 SDG#: PEL88-16FD

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1
08079	HEM (oil & grease)	EPA 1664A	1	13283807901A	10/10/2013 07:52	Yolunder Y Bunch	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-EB-79-100213 Grab Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222569**
LL Group # **1423470**
Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 13:30 by DD

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2E79 SDG#: PEL88-17EB

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
	purge					
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-EB-79-100213 Grab Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222569**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 13:30 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2E79 SDG#: PEL88-17EB

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	0.2 J	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1
GC/MS	Semivolatiles	SW-846 8270C SIM	ug/l	ug/l	ug/l	
08357	Acenaphthene	83-32-9	N.D.	0.011	0.053	1
08357	Acenaphthylene	208-96-8	N.D.	0.011	0.053	1
08357	Anthracene	120-12-7	N.D.	0.011	0.053	1
08357	Benzo(a)anthracene	56-55-3	N.D.	0.011	0.053	1
08357	Benzo(a)pyrene	50-32-8	N.D.	0.011	0.053	1
08357	Benzo(b)fluoranthene	205-99-2	N.D.	0.011	0.053	1
08357	Benzo(g,h,i)perylene	191-24-2	N.D.	0.011	0.053	1
08357	Benzo(k)fluoranthene	207-08-9	N.D.	0.011	0.053	1
08357	Chrysene	218-01-9	N.D.	0.011	0.053	1
08357	Dibenz(a,h)anthracene	53-70-3	N.D.	0.011	0.053	1
08357	Fluoranthene	206-44-0	N.D.	0.011	0.053	1
08357	Fluorene	86-73-7	N.D.	0.011	0.053	1
08357	Indeno(1,2,3-cd)pyrene	193-39-5	N.D.	0.011	0.053	1
08357	1-Methylnaphthalene	90-12-0	N.D.	0.011	0.053	1
08357	2-Methylnaphthalene	91-57-6	N.D.	0.011	0.053	1
08357	Naphthalene	91-20-3	N.D.	0.032	0.053	1
08357	Phenanthrene	85-01-8	N.D.	0.032	0.053	1
08357	Pyrene	129-00-0	N.D.	0.011	0.053	1

The laboratory did not receive sufficient sample volume to perform the method QC requirement for MS/MSD or MS/DUP analysis.

Metals	SM 2340 B-1997	mg/l	mg/l	mg/l		
06256	Total Hardness as CaCO3	471-34-1	0.23	0.033	0.20	1
	SW-846 6010B	mg/l	mg/l	mg/l		
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	N.D.	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1

*=This limit was used in the evaluation of the final result

Sample Description: **WS-EB-79-100213 Grab Water**
Mayflower, AR
Pipeline Incident

LL Sample # **WW 7222569**
 LL Group # **1423470**
 Account # **14739**

Project Name: **Mayflower, AR Pipeline Incident**

Collected: 10/02/2013 13:30 by DD

ExxonMobil c/o Arcadis
 630 Plaza Drive, Suite 600
 Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2E79 SDG#: PEL88-17EB

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals						
	SW-846 6010B		mg/l	mg/l	mg/l	
01750	Calcium	7440-70-2	0.0927 J	0.0334	0.200	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
01757	Magnesium	7439-95-4	N.D.	0.0167	0.100	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
	SW-846 7470A		mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 10:45	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 10:45	Kerri E Legerlotz	1
08357	PAHs in waters by SIM	SW-846 8270C SIM	1	13277WAA026	10/09/2013 12:35	Chad A Moline	1
10470	BNA Water Extraction (SIM)	SW-846 3510C	1	13277WAA026	10/04/2013 16:45	JoElla L Rice	1
06256	Total Hardness as CaCO3	SM 2340 B-1997	1	132826256001	10/09/2013 04:55	Deborah A Krady	1
07035	Arsenic	SW-846 6010B	1	132761848001	10/09/2013 00:34	John W Yanzuk II	1
07046	Barium	SW-846 6010B	1	132761848001	10/09/2013 00:34	John W Yanzuk II	1
07049	Cadmium	SW-846 6010B	1	132761848001	10/09/2013 00:34	John W Yanzuk II	1
01750	Calcium	SW-846 6010B	1	132761848001	10/09/2013 00:34	John W Yanzuk II	1
07051	Chromium	SW-846 6010B	1	132761848001	10/09/2013 00:34	John W Yanzuk II	1
07055	Lead	SW-846 6010B	1	132761848001	10/09/2013 00:34	John W Yanzuk II	1
01757	Magnesium	SW-846 6010B	1	132761848001	10/09/2013 00:34	John W Yanzuk II	1
07061	Nickel	SW-846 6010B	1	132761848001	10/09/2013 00:34	John W Yanzuk II	1
07036	Selenium	SW-846 6010B	1	132761848001	10/09/2013 00:34	John W Yanzuk II	1
07066	Silver	SW-846 6010B	1	132761848001	10/09/2013 00:34	John W Yanzuk II	1
07071	Vanadium	SW-846 6010B	1	132761848001	10/09/2013 00:34	John W Yanzuk II	1
00259	Mercury	SW-846 7470A	1	132765713001	10/07/2013 10:09	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132761848001	10/04/2013 06:00	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132765713001	10/04/2013 17:20	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-TB-166-100213 Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222570
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2166 SDG#: PEL88-18TB*

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	Acetone	67-64-1	N.D.	3.0	5.0	1
02898	Allyl Chloride	107-05-1	N.D.	0.1	0.5	1
02898	Benzene	71-43-2	N.D.	0.1	0.5	1
02898	Bromobenzene	108-86-1	N.D.	0.1	0.5	1
02898	Bromochloromethane	74-97-5	N.D.	0.1	0.5	1
02898	Bromodichloromethane	75-27-4	N.D.	0.1	0.5	1
02898	Bromoform	75-25-2	N.D.	0.1	0.5	1
02898	Bromomethane	74-83-9	N.D.	0.1	0.5	1
02898	2-Butanone	78-93-3	N.D.	1.0	5.0	1
02898	n-Butylbenzene	104-51-8	N.D.	0.1	0.5	1
02898	sec-Butylbenzene	135-98-8	N.D.	0.1	0.5	1
02898	tert-Butylbenzene	98-06-6	N.D.	0.1	0.5	1
02898	Carbon Tetrachloride	56-23-5	N.D.	0.1	0.5	1
02898	Chlorobenzene	108-90-7	N.D.	0.1	0.5	1
02898	Chloroethane	75-00-3	N.D.	0.1	0.5	1
02898	Chloroform	67-66-3	N.D.	0.1	0.5	1
02898	Chloromethane	74-87-3	N.D.	0.2	0.5	1
02898	2-Chlorotoluene	95-49-8	N.D.	0.1	0.5	1
02898	4-Chlorotoluene	106-43-4	N.D.	0.1	0.5	1
02898	1,2-Dibromo-3-chloropropane	96-12-8	N.D.	0.2	0.5	1
02898	Dibromochloromethane	124-48-1	N.D.	0.1	0.5	1
02898	1,2-Dibromoethane	106-93-4	N.D.	0.1	0.5	1
02898	Dibromomethane	74-95-3	N.D.	0.1	0.5	1
02898	1,2-Dichlorobenzene	95-50-1	N.D.	0.1	0.5	1
02898	1,3-Dichlorobenzene	541-73-1	N.D.	0.1	0.5	1
02898	1,4-Dichlorobenzene	106-46-7	N.D.	0.1	0.5	1
02898	Dichlorodifluoromethane	75-71-8	N.D.	0.1	0.5	1
02898	1,1-Dichloroethane	75-34-3	N.D.	0.1	0.5	1
02898	1,2-Dichloroethane	107-06-2	N.D.	0.1	0.5	1
02898	1,1-Dichloroethene	75-35-4	N.D.	0.1	0.5	1
02898	cis-1,2-Dichloroethene	156-59-2	N.D.	0.1	0.5	1
02898	trans-1,2-Dichloroethene	156-60-5	N.D.	0.1	0.5	1
02898	Dichlorofluoromethane	75-43-4	N.D.	0.2	0.5	1
02898	1,2-Dichloropropane	78-87-5	N.D.	0.1	0.5	1
02898	1,3-Dichloropropane	142-28-9	N.D.	0.1	0.5	1
02898	2,2-Dichloropropane	594-20-7	N.D.	0.1	0.5	1
02898	1,1-Dichloropropene	563-58-6	N.D.	0.1	0.5	1
02898	cis-1,3-Dichloropropene	10061-01-5	N.D.	0.1	0.5	1
02898	trans-1,3-Dichloropropene	10061-02-6	N.D.	0.1	0.5	1
02898	Ethyl ether	60-29-7	N.D.	0.1	0.5	1
02898	Ethylbenzene	100-41-4	N.D.	0.1	0.5	1
02898	Freon 113	76-13-1	N.D.	0.2	0.5	1
02898	Hexachlorobutadiene	87-68-3	N.D.	0.1	0.5	1
02898	Isopropylbenzene	98-82-8	N.D.	0.1	0.5	1
02898	p-Isopropyltoluene	99-87-6	N.D.	0.1	0.5	1
02898	Methyl Tertiary Butyl Ether	1634-04-4	N.D.	0.1	0.5	1
02898	4-Methyl-2-Pentanone	108-10-1	N.D.	1.0	5.0	1
02898	Methylene Chloride	75-09-2	N.D.	0.2	0.5	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-TB-166-100213 Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7222570
LL Group # 1423470
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/02/2013

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/03/2013 09:15

Reported: 10/10/2013 15:24

-2166 SDG#: PEL88-18TB*

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
GC/MS	Volatiles	SW-846 8260B 25mL	ug/l	ug/l	ug/l	
		purge				
02898	n-Propylbenzene	103-65-1	N.D.	0.1	0.5	1
02898	Styrene	100-42-5	N.D.	0.1	0.5	1
02898	1,1,1,2-Tetrachloroethane	630-20-6	N.D.	0.1	0.5	1
02898	1,1,2,2-Tetrachloroethane	79-34-5	N.D.	0.1	0.5	1
02898	Tetrachloroethene	127-18-4	N.D.	0.1	0.5	1
02898	Tetrahydrofuran	109-99-9	N.D.	2.0	5.0	1
02898	Toluene	108-88-3	0.1 J	0.1	0.5	1
02898	1,2,3-Trichlorobenzene	87-61-6	N.D.	0.1	0.5	1
02898	1,2,4-Trichlorobenzene	120-82-1	N.D.	0.1	0.5	1
02898	1,1,1-Trichloroethane	71-55-6	N.D.	0.1	0.5	1
02898	1,1,2-Trichloroethane	79-00-5	N.D.	0.1	0.5	1
02898	Trichloroethene	79-01-6	N.D.	0.1	0.5	1
02898	Trichlorofluoromethane	75-69-4	N.D.	0.1	0.5	1
02898	1,2,3-Trichloropropane	96-18-4	N.D.	0.3	1.0	1
02898	1,2,4-Trimethylbenzene	95-63-6	N.D.	0.1	0.5	1
02898	1,3,5-Trimethylbenzene	108-67-8	N.D.	0.1	0.5	1
02898	Vinyl Chloride	75-01-4	N.D.	0.1	0.5	1
02898	Xylene (Total)	1330-20-7	N.D.	0.1	0.5	1

General Sample Comments

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
02898	Silvertip & Mayflower VOCs8260	SW-846 8260B 25mL purge	1	H132771AA	10/04/2013 11:05	Kerri E Legerlotz	1
01163	GC/MS VOA Water Prep	SW-846 5030B	1	H132771AA	10/04/2013 11:05	Kerri E Legerlotz	1

*=This limit was used in the evaluation of the final result

Quality Control Summary

Client Name: ExxonMobil c/o Arcadis
Reported: 10/10/13 at 03:24 PM

Group Number: 1423470

Matrix QC may not be reported if insufficient sample or site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD was performed, unless otherwise specified in the method.

All Inorganic Initial Calibration and Continuing Calibration Blanks met acceptable method criteria unless otherwise noted on the Analysis Report.

Laboratory Compliance Quality Control

<u>Analysis Name</u>	<u>Blank Result</u>	<u>Blank MDL**</u>	<u>Blank LOQ</u>	<u>Report Units</u>	<u>LCS %REC</u>	<u>LCSD %REC</u>	<u>LCS/LCSD Limits</u>	<u>RPD</u>	<u>RPD Max</u>
Batch number: H132771AA	Sample number(s): 7222553-7222570								
Acetone	N.D.	3.0	5.0	ug/l	84		60-139		
Allyl Chloride	N.D.	0.1	0.5	ug/l	78		61-130		
Benzene	N.D.	0.1	0.5	ug/l	94		80-120		
Bromobenzene	N.D.	0.1	0.5	ug/l	92		80-120		
Bromochloromethane	N.D.	0.1	0.5	ug/l	101		80-125		
Bromodichloromethane	N.D.	0.1	0.5	ug/l	96		80-120		
Bromoform	N.D.	0.1	0.5	ug/l	109		73-128		
Bromomethane	N.D.	0.1	0.5	ug/l	79		62-126		
2-Butanone	N.D.	1.0	5.0	ug/l	94		70-130		
n-Butylbenzene	N.D.	0.1	0.5	ug/l	89		80-120		
sec-Butylbenzene	N.D.	0.1	0.5	ug/l	91		80-120		
tert-Butylbenzene	N.D.	0.1	0.5	ug/l	89		80-120		
Carbon Tetrachloride	N.D.	0.1	0.5	ug/l	101		80-129		
Chlorobenzene	N.D.	0.1	0.5	ug/l	98		80-120		
Chloroethane	N.D.	0.1	0.5	ug/l	76		68-120		
Chloroform	N.D.	0.1	0.5	ug/l	96		80-120		
Chloromethane	N.D.	0.2	0.5	ug/l	60		55-120		
2-Chlorotoluene	N.D.	0.1	0.5	ug/l	92		80-120		
4-Chlorotoluene	N.D.	0.1	0.5	ug/l	92		80-120		
1,2-Dibromo-3-chloropropane	N.D.	0.2	0.5	ug/l	118		64-141		
Dibromochloromethane	N.D.	0.1	0.5	ug/l	103		80-126		
1,2-Dibromoethane	N.D.	0.1	0.5	ug/l	97		80-120		
Dibromomethane	N.D.	0.1	0.5	ug/l	99		80-120		
1,2-Dichlorobenzene	N.D.	0.1	0.5	ug/l	97		80-120		
1,3-Dichlorobenzene	N.D.	0.1	0.5	ug/l	96		80-120		
1,4-Dichlorobenzene	N.D.	0.1	0.5	ug/l	96		80-120		
Dichlorodifluoromethane	N.D.	0.1	0.5	ug/l	49		39-120		
1,1-Dichloroethane	N.D.	0.1	0.5	ug/l	93		80-120		
1,2-Dichloroethane	N.D.	0.1	0.5	ug/l	100		80-127		
1,1-Dichloroethene	N.D.	0.1	0.5	ug/l	96		80-123		
cis-1,2-Dichloroethene	N.D.	0.1	0.5	ug/l	96		80-120		
trans-1,2-Dichloroethene	N.D.	0.1	0.5	ug/l	98		80-120		
Dichlorofluoromethane	N.D.	0.2	0.5	ug/l	84		75-145		
1,2-Dichloropropane	N.D.	0.1	0.5	ug/l	94		80-120		
1,3-Dichloropropane	N.D.	0.1	0.5	ug/l	94		80-120		
2,2-Dichloropropane	N.D.	0.1	0.5	ug/l	95		75-122		
1,1-Dichloropropene	N.D.	0.1	0.5	ug/l	93		80-121		
cis-1,3-Dichloropropene	N.D.	0.1	0.5	ug/l	96		80-123		
trans-1,3-Dichloropropene	N.D.	0.1	0.5	ug/l	90		80-120		
Ethyl ether	N.D.	0.1	0.5	ug/l	81		59-130		
Ethylbenzene	N.D.	0.1	0.5	ug/l	92		80-120		
Freon 113	N.D.	0.2	0.5	ug/l	96		78-132		
Hexachlorobutadiene	N.D.	0.1	0.5	ug/l	91		73-120		

*- Outside of specification

** - This limit was used in the evaluation of the final result for the blank

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

Quality Control Summary

Client Name: ExxonMobil c/o Arcadis
Reported: 10/10/13 at 03:24 PM

Group Number: 1423470

<u>Analysis Name</u>	<u>Blank Result</u>	<u>Blank MDL**</u>	<u>Blank LOQ</u>	<u>Report Units</u>	<u>LCS %REC</u>	<u>LCS D %REC</u>	<u>LCS/LCS D Limits</u>	<u>RPD</u>	<u>RPD Max</u>
Isopropylbenzene	N.D.	0.1	0.5	ug/l	94		80-120		
p-Isopropyltoluene	N.D.	0.1	0.5	ug/l	90		80-120		
Methyl Tertiary Butyl Ether	N.D.	0.1	0.5	ug/l	93		80-120		
4-Methyl-2-Pentanone	N.D.	1.0	5.0	ug/l	82		69-135		
Methylene Chloride	N.D.	0.2	0.5	ug/l	95		80-120		
n-Propylbenzene	N.D.	0.1	0.5	ug/l	89		80-120		
Styrene	N.D.	0.1	0.5	ug/l	95		80-120		
1,1,1,2-Tetrachloroethane	N.D.	0.1	0.5	ug/l	99		80-120		
1,1,2,2-Tetrachloroethane	N.D.	0.1	0.5	ug/l	92		80-125		
Tetrachloroethene	N.D.	0.1	0.5	ug/l	99		80-120		
Tetrahydrofuran	N.D.	2.0	5.0	ug/l	104		65-131		
Toluene	N.D.	0.1	0.5	ug/l	93		80-120		
1,2,3-Trichlorobenzene	N.D.	0.1	0.5	ug/l	91		63-120		
1,2,4-Trichlorobenzene	N.D.	0.1	0.5	ug/l	92		70-120		
1,1,1-Trichloroethane	N.D.	0.1	0.5	ug/l	98		80-120		
1,1,2-Trichloroethane	N.D.	0.1	0.5	ug/l	97		80-120		
Trichloroethene	N.D.	0.1	0.5	ug/l	98		80-120		
Trichlorofluoromethane	N.D.	0.1	0.5	ug/l	86		77-132		
1,2,3-Trichloropropane	N.D.	0.3	1.0	ug/l	90		80-120		
1,2,4-Trimethylbenzene	N.D.	0.1	0.5	ug/l	89		80-120		
1,3,5-Trimethylbenzene	N.D.	0.1	0.5	ug/l	91		80-120		
Vinyl Chloride	N.D.	0.1	0.5	ug/l	69		65-127		
Xylene (Total)	N.D.	0.1	0.5	ug/l	95		80-120		

Batch number: 13277WAA026

Sample number(s): 7222553-7222569

Acenaphthene	N.D.	0.010	0.050	ug/l	96	95	77-118	1	30
Acenaphthylene	N.D.	0.010	0.050	ug/l	103	101	80-123	2	30
Anthracene	N.D.	0.010	0.050	ug/l	102	102	78-123	0	30
Benzo(a)anthracene	N.D.	0.010	0.050	ug/l	102	101	73-127	1	30
Benzo(a)pyrene	N.D.	0.010	0.050	ug/l	104	105	72-120	2	30
Benzo(b)fluoranthene	N.D.	0.010	0.050	ug/l	118	117	79-136	1	30
Benzo(g,h,i)perylene	N.D.	0.010	0.050	ug/l	101	100	64-130	0	30
Benzo(k)fluoranthene	N.D.	0.010	0.050	ug/l	106	108	73-131	2	30
Chrysene	N.D.	0.010	0.050	ug/l	103	104	76-125	1	30
Dibenz(a,h)anthracene	N.D.	0.010	0.050	ug/l	100	99	58-131	1	30
Fluoranthene	N.D.	0.010	0.050	ug/l	106	105	79-124	2	30
Fluorene	N.D.	0.010	0.050	ug/l	101	99	74-115	2	30
Indeno(1,2,3-cd)pyrene	N.D.	0.010	0.050	ug/l	103	100	62-130	2	30
1-Methylnaphthalene	N.D.	0.010	0.050	ug/l	109	107	80-126	2	30
2-Methylnaphthalene	N.D.	0.010	0.050	ug/l	108	104	81-124	3	30
Naphthalene	N.D.	0.030	0.050	ug/l	101	99	75-120	2	30
Phenanthrene	N.D.	0.030	0.050	ug/l	98	98	75-120	0	30
Pyrene	N.D.	0.010	0.050	ug/l	107	108	71-130	1	30

Batch number: 132761848001

Sample number(s): 7222553-7222569

Arsenic	N.D.	0.0068	0.0200	mg/l	103		90-113		
Barium	N.D.	0.00033	0.0050	mg/l	102		90-110		
Cadmium	N.D.	0.00076	0.0050	mg/l	104		90-112		
Calcium	0.0358 J	0.0334	0.200	mg/l	102		90-112		
Chromium	N.D.	0.0016	0.0150	mg/l	103		90-110		
Lead	N.D.	0.0047	0.0150	mg/l	107		88-110		
Magnesium	N.D.	0.0167	0.100	mg/l	101		89-110		
Nickel	N.D.	0.0015	0.0100	mg/l	106		90-111		
Selenium	N.D.	0.0084	0.0200	mg/l	102		80-120		
Silver	N.D.	0.0021	0.0050	mg/l	91		80-120		
Vanadium	N.D.	0.0020	0.0050	mg/l	104		90-110		

*- Outside of specification

** - This limit was used in the evaluation of the final result for the blank

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

Quality Control Summary

Client Name: ExxonMobil c/o Arcadis
Reported: 10/10/13 at 03:24 PM

Group Number: 1423470

<u>Analysis Name</u>	<u>Blank Result</u>	<u>Blank MDL**</u>	<u>Blank LOQ</u>	<u>Report Units</u>	<u>LCS %REC</u>	<u>LCS %REC</u>	<u>LCS/LCSD Limits</u>	<u>RPD</u>	<u>RPD Max</u>
Batch number: 132765713001 Mercury	Sample number(s): 7222553-7222569 N.D.	0.00006	0.00020	mg/l	107		80-120		
Batch number: 13283807901A HEM (oil & grease)	Sample number(s): 7222553-7222568 N.D.	1.4	5.0	mg/l	98	94	78-114	3	16

Sample Matrix Quality Control

Unspiked (UNSPK) = the sample used in conjunction with the matrix spike
Background (BKG) = the sample used in conjunction with the duplicate

<u>Analysis Name</u>	<u>MS %REC</u>	<u>MSD %REC</u>	<u>MS/MSD Limits</u>	<u>RPD</u>	<u>RPD MAX</u>	<u>BKG Conc</u>	<u>DUP Conc</u>	<u>DUP RPD</u>	<u>Dup RPD Max</u>
Batch number: H132771AA	Sample number(s): 7222553-7222570 UNSPK: 7222553								
Acetone	88	101	57-163	14	30				
Allyl Chloride	76	82	56-160	8	30				
Benzene	90	102	87-126	13	30				
Bromobenzene	88	104	80-123	17	30				
Bromochloromethane	103	112	82-125	9	30				
Bromodichloromethane	91	106	82-133	15	30				
Bromoform	102	121	60-138	18	30				
Bromomethane	82	83	66-130	1	30				
2-Butanone	81	97	56-160	19	30				
n-Butylbenzene	88	103	83-131	16	30				
sec-Butylbenzene	88	103	84-128	16	30				
tert-Butylbenzene	87	107	84-135	20	30				
Carbon Tetrachloride	100	113	81-148	12	30				
Chlorobenzene	93	110	78-133	17	30				
Chloroethane	79	79	70-139	1	30				
Chloroform	92	106	86-136	14	30				
Chloromethane	62	65	49-135	4	30				
2-Chlorotoluene	88	104	75-134	17	30				
4-Chlorotoluene	86	105	76-134	20	30				
1,2-Dibromo-3-chloropropane	106	127	43-143	18	30				
Dibromochloromethane	94	112	79-125	17	30				
1,2-Dibromoethane	91	106	84-127	15	30				
Dibromomethane	94	108	83-126	14	30				
1,2-Dichlorobenzene	93	109	83-117	16	30				
1,3-Dichlorobenzene	93	109	79-132	16	30				
1,4-Dichlorobenzene	92	109	79-120	18	30				
Dichlorodifluoromethane	52	52	28-136	1	30				
1,1-Dichloroethane	88	101	88-136	13	30				
1,2-Dichloroethane	95	107	82-135	12	30				
1,1-Dichloroethene	96	108	83-150	12	30				
cis-1,2-Dichloroethene	91	105	82-129	14	30				
trans-1,2-Dichloroethene	93	107	88-127	13	30				
Dichlorofluoromethane	88	88	81-161	0	30				
1,2-Dichloropropane	88*	104	91-126	17	30				
1,3-Dichloropropane	87	103	80-127	17	30				
2,2-Dichloropropane	93	104	80-134	11	30				
1,1-Dichloropropene	91	102	86-139	12	30				

*- Outside of specification

** - This limit was used in the evaluation of the final result for the blank

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

Quality Control Summary

Client Name: ExxonMobil c/o Arcadis
Reported: 10/10/13 at 03:24 PM

Group Number: 1423470

Sample Matrix Quality Control

Unspiked (UNSPK) = the sample used in conjunction with the matrix spike
Background (BKG) = the sample used in conjunction with the duplicate

<u>Analysis Name</u>	<u>MS</u> <u>%REC</u>	<u>MSD</u> <u>%REC</u>	<u>MS/MSD</u> <u>Limits</u>	<u>RPD</u> <u>RPD</u>	<u>RPD</u> <u>MAX</u>	<u>BKG</u> <u>Conc</u>	<u>DUP</u> <u>Conc</u>	<u>DUP</u> <u>RPD</u>	<u>Dup RPD</u> <u>Max</u>
cis-1,3-Dichloropropene	89	106	74-132	17	30				
trans-1,3-Dichloropropene	81	98	71-128	19	30				
Ethyl ether	74	79	57-139	6	30				
Ethylbenzene	88	104	80-140	17	30				
Freon 113	96	106	77-147	10	30				
Hexachlorobutadiene	90	107	65-128	17	30				
Isopropylbenzene	91	108	81-133	17	30				
p-Isopropyltoluene	88	103	84-124	16	30				
Methyl Tertiary Butyl Ether	85	97	82-132	13	30				
4-Methyl-2-Pentanone	80	93	69-149	16	30				
Methylene Chloride	89	101	77-135	13	30				
n-Propylbenzene	86	101	79-131	16	30				
Styrene	91	107	63-151	16	30				
1,1,1,2-Tetrachloroethane	94	111	87-126	16	30				
1,1,2,2-Tetrachloroethane	87	103	75-131	17	30				
Tetrachloroethene	96	111	75-129	15	30				
Tetrahydrofuran	86	102	56-154	17	30				
Toluene	89	103	83-127	15	30				
1,2,3-Trichlorobenzene	85	101	73-125	17	30				
1,2,4-Trichlorobenzene	89	103	77-120	16	30				
1,1,1-Trichloroethane	97	109	85-140	12	30				
1,1,2-Trichloroethane	92	106	85-129	14	30				
Trichloroethene	95	111	85-131	15	30				
Trichlorofluoromethane	92	90	73-139	2	30				
1,2,3-Trichloropropane	90	106	76-120	16	30				
1,2,4-Trimethylbenzene	86*	101	87-126	17	30				
1,3,5-Trimethylbenzene	87*	103	89-129	16	30				
Vinyl Chloride	73	74	62-135	1	30				
Xylene (Total)	91	108	81-137	17	30				

Batch number: 132761848001	Sample number(s): 7222553-7222569 UNSPK: 7222563 BKG: 7222563								
Arsenic	103	102	81-123	1	20	0.0084 J	0.0070 J	19 (1)	20
Barium	103	104	78-118	1	20	0.0428	0.0424	1	20
Cadmium	105	105	83-116	0	20	N.D.	N.D.	0 (1)	20
Calcium	99	104	75-125	2	20	6.72	6.67	1	20
Chromium	105	105	76-120	0	20	N.D.	N.D.	0 (1)	20
Lead	109	107	75-125	1	20	N.D.	N.D.	0 (1)	20
Magnesium	100	103	75-125	1	20	3.13	3.11	1	20
Nickel	107	107	86-115	0	20	N.D.	0.0017 J	200* (1)	20
Selenium	104	102	75-125	2	20	N.D.	N.D.	0 (1)	20
Silver	92	93	75-125	1	20	N.D.	N.D.	0 (1)	20
Vanadium	106	106	90-117	0	20	N.D.	N.D.	0 (1)	20

Batch number: 132765713001	Sample number(s): 7222553-7222569 UNSPK: 7222559 BKG: 7222559								
Mercury	108	105	80-120	3	20	N.D.	N.D.	0 (1)	20

Batch number: 13283807901A	Sample number(s): 7222553-7222568 UNSPK: 7222553								
HEM (oil & grease)	47*		78-114						

*- Outside of specification

** - This limit was used in the evaluation of the final result for the blank

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

Quality Control Summary

Client Name: ExxonMobil c/o Arcadis
Reported: 10/10/13 at 03:24 PM

Group Number: 1423470

Surrogate Quality Control

Surrogate recoveries which are outside of the QC window are confirmed unless attributed to dilution or otherwise noted on the Analysis Report.

Analysis Name: BTEX 25-ml purge

Batch number: H132771AA

	Dibromofluoromethane	1,2-Dichloroethane-d4	Toluene-d8	4-Bromofluorobenzene
7222553	104	105	97	96
7222554	106	105	97	97
7222555	105	105	98	97
7222556	105	104	97	95
7222557	105	104	98	97
7222558	106	105	97	97
7222559	104	107	96	97
7222560	105	107	97	97
7222561	105	105	97	96
7222562	104	104	97	96
7222563	105	104	96	95
7222564	104	103	97	95
7222565	104	103	97	96
7222566	105	104	97	97
7222567	105	107	97	96
7222568	105	104	96	96
7222569	105	104	97	96
7222570	104	106	97	97
Blank	104	106	97	97
LCS	104	103	98	99
MS	105	105	97	98
MSD	104	105	98	99
<hr/>				
Limits:	77-114	74-113	77-110	78-110

Analysis Name: PAHs in waters by SIM

Batch number: 13277WAA026

	Fluoranthene-d10	Benzo(a)pyrene-d12	1-Methylnaphthalene-d10
7222553	80	71	89
7222554	93	74	96
7222555	88	69	94
7222556	81	71	91
7222557	74	45*	81
7222558	84	66	84
7222559	90	66	94
7222560	81	57*	91
7222561	83	58*	90
7222562	89	59*	94
7222563	83	52*	85
7222564	91	66	93
7222565	85	61*	90
7222566	78	68	86
7222567	59	47*	58
7222568	72	38*	81
7222569	87	85	92
Blank	92	95	94
LCS	97	100	101

*- Outside of specification

** - This limit was used in the evaluation of the final result for the blank

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

Quality Control Summary

Client Name: ExxonMobil c/o Arcadis
Reported: 10/10/13 at 03:24 PM

Group Number: 1423470

Surrogate Quality Control

LCSD	94	99	98
Limits:	44-137	62-141	51-136

*- Outside of specification

** - This limit was used in the evaluation of the final result for the blank

- (1) The result for one or both determinations was less than five times the LOQ.
- (2) The unspiked result was more than four times the spike added.

ExxonMobil Analysis Request/Chain of Custody



Lancaster Laboratories Environmental

Acct. # 14739 For Eurofins Lancaster Laboratories Environmental use only
 Group # 1423470 Sample # 7222553-70
 Instructions on reverse side correspond with circled numbers.

1 of 2

1 Client Information				4 Matrix				5 Analyses Requested															
Facility #/SID <u>Mayflower Pipeline Incident</u>				Sediment <input type="checkbox"/> Potable <input type="checkbox"/> Ground <input type="checkbox"/> Water <input type="checkbox"/> NPDES <input type="checkbox"/> Surface <input checked="" type="checkbox"/> Oil <input type="checkbox"/> Air <input type="checkbox"/>	Total # of Containers	Preservation Code												SCR#: _____ Preservation Codes H = HCl T = Thiosulfate N = HNO ₃ B = NaOH S = H ₂ SO ₄ O = Other					
Site Address <u>Mayflower, AR</u>						VOCs <u>8260 B</u> PAHs <u>8270 SIM</u> PCRA Metals <u>Ni, Cu, V, Mg</u> Diss Metals HEM Oil & Grease	H	N	H														
ExxonMobil PM <u>Scott Bushroe</u>		Cost Center/AFE																					
Consultant/Office <u>Arcadis</u>																							
Consultant PM <u>Steve Barrick</u>		Consultant Phone # <u>919 302 6799</u>																					
Sampler <u>Dave Drost / Hans Van Aller</u>																							
2 Sample Identification			3 Collected		Grab	Composite																	
		Date	Time																				
<u>WS-014(1.5-2.0)100213</u>		<u>10/2/13</u>	<u>850</u>	<u>X</u>		<u>X</u>		<u>9</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>										
<u>WS-014(3.5-6.0)100213</u>			<u>900</u>	<u>X</u>		<u>X</u>		<u>9</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>										
<u>WS-012(1.5-2.0)100213</u>			<u>920</u>	<u>X</u>		<u>X</u>		<u>9</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>										
<u>WS-012(5.0-5.5)100213</u>			<u>930</u>	<u>X</u>		<u>X</u>		<u>9</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>										
<u>WS-010(1.5-2.0)100213</u>			<u>950</u>	<u>X</u>		<u>X</u>		<u>9</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>										
<u>WS-010(3.5-4.0)100213</u>			<u>1000</u>	<u>X</u>		<u>X</u>		<u>9</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>										
<u>WS-006(0.5-1.0)100213</u>			<u>1010</u>	<u>X</u>		<u>X</u>		<u>9</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>										
<u>WS-005(surface)100213</u>			<u>1040</u>	<u>X</u>		<u>X</u>		<u>9</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>										
<u>WS-011(1.5-2.0)100213</u>			<u>1100</u>	<u>X</u>		<u>X</u>		<u>9</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>										
<u>WS-011(1.5-2.0)100213</u>			<u>1110</u>	<u>X</u>		<u>X</u>		<u>9</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>										
<u>WS-002(surface)100213</u>			<u>1130</u>	<u>X</u>		<u>X</u>		<u>9</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>										
<u>WS-018(surface)100213</u>			<u>1150</u>	<u>X</u>		<u>X</u>		<u>9</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>	<u>X</u>										

7 Turnaround Time Requested (TAT) (please circle)			Relinquished by <u>H Van Aller</u>		Date <u>10/2/13</u>	Time <u>1500</u>	Received by	Date	Time
Standard	<u>5 day</u>	4 day							
72 hour	48 hour	24 hour							
			Relinquished by		Date	Time	Received by	Date	Time
			Relinquished by		Date	Time	Received by	Date	Time
			Relinquished by Commercial Carrier		UPS <input checked="" type="checkbox"/> FedEx _____ Other _____		Received by <u>C. Ehl</u>	Date <u>10/3/13</u>	Time <u>915</u>
			Temperature Upon Receipt <u>0.7-1.8 °C</u>				Custody Seals Intact? <u>Yes</u> No		

ExxonMobil Analysis Request/Chain of Custody



Lancaster Laboratories
Environmental

Acct. # 14739 For Eurofins Lancaster Laboratories Environmental use only
Group # 1423470 Sample # 7222553-70
Instructions on reverse side correspond with circled numbers.

2 of 2

1 Client Information				4 Matrix			5 Analyses Requested											6																																																																																																																																																																														
Facility #/SID <u>May flower Pipeline Incident</u>				Sediment	Potable	Ground	Surface	Preservation Code											SCR#: _____																																																																																																																																																																													
Site Address <u>May flower, AR</u>								Soil	Water	Oil	Air	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">H</td><td style="text-align: center;">N</td><td style="text-align: center;">H</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td style="text-align: center;">VOCs</td><td style="text-align: center;">PAH</td><td style="text-align: center;">PCRAA Metals</td><td style="text-align: center;">Diss Metals</td><td style="text-align: center;">HEM Oil & Grease</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> </table>											H	N	H																			VOCs	PAH	PCRAA Metals	Diss Metals	HEM Oil & Grease																	Preservation Codes H = HCl T = Thiosulfate N = HNO ₃ B = NaOH S = H ₂ SO ₄ O = Other																																																																																																																															
H	N	H																																																																																																																																																																																														
VOCs	PAH	PCRAA Metals	Diss Metals	HEM Oil & Grease																																																																																																																																																																																												
ExxonMobil PM <u>Scott Bushroe</u>				NPDES			Total # of Containers											Remarks																																																																																																																																																																														
Consultant/Office <u>Arcadis</u>				Air																																																																																																																																																																																												
Consultant PM <u>Steve Barrick</u>				Composite			<table style="width: 100%; border-collapse: collapse;"> <tr> <th style="width: 15%;">Sample Identification</th> <th style="width: 15%;">Date</th> <th style="width: 15%;">Time</th> <th style="width: 5%;">Grab</th> <th style="width: 5%;">Composite</th> <th style="width: 5%;">Soil</th> <th style="width: 5%;">Water</th> <th style="width: 5%;">Oil</th> <th style="width: 5%;">Air</th> <th style="width: 5%;">Total # of Containers</th> <th style="width: 5%;">VOCs</th> <th style="width: 5%;">PAH</th> <th style="width: 5%;">PCRAA Metals</th> <th style="width: 5%;">Diss Metals</th> <th style="width: 5%;">HEM Oil & Grease</th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> <th style="width: 5%;"> </th> </tr> <tr> <td><u>WS-003 (surface) 100213</u></td> <td><u>10/2/13</u></td> <td><u>1200</u></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> <td style="text-align: center;">9</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td><u>WS-007 (0.5-1.0) 100213</u></td> <td><u>10/2/13</u></td> <td><u>1220</u></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> <td style="text-align: center;">9</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td><u>WS-001 (0.5-1.0) 100213</u></td> <td><u>10/2/13</u></td> <td><u>1240</u></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> <td style="text-align: center;">9</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td><u>DUP-WS-96-100213</u></td> <td><u>10/2/13</u></td> <td><u>—</u></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> <td style="text-align: center;">9</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td><u>WS-EP-79-100213</u></td> <td><u>10/2/13</u></td> <td><u>1330</u></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> <td style="text-align: center;">7</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td style="text-align: center;">x</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> <tr> <td><u>WS-TB-165-100213</u></td> <td><u>10/2/13</u></td> <td><u>—</u></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> <td style="text-align: center;"><input checked="" type="checkbox"/></td> <td></td> <td></td> <td style="text-align: center;">2</td> <td style="text-align: center;">x</td> <td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td> </tr> </table>											Sample Identification	Date	Time	Grab	Composite	Soil	Water	Oil	Air	Total # of Containers	VOCs	PAH	PCRAA Metals	Diss Metals	HEM Oil & Grease											<u>WS-003 (surface) 100213</u>	<u>10/2/13</u>	<u>1200</u>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>			9	x	x	x	x	x											<u>WS-007 (0.5-1.0) 100213</u>	<u>10/2/13</u>	<u>1220</u>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>			9	x	x	x	x	x											<u>WS-001 (0.5-1.0) 100213</u>	<u>10/2/13</u>	<u>1240</u>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>			9	x	x	x	x	x											<u>DUP-WS-96-100213</u>	<u>10/2/13</u>	<u>—</u>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>			9	x	x	x	x	x											<u>WS-EP-79-100213</u>	<u>10/2/13</u>	<u>1330</u>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>			7	x	x	x	x												<u>WS-TB-165-100213</u>	<u>10/2/13</u>	<u>—</u>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>			2	x														
Sample Identification	Date	Time	Grab	Composite	Soil	Water												Oil	Air	Total # of Containers	VOCs	PAH	PCRAA Metals	Diss Metals	HEM Oil & Grease																																																																																																																																																																							
<u>WS-003 (surface) 100213</u>	<u>10/2/13</u>	<u>1200</u>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>			9	x	x	x	x	x																																																																																																																																																																																		
<u>WS-007 (0.5-1.0) 100213</u>	<u>10/2/13</u>	<u>1220</u>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>			9	x	x	x	x	x																																																																																																																																																																																		
<u>WS-001 (0.5-1.0) 100213</u>	<u>10/2/13</u>	<u>1240</u>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>			9	x	x	x	x	x																																																																																																																																																																																		
<u>DUP-WS-96-100213</u>	<u>10/2/13</u>	<u>—</u>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>			9	x	x	x	x	x																																																																																																																																																																																		
<u>WS-EP-79-100213</u>	<u>10/2/13</u>	<u>1330</u>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>			7	x	x	x	x																																																																																																																																																																																			
<u>WS-TB-165-100213</u>	<u>10/2/13</u>	<u>—</u>	<input checked="" type="checkbox"/>			<input checked="" type="checkbox"/>			2	x																																																																																																																																																																																						
2 Sample Identification Collected Date Time Grab Composite				3 Grab Composite Soil Water Oil			4 Matrix Sediment Potable Ground Surface NPDES Air											5 Analyses Requested Preservation Code	6 Remarks																																																																																																																																																																													
7 Turnaround Time Requested (TAT) (please circle) Standard <u>5 day</u> 4 day 72 hour 48 hour 24 hour				Relinquished by <u>U/Vann</u>			Date <u>10/2/13</u>		Time <u>1500</u>		Received by _____		Date _____		Time _____																																																																																																																																																																																	
8 Data Package (circle if required) Type I - Full Type VI (Raw Data) NJ Reduced Other _____				EDD (circle if required) Locus EIM (default) Other _____			Relinquished by Commercial Carrier UPS <input checked="" type="checkbox"/> FedEx _____ Other _____			Received by <u>CC</u>		Date <u>10/3/13</u>		Time <u>0915</u>																																																																																																																																																																																		
				Temperature Upon Receipt <u>0.7 - 1.8</u> °C			Custody Seals Intact? <u>Yes</u> No																																																																																																																																																																																									

Rachel L. Kreamer

A# 14739, Gr. 1423470, Samples 7222553-70

From: Mott, Lyndi [Lyndi.Mott@arcadis-us.com]
Sent: Thursday, October 03, 2013 3:17 PM
To: Rachel L. Kreamer
Cc: Kathy Klinefelter; Drost, Dave; Van Aller, Hans
Subject: FW: Sample ID on samples received today

Attachments: 20131003150810794.pdf



2013100315081079
4.pdf (774 KB)...

Rachel,

That is correct based on the field logs. The sample location collected at 1110 is WS-011(5.0-5.5)100213.

Lyndi Mott

-----Original Message-----

From: Rachel L. Kreamer [mailto:RKreamer@lanasterlabs.com]
Sent: Thursday, October 03, 2013 2:14 PM
To: Mott, Lyndi
Cc: Kathy Klinefelter
Subject: Sample ID on samples received today

Hi Lyndi.

There are two WS-011(1.5-2.0)100213 samples on today's chain. Per the bottle labels, the set collected at 1110 should be WS-011(5.0-5.5)100213. We'll use this on the reports unless we hear otherwise.

Thanks,
Rachel

-----Original Message-----

From: 39Scanner@lanasterlabs.com [mailto:39Scanner@lanasterlabs.com]
Sent: Thursday, October 03, 2013 3:08 PM
To: Rachel L. Kreamer
Subject:

This E-mail was sent from "RNP367EC2" (MP 4001/LD140).

Scan Date: 10.03.2013 15:08:10 (-0400)
Queries to: 39Scanner@lanasterlabs.com

NOTICE: This e-mail and any files transmitted with it are the property of ARCADIS U.S., Inc. and its affiliates. All rights, including without limitation copyright, are reserved. The proprietary information contained in this e-mail message, and any files transmitted with it, is intended for the use of the recipient(s) named above. If the reader of this e-mail is not the intended recipient, you are hereby notified that you have received this e-mail in error and that any review, distribution or copying of this e-mail or any files transmitted with it is strictly prohibited. If you have received this e-mail in error, please notify the sender immediately and delete the original message and any files transmitted. The unauthorized use of this e-mail or any files transmitted with it is prohibited and disclaimed by ARCADIS U.S., Inc. and its affiliates. Nothing herein is intended to constitute the offering or performance of services where otherwise restricted by law.

Environmental Sample Administration 1423470
Receipt Documentation Log

Client/Project: Mayflower
Date of Receipt: 10/3/13
Time of Receipt: 0915
Source Code: 60-1

Shipping Container Sealed: YES NO
Custody Seal Present * : YES NO
* Custody seal was intact unless otherwise noted in the discrepancy section
Package: Chilled Not Chilled

Temperature of Shipping Containers							
Cooler #	Thermometer ID	Temperature (°C)	Temp Bottle (TB) or Surface Temp (ST)	Wet Ice (WI) or Dry Ice (DI) or Ice Packs (IP)	Ice Present? Y/N	Loose (L) Bagged Ice (B) or NA	Comments
1	DT146	1.8	TB	WI	Y	B	
2	↓	1.3	↓	↓	↓	↓	
3		1.2					
4		0.9					
5		0.8					
6		0.7					
6							

Number of Trip Blanks received NOT listed on chain of custody: 0

Paperwork Discrepancy/Unpacking Problems:
WS-011 (1.5-2.0)100213 coll @ 1110 = -(5.0-5.5) on label

Unpacker Signature/Emp#: CEshl 3647 Date/Time: 10/3/13 1000

Explanation of Symbols and Abbreviations

The following defines common symbols and abbreviations used in reporting technical data:

RL	Reporting Limit	BMQL	Below Minimum Quantitation Level
N.D.	none detected	MPN	Most Probable Number
TNTC	Too Numerous To Count	CP Units	cobalt-chloroplatinate units
IU	International Units	NTU	nephelometric turbidity units
umhos/cm	micromhos/cm	ng	nanogram(s)
C	degrees Celsius	F	degrees Fahrenheit
meq	milliequivalents	lb.	pound(s)
g	gram(s)	kg	kilogram(s)
µg	microgram(s)	mg	milligram(s)
mL	milliliter(s)	L	liter(s)
m³	cubic meter(s)	µL	microliter(s)
		pg/L	picogram/liter

< less than - The number following the sign is the limit of quantitation, the smallest amount of analyte which can be reliably determined using this specific test.

> greater than

ppm parts per million - One ppm is equivalent to one milligram per kilogram (mg/kg), or one gram per million grams. For aqueous liquids, ppm is usually taken to be equivalent to milligrams per liter (mg/l), because one liter of water has a weight very close to a kilogram. For gases or vapors, one ppm is equivalent to one microliter per liter of gas.

ppb parts per billion

Dry weight basis Results printed under this heading have been adjusted for moisture content. This increases the analyte weight concentration to approximate the value present in a similar sample without moisture. All other results are reported on an as-received basis.

Data Qualifiers:

C – result confirmed by reanalysis.

J - estimated value – The result is \geq the Method Detection Limit (MDL) and $<$ the Limit of Quantitation (LOQ).

U.S. EPA CLP Data Qualifiers:

Organic Qualifiers

- A** TIC is a possible aldol-condensation product
- B** Analyte was also detected in the blank
- C** Pesticide result confirmed by GC/MS
- D** Compound quantitated on a diluted sample
- E** Concentration exceeds the calibration range of the instrument
- N** Presumptive evidence of a compound (TICs only)
- P** Concentration difference between primary and confirmation columns $>25\%$
- U** Compound was not detected
- X,Y,Z** Defined in case narrative

Inorganic Qualifiers

- B** Value is $<$ CRDL, but \geq IDL
- E** Estimated due to interference
- M** Duplicate injection precision not met
- N** Spike sample not within control limits
- S** Method of standard additions (MSA) used for calculation
- U** Compound was not detected
- W** Post digestion spike out of control limits
- *** Duplicate analysis not within control limits
- +** Correlation coefficient for MSA <0.995

Analytical test results meet all requirements of NELAC unless otherwise noted under the individual analysis.

Measurement uncertainty values, as applicable, are available upon request.

Tests results relate only to the sample tested. Clients should be aware that a critical step in a chemical or microbiological analysis is the collection of the sample. Unless the sample analyzed is truly representative of the bulk of material involved, the test results will be meaningless. If you have questions regarding the proper techniques of collecting samples, please contact us. We cannot be held responsible for sample integrity, however, unless sampling has been performed by a member of our staff. This report shall not be reproduced except in full, without the written approval of the laboratory.

Times are local to the area of activity. Parameters listed in the 40 CFR part 136 Table II as “analyze immediately” are not performed within 15 minutes.

WARRANTY AND LIMITS OF LIABILITY - In accepting analytical work, we warrant the accuracy of test results for the sample as submitted. THE FOREGOING EXPRESS WARRANTY IS EXCLUSIVE AND IS GIVEN IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED. WE DISCLAIM ANY OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING A WARRANTY OF FITNESS FOR PARTICULAR PURPOSE AND WARRANTY OF MERCHANTABILITY. IN NO EVENT SHALL EUROFINS LANCASTER LABORATORIES ENVIRONMENTAL, LLC BE LIABLE FOR INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES INCLUDING, BUT NOT LIMITED TO, DAMAGES FOR LOSS OF PROFIT OR GOODWILL REGARDLESS OF (A) THE NEGLIGENCE (EITHER SOLE OR CONCURRENT) OF EUROFINS LANCASTER LABORATORIES ENVIRONMENTAL AND (B) WHETHER EUROFINS LANCASTER LABORATORIES ENVIRONMENTAL HAS BEEN INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. We accept no legal responsibility for the purposes for which the client uses the test results. No purchase order or other order for work shall be accepted by Eurofins Lancaster Laboratories Environmental which includes any conditions that vary from the Standard Terms and Conditions, and Eurofins Lancaster Laboratories Environmental hereby objects to any conflicting terms contained in any acceptance or order submitted by client.