

ANALYTICAL RESULTS

Prepared by:

Eurofins Lancaster Laboratories Environmental
2425 New Holland Pike
Lancaster, PA 17601

Prepared for:

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

October 25, 2013

Project: Mayflower, AR Pipeline Incident

Submittal Date: 10/21/2013

Group Number: 1427997

SDG: PEM36

PO Number: B0086003.1301

State of Sample Origin: AR

Client Sample DescriptionLancaster Labs (LL) #

WS-018(Surface)102013 Filt Grab Surface Water	7245619
WS-003(Surface)102013 Filt Grab Surface Water	7245620
WS-007(0.5-1.0)102013 Filt Grab Surface Water	7245621
WS-001(0.5-1.0)102013 Filt Grab Surface Water	7245622
WS-005(Surface)102013 Filt Grab Surface Water	7245623
WS-014(1.5-2.0)102013 Filt Grab Surface Water	7245624
WS-014(5.5-6.0)102013 Filt Grab Surface Water	7245625
WS-012(1.5-2.0)102013 Filt Grab Surface Water	7245626
WS-012(5.0-5.5)102013 Filt Grab Surface Water	7245627
WS-010(1.5-2.0)102013 Filt Grab Surface Water	7245628
WS-010(3.5-4.0)102013 Filt Grab Surface Water	7245629
WS-006(0.5-1.0)102013 Filt Grab Surface Water	7245630
WS-002(Surface)102013 Filt Grab Surface Water	7245631
WS-011(1.5-2.0)102013 Filt Grab Surface Water	7245632
WS-011(5.0-5.5)102013 Filt Grab Surface Water	7245633
WS-EB-097-102013 Filt Grab Water	7245634
DUP-WS-105-102013 Filt Grab Surface Water	7245635

The specific methodologies used in obtaining the enclosed analytical results are indicated on the Laboratory Sample Analysis Record.

ELECTRONIC COPY TO
ARCADIS

Attn: Stephen Barrick

ELECTRONIC COPY TO
ARCADIS

Attn: Lyndi Mott

ELECTRONIC COPY TO
ExxonMobil

Attn: Michael J. Firth

ELECTRONIC COPY TO
ARCADIS

Attn: Emily Leamer

COPY TO		
ELECTRONIC	ARCADIS	Attn: Rhiannon Parmalee
COPY TO		
ELECTRONIC	ARCADIS	Attn: Jamie Pritchard
COPY TO		
ELECTRONIC	ExxonMobil	Attn: Michael L Sixsmith
COPY TO		
ELECTRONIC	ExxonMobil	Attn: Julie Foster
COPY TO		

Respectfully Submitted,



Katherine A. Klinefelter
Principal Specialist

(717) 556-7256

Project Name: Mayflower, AR Pipeline Incident
LLI Group #: 1427997

General Comments:

See the Laboratory Sample Analysis Record section of the Analysis Report for the method references.

All QC met criteria unless otherwise noted in an Analysis Specific Comment below. Refer to the QC Summary for specific values and acceptance criteria.

Project specific QC samples are not included in this data set

Matrix QC may not be reported if site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD was performed, unless otherwise specified in the method.

Surrogate recoveries (if applicable) which are outside of the QC window are confirmed unless attributed to a dilution or otherwise noted in an Analysis Specific Comment below.

The samples were received at the appropriate temperature and in accordance with the chain of custody unless otherwise noted.

Analysis Specific Comments:

No additional comments are necessary.

Sample Description: WS-018(Surface)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245619
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 08:05 by HVA

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-18SF SDG#: PEM36-01

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0226	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 06:15	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 06:15	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 06:15	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 06:15	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 06:15	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 06:15	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 06:15	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 06:15	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 06:15	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 04:43	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-003(Surface)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245620
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 08:15 by HVA

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-3S-F SDG#: PEM36-02

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0192	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 06:19	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 06:19	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 06:19	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 06:19	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 06:19	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 06:19	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 06:19	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 06:19	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 06:19	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 04:45	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-007(0.5-1.0)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245621
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 08:35 by HVA

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-705F SDG#: PEM36-03

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0312	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 06:31	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 06:31	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 06:31	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 06:31	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 06:31	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 06:31	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 06:31	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 06:31	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 06:31	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 04:47	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-001(0.5-1.0)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245622
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 08:50 by HVA

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-105F SDG#: PEM36-04

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0176	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 06:35	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 06:35	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 06:35	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 06:35	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 06:35	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 06:35	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 06:35	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 06:35	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 06:35	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 04:49	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-005(Surface)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245623
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 09:10 by HVA

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-5S-F SDG#: PEM36-05

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0146	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	0.0016 J	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 06:39	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 06:39	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 06:39	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 06:39	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 06:39	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 06:39	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 06:39	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 06:39	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 06:39	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 04:52	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-014(1.5-2.0)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245624
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 10:00 by HVA

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-141F SDG#: PEM36-06

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0134	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 06:43	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 06:43	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 06:43	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 06:43	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 06:43	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 06:43	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 06:43	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 06:43	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 06:43	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 04:54	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-014(5.5-6.0)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245625
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 10:05 by CP

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-145F SDG#: PEM36-07

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0145	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 05:49	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 05:49	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 05:49	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 05:49	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 05:49	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 05:49	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 05:49	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 05:49	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 05:49	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 04:57	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-012(1.5-2.0)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245626
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 10:20 by CP

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-121F SDG#: PEM36-08

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0168	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 06:47	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 06:47	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 06:47	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 06:47	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 06:47	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 06:47	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 06:47	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 06:47	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 06:47	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 04:59	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-012(5.0-5.5)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245627
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 10:25 by CP

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-125F SDG#: PEM36-09

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0167	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 06:51	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 06:51	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 06:51	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 06:51	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 06:51	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 06:51	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 06:51	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 06:51	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 06:51	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 05:01	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-010(1.5-2.0)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245628
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 10:50 by CP

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-101F SDG#: PEM36-10

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0174	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 06:55	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 06:55	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 06:55	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 06:55	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 06:55	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 06:55	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 06:55	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 06:55	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 06:55	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 05:03	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-010(3.5-4.0)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245629
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 10:55 by CP

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-103F SDG#: PEM36-11

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0177	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 06:59	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 06:59	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 06:59	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 06:59	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 06:59	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 06:59	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 06:59	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 06:59	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 06:59	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 05:09	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-006(0.5-1.0)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245630
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 11:10 by CP

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-605F SDG#: PEM36-12

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0171	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 07:03	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 07:03	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 07:03	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 07:03	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 07:03	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 07:03	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 07:03	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 07:03	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 07:03	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 05:17	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-002(Surface)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245631
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 11:50 by CP

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-02SF SDG#: PEM36-13

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0168	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 07:07	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 07:07	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 07:07	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 07:07	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 07:07	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 07:07	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 07:07	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 07:07	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 07:07	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 05:19	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-011(1.5-2.0)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245632
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 12:05 by CP

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-111F SDG#: PEM36-14

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0183	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 07:19	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 07:19	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 07:19	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 07:19	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 07:19	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 07:19	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 07:19	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 07:19	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 07:19	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 05:22	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-011(5.0-5.5)102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245633
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 12:10 by CP

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

-115F SDG#: PEM36-15

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0183	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 07:23	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 07:23	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 07:23	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 07:23	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 07:23	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 07:23	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 07:23	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 07:23	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 07:23	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 05:24	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: WS-EB-097-102013 Filt Grab Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245634
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 13:10 by CP

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

EF97F SDG#: PEM36-16EB

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.00094 J	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 07:27	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 07:27	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 07:27	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 07:27	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 07:27	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 07:27	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 07:27	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 07:27	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 07:27	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 05:26	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Sample Description: DUP-WS-105-102013 Filt Grab Surface Water
Mayflower, AR
Pipeline Incident

LL Sample # WW 7245635
LL Group # 1427997
Account # 14739

Project Name: Mayflower, AR Pipeline Incident

Collected: 10/20/2013 by CP

ExxonMobil c/o Arcadis
630 Plaza Drive, Suite 600
Highlands Ranch CO 80129

Submitted: 10/21/2013 17:35

Reported: 10/25/2013 13:11

FD15F SDG#: PEM36-17FD*

CAT No.	Analysis Name	CAS Number	As Received Result	As Received Method Detection Limit*	As Received Limit of Quantitation	Dilution Factor
Metals Dissolved		SW-846 6010B	mg/l	mg/l	mg/l	
07035	Arsenic	7440-38-2	N.D.	0.0068	0.0200	1
07046	Barium	7440-39-3	0.0175	0.00033	0.0050	1
07049	Cadmium	7440-43-9	N.D.	0.00076	0.0050	1
07051	Chromium	7440-47-3	N.D.	0.0016	0.0150	1
07055	Lead	7439-92-1	N.D.	0.0047	0.0150	1
07061	Nickel	7440-02-0	N.D.	0.0015	0.0100	1
07036	Selenium	7782-49-2	N.D.	0.0084	0.0200	1
07066	Silver	7440-22-4	N.D.	0.0021	0.0050	1
07071	Vanadium	7440-62-2	N.D.	0.0020	0.0050	1
		SW-846 7470A	mg/l	mg/l	mg/l	
00259	Mercury	7439-97-6	N.D.	0.000060	0.00020	1

General Sample Comments

This sample was filtered in the lab for dissolved metals.

All QC is compliant unless otherwise noted. Please refer to the Quality Control Summary for overall QC performance data and associated samples.

Laboratory Sample Analysis Record

CAT No.	Analysis Name	Method	Trial#	Batch#	Analysis Date and Time	Analyst	Dilution Factor
07035	Arsenic	SW-846 6010B	1	132961848003	10/25/2013 07:31	Tara L Snyder	1
07046	Barium	SW-846 6010B	1	132961848003	10/25/2013 07:31	Tara L Snyder	1
07049	Cadmium	SW-846 6010B	1	132961848003	10/25/2013 07:31	Tara L Snyder	1
07051	Chromium	SW-846 6010B	1	132961848003	10/25/2013 07:31	Tara L Snyder	1
07055	Lead	SW-846 6010B	1	132961848003	10/25/2013 07:31	Tara L Snyder	1
07061	Nickel	SW-846 6010B	1	132961848003	10/25/2013 07:31	Tara L Snyder	1
07036	Selenium	SW-846 6010B	1	132961848003	10/25/2013 07:31	Tara L Snyder	1
07066	Silver	SW-846 6010B	1	132961848003	10/25/2013 07:31	Tara L Snyder	1
07071	Vanadium	SW-846 6010B	1	132961848003	10/25/2013 07:31	Tara L Snyder	1
00259	Mercury	SW-846 7470A	1	132965713004	10/25/2013 05:28	Damary Valentin	1
01848	WW SW846 ICP Digest (tot rec)	SW-846 3005A	1	132961848003	10/24/2013 08:59	James L Mertz	1
05713	WW SW846 Hg Digest	SW-846 7470A	1	132965713004	10/24/2013 16:05	Nelli S Markaryan	1

*=This limit was used in the evaluation of the final result

Quality Control Summary

Client Name: ExxonMobil c/o Arcadis
Reported: 10/25/13 at 01:11 PM

Group Number: 1427997

Matrix QC may not be reported if insufficient sample or site-specific QC samples were not submitted. In these situations, to demonstrate precision and accuracy at a batch level, a LCS/LCSD was performed, unless otherwise specified in the method.

All Inorganic Initial Calibration and Continuing Calibration Blanks met acceptable method criteria unless otherwise noted on the Analysis Report.

Laboratory Compliance Quality Control

<u>Analysis Name</u>	<u>Blank Result</u>	<u>Blank MDL**</u>	<u>Blank LOQ</u>	<u>Report Units</u>	<u>LCS %REC</u>	<u>LCSD %REC</u>	<u>LCS/LCSD Limits</u>	<u>RPD</u>	<u>RPD Max</u>
Batch number: 132961848003	Sample number(s): 7245619-7245635								
Arsenic	N.D.	0.0068	0.0200	mg/l	103		90-113		
Barium	N.D.	0.00033	0.0050	mg/l	104		90-110		
Cadmium	N.D.	0.00076	0.0050	mg/l	105		90-112		
Chromium	N.D.	0.0016	0.0150	mg/l	103		90-110		
Lead	N.D.	0.0047	0.0150	mg/l	110		88-110		
Nickel	N.D.	0.0015	0.0100	mg/l	107		90-111		
Selenium	N.D.	0.0084	0.0200	mg/l	104		80-120		
Silver	N.D.	0.0021	0.0050	mg/l	92		80-120		
Vanadium	N.D.	0.0020	0.0050	mg/l	102		90-110		
Batch number: 132965713004	Sample number(s): 7245619-7245635								
Mercury	N.D.	0.00006	0.00020	mg/l	102		80-120		
		0							

Sample Matrix Quality Control

Unspiked (UNSPK) = the sample used in conjunction with the matrix spike
Background (BKG) = the sample used in conjunction with the duplicate

<u>Analysis Name</u>	<u>MS %REC</u>	<u>MSD %REC</u>	<u>MS/MSD Limits</u>	<u>RPD</u>	<u>RPD MAX</u>	<u>BKG Conc</u>	<u>DUP Conc</u>	<u>DUP RPD</u>	<u>Dup RPD Max</u>
Batch number: 132961848003	Sample number(s): 7245619-7245635 UNSPK: 7245625 BKG: 7245625								
Arsenic	106	105	81-123	1	20	N.D.	N.D.	0 (1)	20
Barium	106	105	78-118	1	20	0.0145	0.0145	0 (1)	20
Cadmium	107	106	83-116	1	20	N.D.	N.D.	0 (1)	20
Chromium	105	104	76-120	1	20	N.D.	N.D.	0 (1)	20
Lead	111	112	75-125	0	20	N.D.	N.D.	0 (1)	20
Nickel	109	108	86-115	1	20	N.D.	N.D.	0 (1)	20
Selenium	105	107	75-125	2	20	N.D.	N.D.	0 (1)	20
Silver	94	94	75-125	1	20	N.D.	N.D.	0 (1)	20
Vanadium	105	105	90-117	0	20	N.D.	N.D.	0 (1)	20
Batch number: 132965713004	Sample number(s): 7245619-7245635 UNSPK: 7245629 BKG: 7245629								
Mercury	104	100	80-120	3	20	N.D.	N.D.	0 (1)	20

*- Outside of specification

** - This limit was used in the evaluation of the final result for the blank

(1) The result for one or both determinations was less than five times the LOQ.

(2) The unspiked result was more than four times the spike added.

eurofins

Acct. # 14739

Group # 1427997 Sample # 7245619-35

Instructions on reverse side correspond with circled numbers

Py 2/3

Eurofins Lancaster Laboratories Environmental, LLC • 2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300

The white copy should accompany samples to Eurofins Lancaster Laboratories Environmental. The yellow copy should be retained by the client.

ExxonMobil Analysis Request/Chain of Custody



Lancaster Laboratories
Environmental

Acct. # 14739 For Eurofins Lancaster Laboratories Environmental use only
Group # 142957 Sample # 7245619-35
Instructions on reverse side correspond with circled numbers.

pg 3/3

1 Client Information				4 Matrix				5 Analyses Requested												6 Remarks			
Facility #/SID <u>Mayflower Pipeline Incident</u>				☐ Sediment ☐ Potable ☐ Ground ☒ Surface ☐ NPDES ☐ Air ☐ Oil ☐ Total # of Containers				Preservation Code												Preservation Codes H = HCl T = Thiosulfate N = HNO ₃ B = NaOH S = H ₂ SO ₄ O = Other			
Site Address <u>Mayflower, AR</u>								# <u>8260B</u> # <u>8270 SIM</u> # <u>hard hats</u> # <u>RCA Metals & H₂CO₃ Mg</u> # <u>Diss. Metals</u> # <u>HEM Oil & Grease</u>															
ExxonMobil PM <u>Scott Bushroe</u>		Cost Center/AFE																		6 Lab to filter and pressure diss. metals upon receipt			
Consultant/Office <u>ARCADIS</u>																							
Consultant PM <u>Stephen Barrick</u>		Consultant Phone # <u>919-302-6799</u>																					
Sampler <u>Clement Papaio / Danny Mays</u>																							
2 Sample Identification		3 Collected																					
		Date	Time	Grab	Composite	Soil	Water	Oil	Total # of Containers														
WS-014(5.5-6.0) 102013		10-20-13	1005	X			X		9	X	X	X	X	X	X								
WS-012(1.5-2.0) 102013		10-20-13	1020	X			X		9	X	X	X	X	X	X								
WS-012(5.0-5.5) 102013		10-20-13	1025	X			X		9	X	X	X	X	X	X								
WS-010(1.5-2.0) 102013		10-20-13	1050	X			X		9	X	X	X	X	X	X								
WS-010(3.5-4.0) 102013		10-20-13	1055	X			X		9	X	X	X	X	X	X								
WS-006(0.5-1.0) 102013		10-20-13	1110	X			X		9	X	X	X	X	X	X								
WS-002(surf) 102013		10-20-13	1150	X			X		9	X	X	X	X	X	X								
WS-011(1.5-2.0) 102013		10-20-13	1205	X			X		9	X	X	X	X	X	X								
WS-011(5.0-5.5) 102013		10-20-13	1210	X			X		9	X	X	X	X	X	X								
WS-EB-097-102013		10-20-13	1310	X			X		9	X	X	X	X	X	X								
DUP-WS-105-102013		10-20-13		X			X		9	X	X	X	X	X	X								

7 Turnaround Time Requested (TAT) (please circle)			Relinquished by		Date		Time		Received by		Date		Time	
Standard <u>5 day</u> 4 day			<u>Daniel Mays</u>		<u>10-20-13</u>		<u>1600</u>							
72 hour 48 hour 24 hour														
			Relinquished by		Date		Time		Received by		Date		Time	
			Relinquished by		Date		Time		Received by		Date		Time	
8 Data Package (circle if required)			EDD (circle if required)		Relinquished by Commercial Carrier				Received by		Date		Time	
Type I - Full			Locus EIM (default)		UPS FedEx Other <u>X</u>				<u>Annalise H. Owen</u>		<u>10/21/13</u>		<u>1735</u>	
Type VI (Raw Data)			Other _____											
NJ Reduced														
Other _____														
Temperature Upon Receipt <u>0.2-2.4 °C</u>								Custody Seals Intact? <u>Yes</u> No						

Eurofins Lancaster Laboratories Environmental, LLC • 2425 New Holland Pike, Lancaster, PA 17601 • 717-656-2300

The white copy should accompany samples to Eurofins Lancaster Laboratories Environmental. The yellow copy should be retained by the client.

G-1427997

Environmental Sample Administration
Receipt Documentation LogClient/Project: Exxon Mobil: MayflowerShipping Container Sealed: YES NODate of Receipt: 10/21/13Custody Seal Present * : YES NOTime of Receipt: 1735

* Custody seal was intact unless otherwise noted in the discrepancy section

Source Code: 01Package: Chilled Not Chilled

Temperature of Shipping Containers							
Cooler #	Thermometer ID	Temperature (°C)	Temp Bottle (TB) or Surface Temp (ST)	Wet Ice (WI) or Dry Ice (DI) or Ice Packs (IP)	Ice Present? Y/N	Loose (L) Bagged Ice (B) or NA	Comments
1	DT131	1.8	TB	WI	Y	B	
2	↓	1.9	↓	↓	↓	↓	
3	↓	0.7	↓	↓	↓	↓	
4	↓	2.4	↓	↓	↓	↓	
5	↓	0.3	↓	↓	↓	↓	
6	↓	2.1	↓	↓	↓	↓	

Number of Trip Blanks received NOT listed on chain of custody: 0

Paperwork Discrepancy/Unpacking Problems:

Unpacker Signature/Emp#: Anne H. Owens / 210 Date/Time: 10/21/13 1750

Issued by Dept. 6042 Management

G-1427997

Environmental Sample Administration
Receipt Documentation LogClient/Project: Exxon Mobil: MayflowerShipping Container Sealed: YES NODate of Receipt: 10/21/13Custody Seal Present *: YES NOTime of Receipt: 1735

* Custody seal was intact unless otherwise noted in the discrepancy section

Source Code: 01Package: Chilled Not Chilled

Temperature of Shipping Containers

Cooler #	Thermometer ID	Temperature (°C)	Temp Bottle (TB) or Surface Temp (ST)	Wet Ice (WI) or Dry Ice (DI) or Ice Packs (IP)	Ice Present? Y/N	Loose (L) Bagged Ice (B) or NA	Comments
7A	DT121	0.6	TB	WI	Y	B	
8A	↓	0.3	↓	↓	↓	↓	
9A	↓	0.2	↓	↓	↓	↓	
10A	↓	0.6	↓	↓	↓	↓	
11A	↓	1.1	↓	↓	↓	↓	
12A	V	0.4	↓	↓	↓	↓	

AKD 10/21/13

Number of Trip Blanks received NOT listed on chain of custody: 0

Paperwork Discrepancy/Unpacking Problems:

Unpacker Signature/Emp#: Anneliese H. Owen /210 Date/Time: 10/21/13 1750

Issued by Dept. 6042 Management

2174.06

Explanation of Symbols and Abbreviations

The following defines common symbols and abbreviations used in reporting technical data:

RL	Reporting Limit	BMQL	Below Minimum Quantitation Level
N.D.	none detected	MPN	Most Probable Number
TNTC	Too Numerous To Count	CP Units	cobalt-chloroplatinate units
IU	International Units	NTU	nephelometric turbidity units
umhos/cm	micromhos/cm	ng	nanogram(s)
C	degrees Celsius	F	degrees Fahrenheit
meq	milliequivalents	lb.	pound(s)
g	gram(s)	kg	kilogram(s)
µg	microgram(s)	mg	milligram(s)
mL	milliliter(s)	L	liter(s)
m3	cubic meter(s)	µL	microliter(s)
		pg/L	picogram/liter
<	less than - The number following the sign is the <u>limit of quantitation</u> , the smallest amount of analyte which can be reliably determined using this specific test.		
>	greater than		
ppm	parts per million - One ppm is equivalent to one milligram per kilogram (mg/kg), or one gram per million grams. For aqueous liquids, ppm is usually taken to be equivalent to milligrams per liter (mg/l), because one liter of water has a weight very close to a kilogram. For gases or vapors, one ppm is equivalent to one microliter per liter of gas.		
ppb	parts per billion		
Dry weight basis	Results printed under this heading have been adjusted for moisture content. This increases the analyte weight concentration to approximate the value present in a similar sample without moisture. All other results are reported on an as-received basis.		

Data Qualifiers:

C – result confirmed by reanalysis.

J - estimated value – The result is $\geq$ the Method Detection Limit (MDL) and $<$ the Limit of Quantitation (LOQ).

U.S. EPA CLP Data Qualifiers:

Organic Qualifiers		Inorganic Qualifiers	
A	TIC is a possible aldol-condensation product	B	Value is $<$ CRDL, but $\geq$ IDL
B	Analyte was also detected in the blank	E	Estimated due to interference
C	Pesticide result confirmed by GC/MS	M	Duplicate injection precision not met
D	Compound quantitated on a diluted sample	N	Spike sample not within control limits
E	Concentration exceeds the calibration range of the instrument	S	Method of standard additions (MSA) used for calculation
N	Presumptive evidence of a compound (TICs only)	U	Compound was not detected
P	Concentration difference between primary and confirmation columns $>25\%$	W	Post digestion spike out of control limits
U	Compound was not detected	*	Duplicate analysis not within control limits
X,Y,Z	Defined in case narrative	+	Correlation coefficient for MSA <0.995

Analytical test results meet all requirements of NELAC unless otherwise noted under the individual analysis.

Measurement uncertainty values, as applicable, are available upon request.

Tests results relate only to the sample tested. Clients should be aware that a critical step in a chemical or microbiological analysis is the collection of the sample. Unless the sample analyzed is truly representative of the bulk of material involved, the test results will be meaningless. If you have questions regarding the proper techniques of collecting samples, please contact us. We cannot be held responsible for sample integrity, however, unless sampling has been performed by a member of our staff. This report shall not be reproduced except in full, without the written approval of the laboratory.

Times are local to the area of activity. Parameters listed in the 40 CFR part 136 Table II as “analyze immediately” are not performed within 15 minutes.

WARRANTY AND LIMITS OF LIABILITY - In accepting analytical work, we warrant the accuracy of test results for the sample as submitted. THE FOREGOING EXPRESS WARRANTY IS EXCLUSIVE AND IS GIVEN IN LIEU OF ALL OTHER WARRANTIES, EXPRESSED OR IMPLIED. WE DISCLAIM ANY OTHER WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING A WARRANTY OF FITNESS FOR PARTICULAR PURPOSE AND WARRANTY OF MERCHANTABILITY. IN NO EVENT SHALL EUROFINS LANCASTER LABORATORIES ENVIRONMENTAL, LLC BE LIABLE FOR INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES INCLUDING, BUT NOT LIMITED TO, DAMAGES FOR LOSS OF PROFIT OR GOODWILL REGARDLESS OF (A) THE NEGLIGENCE (EITHER SOLE OR CONCURRENT) OF EUROFINS LANCASTER LABORATORIES ENVIRONMENTAL AND (B) WHETHER EUROFINS LANCASTER LABORATORIES ENVIRONMENTAL HAS BEEN INFORMED OF THE POSSIBILITY OF SUCH DAMAGES. We accept no legal responsibility for the purposes for which the client uses the test results. No purchase order or other order for work shall be accepted by Eurofins Lancaster Laboratories Environmental which includes any conditions that vary from the Standard Terms and Conditions, and Eurofins Lancaster Laboratories Environmental hereby objects to any conflicting terms contained in any acceptance or order submitted by client.