

08/04/2016

Robert Blanz, Ph.D.
Arkansas Department of Environmental Quality
5301 Northshore Drive
North Little Rock, AR 72118-5317

**RE: C&H Hog Farms
Mt. Judea, Newton County, Arkansas
Harbor Project No. ADEQ-16331**

Dr. Blanz,

I am writing regarding the referenced. If the site investigation determines the following:

- Elevated levels of chemical and/or bacteria leachate from the swine waste lagoons in soil and/or groundwater or;
- Anomalous soil and/or fractured solid cores (i.e. bedrock) indicating zones of contaminant transport.


What is the next step ? **Please provide your response prior to field activities.**

We are requesting a complete photographic log of all field activities. In particular, all drilling activities with photo documentation of each core sample and samples collected which is normally included as an Appendix as you are aware.

Please respond to jfmurdoch3@gmail.com or mail to the following address prior to field activities:

John Murdoch
11908 Elk Ridge
Wesley, Ar. 72773-9111

Sincerely,



John Murdoch
Geologist