

C+H DRILLING OPERATION

9/20/2016: ARRIVED @ 1245
DEPARTED @ ~1400

9/21/2016: ARRIVED @ 0822
DEPARTED @ 1721

- SIGNED HEALTH AND SAFETY PLAN (HASP) @ 0924
- MIKE LYBRAND (HARBOR ENVIRONMENTAL) SPLIT SAMPLES FOR HARBOR ENVIRONMENTAL, ADEQ, AND UOFA FOR B-15-1. B-15-1 WAS THE SURFACE SAMPLE MEASURE FROM APPROXIMATELY 0-6 INCHES.
- CREW HIT ROCK AND UNSURE ABOUT ANY FURTHER SOIL SAMPLES MIKE LYBRAND DUPLICATED B-15-4; HOWEVER ~~THESE~~^{THESE} DUPLICATES WERE NOT TAKEN FOR ADEQ OR UOFA DUE TO LACK OF SAMPLE.
- BROKE CUSTODY SEAL ON ADEQ AND UOFA SAMPLE JARS FOR B-15-5 SO MIKE LYBRAND COULD GET ENOUGH SOIL FOR FECAL COLIFORM BACTERIA TEST. NEW CUSTODY SEALS WERE AFFIXED BUT OLD SEALS WERE LEFT ATTACHED TO JARS.
- DEPARTED SITE AT 17:21
- DELIVERED SAMPLES TO UOFA IN JASPER AT 1800
- DELIVERED SAMPLES TO ADEQ LABORATORY AT 20:56

9/22/2016: ARRIVED @ 0652
DEPARTED @ 1751

- SAFETY BRIEFING BY MIKE LYBRAND @ 0720
- 1047 A GROUND WATER SAMPLE AND DUPLICATE WAS COLLECTED BY HARBOR ENVIRONMENTAL, HOWEVER THERE WAS ONLY ENOUGH GROUND WATER FOR THEIR SAMPLE AND DUPLICATE. I BELIEVE SAMPLE DEPTH WAS ~68.5'.
- SHUT DOWN FOR THE DAY
- DELIVERED SAMPLES TO ADEQ LAB AT 20:44

9/23/2016: ARRIVED @ 0640

DEPARTED @ 1315

- MEASURED BORE HOLE LOCATION @ 0702

- LOCATION N 35.92277

W 093.07328

- ACCURACY 12 FEET AT TIME OF MARK

- CONFIRMED DRILL DEPTH OF 120.5 FT @ 10:35

- DEPARTED SITE @ 1315

26 MB

9/24/2016: ARRIVED @ 12:03

DEPARTED @ 13:51

- PLANNING ON COLLECTING SAMPLES OF MUNICIPAL WATER FROM DRILLING RIG/HOLDING TANK. SAMPLES WILL ALSO BE TAKEN FROM THE MUNICIPAL WATER DISCHARGE.